HISTORIC ARCHITECTURAL SURVEY AND EVALUATION REPORT AND FINDING OF NO ADVERSE EFFECT

BROADWAY STREETSCAPE IMPROVEMENT PROJECT

BROADWAY FROM SECOND STREET TO OLYMPIC BOULEVARD CITY OF LOS ANGELES COUNTY OF LOS ANGELES

Prepared for:

Community Redevelopment Agency City of Los Angeles Los Angeles County ISTEA GRANT NO. STPLE5006 (038)

Prepared by:

Teresa Grimes

Historic Resources Group

1728 Whittey Avenue

Los Angeles, CA 90028

coding of News

and a firm

po a 8 m

The State of the S

enderly of a 180 page of the chimacatorical Skinner i

A ADDRESS CANADA AND PORTION AND A SECOND OF THE SECOND OF

the court of the consiste the track that a track with the state of the

SUMMARY OF FINDINGS

This Historic Architectural Survey and Evaluation Report (HASER) and Finding of No Adverse Effect is for the Broadway Streetscape Improvement Project described below. The project area extends from Second Street to Olympic Boulevard along Broadway in downtown Los Angeles, California, and includes the Broadway Theater and Commercial National Register District. The boundaries of the district which was listed in the National Register of Historic Places in 1979 extend along Broadway from Third Street on the north to Ninth Street on the south. The district is significant under National Register Criterion A as the historic commercial and theater center of Los Angeles. The district is also significant under Criterion C for the architectural quality of its contributing buildings. These contributors were constructed between 1894 and 1931, the established period of significance for the district. The purpose of this report is to identify and evaluate the historic streetscape features of Broadway, as they were not specifically addressed in the National Register nomination form, to evaluate how the district has changed in the last nineteen years, to determine if other resources in the project area are eligible for listing in the National Register, and to determine the effects of the project, if any, on historic resources.

The 1983 Historic Resources Survey of the Central Business District completed by the Community Redevelopment Agency did not include the Broadway National Register District, presumably because it was listed in the National Register. As such, California Historic Resources Inventory forms were not prepared for buildings in the 300 through 800 blocks of Broadway. A few buildings in the project area, but outside of the district boundaries were evaluated as individual resources and documented on state forms.

The report makes six findings: 1) many of the historic streetscape features remain from the period of significance and contribute to the historic character of the district; 2) one contributing building has been demolished and several buildings should no longer be considered contributing due to substantial alterations; 3) the boundaries of the historic district should be expanded roughly one block to the north and south to include properties in the 200 and 900 blocks of Broadway; 4) the terrazzo sidewalk in front of Clifton's Cafeteria is individually eligible for listing in the National Register under Criteria C for its high artistic qualities; 5) none of the buildings within the project area, but outside of the expanded district boundaries are individually eligible for listing in the National Register; and 6) any effects the project will have on character-defining features of the district will be mitigated to the level of insignificance by the measures described on page 14.

Several state forms were used to document the findings made in this report and are included in Appendix B. A District Record states the historic and architectural significance of the district, justifies the new district boundaries, describes the district and its integrity, provides a list of contributing and non-contributing buildings, and includes a map of the district. Continuation Sheets were created for buildings which were previously documented and include the California Historic Resources Inventory forms prepared in 1983 and new black and white photographs. Building, Structure, and Object Records were prepared for buildings which were not previously documented in either the National Register nomination form or the 1983 Historic Resources Survey of the Central Business District. Primary Records were prepared for all of the other buildings in the district and note changes that have occurred in the last nineteen years.

and the second controlled that it into a fine the medical fine to the description of the fine the medical medical materials and the medical fine the medical fine the medical fine the medical fine the medical materials and medical medical fine the medical fine t

The second control of the second control of

e sof allocate the algorithm for the control of the software the confidence of the control of th

The state of the s

HISTORIC ARCHITECTURAL SURVEY AND EVALUATION REPORT

TABLE OF CONTENTS

I.	PROJ	ECT DESCRIPTION		1
II.	RESE	ARCH METHODS		1
III.	DESC	CRIPTION OF RESOURCES	2	2
IV.	HISTO	ORICAL OVERVIEW	3	3
V.	FIELI	O METHODS	5	5
VI.	Chang Chang Chang Cliftor Ineligi	INGS AND CONCLUSIONS uction cter-defining Features of the Streetscape Street Trees Street Lights Sidewalks Basement Fixtures and Hardware Public Utility Hardware Granite Curbs es in Boundaries of the Broadway Theater and Commercial District es in Contributing and Noncontributing Buildings n's Cafeteria ble Buildings Within the APE gs of No Adverse Effect	6 6 6 7 7 8 9 9 9 10 11 12 12	555773000
VII.	MITIC	SATION MEASURES	14	1000
VIII.	BIBLI	OGRAPHY	15	
Illustra	ations			
Maps				
Appen	dix A:	National Register of Historic Places Nomination Form, 1979		
Appen	dix B:	Department of Parks and Recreation Forms for Buildings Within the Area of Potential Effects		
Appendix C:		Field Notes and Recommendations		
Append	dix D:	Broadway Streetscape Design Study		
Append	lix E:	Table of Changes in Evaluation Codes		

		6	

I. PROJECT DESCRIPTION

The Community Redevelopment Agency of the City of Los Angeles proposes to use federal funds to make improvements to the Broadway streetscape. The improvement plan includes changes to sidewalk paving, street lighting, street graphics, building facade treatments, street furnishings, and street trees (see Appendix D.) The Area of Potential Effects (APE) for the project encompasses Broadway from Second Street on the north to Olympic Boulevard on the south, and includes the first row of buildings on either side of the street, street, sidewalks, curbs, and street amenities such as trees and light standards.

The project will be constructed in several phases. The first phase of the project will include changes to street lights, street trees, sidewalks, and related basements on Broadway from Second to Fifth Streets. The work will take place between the curb and the building facades. A few properties will not be included in the project at the request of the owners. They are the Million Dollar Theater (301-13) and the Grand Central Market (315). Funded by an ISTEA grant, the first phase is scheduled to begin construction in 1999. The remaining elements of the improvement plan will be implemented as funding becomes available.

II. RESEARCH METHODS

The consultant performed a records search of the National Register of Historic Places, the California Historic Resources Inventory, and various City of Los Angeles agencies in order to compile and analyze previous research and evaluations. Sources include National Register Nomination Forms, Historic Resources Surveys, Historic Context Statements, and other studies.

In order to re-evaluate and document the district's boundaries, contributing and non-contributing buildings, architectural integrity, and character-defining features, the consultant performed the following tasks:

- Conducted general research at-the Los Angeles Central Library to expand the historic context of the district.
- Conducted building specific research including the use of City of Los Angeles building permit records, Sanborn Fire Insurance Maps, and the Los Angeles Central Library collection.
- Searched historic photograph collections at the Los Angeles Public Library History
 Department and the Department of Special Collections at the UCLA University
 Research Library for images of the district.

The buildings on Broadway between Second Street and Olympic are mostly one-story to twelve-story commercial buildings and motion picture theaters designed in a variety of Beaux-Arts and period revival styles. All of the buildings fill the 'respective streetwall. Most contain street-level storefronts. While the styles of the buildings vary, the buildings are clad in many of the same materials, notably east and glazed terra cotta, glazed brick, and east stone.

The buildings range in size from small, one or two story retail buildings to large, 150-foot office buildings, and department stores with very large footprints. The range also includes mid-size loft buildings which were designed with large, open upper floors for several possible uses.

Most of the buildings between Second Street and Olympic are designed in traditional architectural styles. The most common style is the Beaux-Arts, which in commercial buildings usually exhibits a division of the building's elevation into three horizontal zones based on the parts of a column in Classical architecture. This consists of a "base," composed of a first floor and mezzanine level, a relatively unornamented "shaft," composed of repeated floors containing offices, and a "capital," the ornamented and often projecting cornice or elaborated top floor of the building. Most of the buildings are further articulated with the use of classical elements such as pilasters, engaged columns, floral swags, and escutcheons. Such ornamentation is often executed in glazed terra cotta.

The second most common architectural style of Broadway buildings is Art Deco, or Zig-Zag Moderne. The most noted examples of this style are the green and blue glazed terra cotta Eastern Columbia Building, and the Ninth and Broadway Building, clad largely in cast stone with ornamental bronze panels. Also present on Broadway are styles such as Gothic Revival in buildings from the 1920s and late Streamline Moderne buildings, mostly from the 1930s and 1940s.

All of the streetlights on Broadway between Second Street and Olympic Boulevard have original bases, but their poles and lamps have been replaced. There are two styles of historic bases, both of which were installed in 1920. These lamps were elaborately ornamented with stylized motifs from nature. Like many of the Beaux-Arts buildings on the street, the lights consisted of a tripartite composition, with base, shaft, and capital. The bases, which still remain, are covered with ornament of stylized leaves and flowers. The shaft, or pole, consisted of a climbing vine with two lanterns forming the capital. Acorn-shaped lanterns branched off from the shaft in an elaborate scroll.

Broadway's sidewalks are fifteen feet wide and are characterized by a variety of materials, patterns, and colors. Sidewalks often extended beyond the building facade into the foyer providing a visual link between interior and exterior, and encouraging pedestrian traffic to enter theaters and department stores. Stamped, stained concrete is the most common form of sidewalk material on department stores. Stamped, stained concrete is the most common form of sidewalk material on

the street. The basements of most of the buildings extend out to the street line below the sidewalk. In several places, cast iron vents and glass blocks are inserted into the sidewalks to light these below-grade storage areas, which are accessed by way of cast steel doors in the sidewalk.

Broadway is notable, however, for the quality and variety of its terrazzo sidewalks, present in front of some stores and many theaters on Broadway. These sidewalks often extend from the lobbies to the curb. The elaborate patterns seen at Clifton's Cafeteria, the Eastern Columbia Building, and the Los Angeles Theater are some of the most important examples. Each represents a particular style of terrazzo ornamentation: the sidewalk at Clifton's depicts scenes of California, that in front of the Eastern Columbia Building is an abstract, geometric Art Deco design, and the abstracted fleur-de-lis motif in front of the Los Angeles Theater enhances the more traditional revival style of the theater. Other notable terrazzo sidewalks include the sunburst pattern in front of the Roxie Theater.

The most severe alterations to the buildings on Broadway are the modification of storefronts. In many cases, the entire bases (ground floor and mezzanine or second floor) of the buildings have been stripped of their original features and/or reclad with a new, incompatible design meant to "update" the buildings as the area fell out of favor with new generations of shoppers. However, the upper floors of the vast majority of the buildings remain intact.

IV. HISTORICAL OVERVIEW

Originally called Fort Street, Broadway played a prominent role in the residential development of downtown Los Angeles in the nineteenth century. A tree-lined street of medium and large sized Victorian homes, Fort Street was home to some of the city's most distinguished citizens. But in the late 1880s, a new City Hall was constructed between Second and Third Streets and the character of the street began to dramatically change. Proximity to the city's new municipal headquarters attracted major businesses to the street, a situation which caused the City Council to change the street's name to Broadway in 1887.

Broadway quickly became an important commercial thoroughfare. Boston Dry Goods relocated from First and Temple to a site across from City Hall in 1891. Other early retailers on Broadway included Coulter's Dry Goods, Silverwood's, the Broadway Department Store, Bullock's Department Store, and Hamburger's (later the May Company). Many two- and three-story brick buildings were developed at the northern end of the street to meet the quickly growing commercial needs.

In the first decades after the turn of the century, business on Broadway continued to boom. Many commercial establishments outgrew their original small-scale headquarters and began to develop large, multistory structures. Pioneering the south end of Broadway was Bullock's and Hamburger's Department Stores, two of the region's largest retail establishments. Both companies built major buildings in 1906 to serve as their flagship stores -- Bullock's at Seventh Street and

Hamburger's at Ninth Street. In 1918, Blackstone's Dry Goods joined the department stores at the south end of Broadway when they built a new store at Ninth Street.

Broadway's preeminence as the commercial core of Los Angeles was matched by its growth as the leading theater district for the region. Around 1910, nickelodcons and vaudeville theaters began to appear on Broadway, drawing business downtown. Talley's Theater and the Majestic Theater, both later demolished, were located south of Eighth Street. Other early vaudeville theaters on Broadway included Quinn's Superba Theater and the Garrick Theater.

Broadway's status as the new theater district was boosted by the decision of the West Coast's two major vaudeville circuits — the Orpheum and the Pantages — to locate there. In 1910, the Orpheum circuit constructed a theater on Broadway now named the Palace. That same year Alexander Pantages relocated his operations to what is now the Arcade Theater. A few years later full-scale dramatic productions were brought to Broadway with the construction of the Morosco Theater, which is now the Globe.

Sid Graumann built the first theater on Broadway specifically designed for film exhibition in 1918. His Million Dollar Theater is considered the city's first movie palace. Graumann quickly added the nearby Rialto and Paramount to his growing chain of theaters on the street. Loew's became the first national film house chain to establish a presence on Broadway with the opening of the State Theater in 1921.

The vaudeville theaters were forced to upgrade their facilities in an effort to compete with expanding movie audiences. In 1925, a new Orpheum Theater was constructed farther south on Broadway. Housed in equally lavish theaters, vaudeville continued to be a popular form of entertainment on Broadway until the late 1920s.

The introduction of sound to the movies caused a new wave of theater building in the late 1920s. By 1930, every major film studio had secured an outlet in downtown Los Angeles. With a dozen major theaters in a six block area, Broadway contained the highest concentration of movie palaces in the world and a combined seating capacity of more than 15,000.

In their heyday, Broadway's greatest theaters were total entertainment environments, equaling or surpassing the glamour of anything found on stage or screen. Ticket booths, lobbies, auditoriums, staircases, restrooms, and sidewalks were all styled to satisfy the most romantic imagination. Decorative elements borrowed from a wide range of cultures and historical periods came together in fantastic combinations that prompted one critic to complain that "no more pitiful degradation of an art" had ever occurred than "the prostitution of architecture" in movie theaters. "Taste and beauty," he concluded, were abased to the lowest degree. But the public responded otherwise, flocking to theaters on Broadway and around the nation, where, for the price of admission, they were transported into a world of luxury and enchantment.

In the next several decades after 1930, Broadway began to lose its central role as the theater and commercial core of the city. As the white clientele moved away from downtown into the suburbs, so did the lavish movie theaters and department stores. The demise of a city-wide public transit system also contributed to the dispersal of white middle class audiences from the downtown area.

After World War II, the patronage of the Mexican-American population living close to downtown transformed Broadway into a Latino-oriented shopping district. Spanish language signs were layered on top of the opulent architecture of the 1920s and ground floors were transformed to accommodate smaller stores. By the end of the 1960s, the street was dominated by Latinos and it became a primary venue for their commercial, religious, and cultural expression. Today, Broadway remains a hub of activity for Latinos in the city, and Chicanos have been joined by Salvadorans, Guatemalans, and Nicaraguans in their intense public use of the street.

After undergoing a dramatic transformation from the 1880s through the 1920s, the streetscape of Broadway has since evolved much more slowly. Unlike other parts of downtown Los Angeles which have completely lost their historic character, Broadway remains in many ways the street that it was in the 1920s.

V. FIELD METHODS

A field survey was conducted of the district to identify and examine the integrity of the boundaries, contributing resource, and character-defining features. Every building in the APE was photographed using black and white film. In addition, features of the streetscape were measured, sketched, and photographed on site to determine their condition. The field survey was conducted in two phases. The first phase was conducted by Teresa Grimes and William Adair and included the portion of Broadway between Third and Ninth Streets. Phase one of the field survey took place in November of 1995 and involved a thorough documentation of the streetscape. The second phase of the survey was conducted in January of 1998 by Teresa Grimes and Jennifer Minasian. Phase two of the field survey included the photography of the buildings as well as the identification of historic streetscape features in the 200 and 900 blocks of Broadway.

All three of the individuals who contributed to the preparation of this report more than fulfill the qualifications for historic preservation professionals outlined in 36 CFR, Part 61. Teresa Grimes has been a Project Manager for Historic Resources Group four years. She has over ten years of full-time professional experience in the evaluation and documentation of historic resources. Ms. Grimes has a Bachelor's degree in Political Science and a Master's degree in Architectural History from UCLA. William Adair was an Associate Planner at Historic Resources Group for three years and is no longer with the firm. He received a Bachelor's degree in American History from the University Pennsylvania and a Master's degree in Urban Planning from UCLA. Jennifer Minasian has worked at Historic Resources Group for over two years. Currently a Research Associate, Ms. Minasian holds at Bachelor's Degree in Architectural Studies from Scripps College and has completed the course work for a Master's degree in Art History from the University of Chicago.

VI. FINDINGS AND CONCLUSIONS

Introduction

The Broadway Theater and Commercial District was listed in the National Register of Historical Places in 1979. The district includes a total of ninety-five buildings, sixty-nine contributing and twenty-six noncontributing, within its boundaries which extend along Broadway from Third Street on the north to Ninth Street on the south. The district is significant under National Register Criterion A as the historic commercial and theater center of Los Angeles. The district is also significant under Criterion C for the architectural quality of its contributing buildings. These contributors were constructed between 1894 and 1931, the established period of significance for the district.

The report makes six findings: 1) many of the historic streetscape features remain from the period of significance and contribute to the historic character of the district; 2) one contributing building has been demolished and several should no longer be considered contributing due to substantial alterations; 3) the boundaries of the historic district should be expanded roughly one block to the north and south to include properties in the 200 and 900 blocks of Broadway; 4) the terrazzo sidewalk in front of Clifton's Cafeteria is individually eligible for listing in the National Register of the expanded district boundaries are individually eligible for listing in the National Register; and 6) any effects the project will have on character-defining features of the district will be mitigated to the level of insignificance by the measures described on page --

1. Character-defining Features of the Streetscape

Remarkably, many of the original features which characterized the streetscape of Broadway during its period as the premiere commercial and theater district of Los Angeles remain in place. In Substantive ways, the current character of the street is identical to the Broadway of the 1920s. Much of the decorative sidewalk pavement remains, as do the street light bases, and public utility hardware. (See Illustrations.)

a. Street Trees

Trees, the species is unknown, were planted along Broadway during the nineteenth century when it was a residential street. Historic photographs indicate that those trees had been removed by the 1910 s. Additional historic photographs of Broadway through the 1960s indicate that no trees had been planted. There are currently ficus tree scattered about the street which appear to have been planted in the last few decades. Sycamore trees are located on the 900 block of Broadway and are also relatively young. A few empty treewells also indicate the past presence of additional trees on the street. The existing trees do not date from the period of significance and are not character-defining features of the district.

b. Street Lights

Broadway was one of the first streets in Los Angeles to be fit with gas lamps. By 1920, the gas lamps had been supplanted by electric fixtures as well as stop lights to control the burgeoning automobile traffic. All of the street lights on Broadway between Second Street and Olympic Boulevard have original bases but their poles and lamps have been replaced. There are two styles of historic bases, both of which were installed in 1920. These lamps were elaborately ornamented with stylized nature motifs. Like many of the Beaux-Arts buildings on the street, the lights consisted of a tripartite composition, with base, shaft, and capital. The bases, which still remain, are covered with ornament of stylized leaves and flowers. The shaft, or pole, consisted of a climbing vine, and two lanterns formed the capital. Acorn shaped lanterns branched off from the shaft in an elaborate scroll. Although only the bases remain, they should be considered character-defining features of the district. They have been successfully reused in the past and are the most noticeable element of the street lights to pedestrians.

c. Sidewalks

Broadway's sidewalks are fifteen feet wide and are characterized by a variety of materials, patterns, and colors. Sidewalks often extended beyond the building facade into the lobbies providing a visual link between interior and exterior, and encouraging pedestrian traffic to enter theaters and department stores. The property line, which is actually five feet in front of the building facades is sometimes indicated by a narrow band of brass and a plaque.

Concrete - Scored, stained concrete is the most common form of sidewalk material on the street. Probably beginning in the 1920s and continuing until today, concrete was stained in various colors such as charcoal, dark red, or green and scored in square, rectangular, or diamond patterns. Attempts to learn the age of the concrete sidewalks and determine if they were present during the district's period of significance were unsuccessful. One might assume that the sidewalks were poured when the buildings with which they are associated were constructed and therefore are historic fabric. Even if that is the case, the pattern and stain on the vast majority of the concrete sidewalks has faded. Due to their questionable age and lack of integrity, the scored, stained concrete sidewalks are not character-defining features of the district.

Terrazzo - Important public buildings of the 1920s -- such as theaters and department stores, welcomed pedestrians with elaborate sidewalk ornamentation, usually of colorful terrazzo. Terrazzo, an ancient material combining marble chips with white cement, was perfected by Fifteenth century Venetian craftsmen to pave terraces, thus the name. During the 1920s and 1930s, architects began using terrazzo for sidewalks to distinguish individual buildings and businesses with which they were associated. On Broadway, terrazzo is employed in a range of colorful patterns, images, and messages either in front of or at the entrance to buildings. The most elaborate designs are found in front of the Los Angeles Theater and Clifton's Cafeteria, although advertisements and simple geometric patterns are more common. Terrazzo sidewalks are a character-defining feature of the district as well as the buildings with which they are associated.

Romero Tile - At various locations along the street there exists brown ceramic tile sidewalks with abstracted Mexican motifs in contrasting colors. The sidewalk was designed by Frank Romero and installed in 1984. The sidewalk is not a character-defining feature of the district as it was installed well after the period of significance. It is not individually eligible for listing in the National Register as it does not meet the minimum fifty year age requirement. Furthermore, the sidewalk does not meet the considerations for resources which are less than fifty years of age.

Brass Property Line Markers and Plaques - Thin bands of brass delineate the property lines in front of various buildings. In some instances there are also small brass plaques, approximately three by nine inches, which identify the first five feet from the building facade as private property. They should not be considered character-defining features of the district as the date these bands and plaques were installed is unknown and as they lack any design qualities.

d. Basement Fixtures and Hardware

Steel doors, cast iron vents, and glass blocks are inlaid at various places along the sidewalk. These artifacts are evidence that many of the buildings had basements that projected under the sidewalk. For many businesses, this was the only access to the building for service delivery. It can be reasonably assumed that these artifacts date from the construction of the building with which they are associated, and depending on their integrity, should be considered character-defining features of the district.

Basement Hatches and Doors - In the case of the basement doors, the physical evidence of the sidewalks and the inspection of some of the basements by the City's Bureau of Engineering suggest that many hatches and doors and have been removed or covered with asphalt or concrete over the years. The vast majority of those which remain have had the doors replaced. Those that appear to be of older vintage are no longer operable and are in poor condition. The basement hatches and doors in front of the street-facing facades of the Bradbury Building, a National Historic Landmark, are the only ones on the street which should be considered character-defining features as they appear to be from the period of significance and in fair condition.

Vents - Five styles of cast iron vents were identified in the field survey of the district: one large round, two smaller round, and two square. The vast majority appear to be in good condition and should be considered character-defining features of the district.

Glass Blocks - Glass blocks, clear and purple, square and round, distinguish some sidewalks. When originally installed, most extended the full-length of the building facades. Many have been completely or partially covered with concrete or asphalt. Today only four sections remain. Given their unique and rare quality, the remaining glass block sidewalks should be considered character-defining features of the district.

e. Public Utility Hardware

Decorative cast iron manhole covers, water meter plates, and flag pole plates add a note of interest to the street for the pedestrians and should be considered character-defining features of the district.

f. Granite Curbs

The streets in the historic core of downtown Los Angeles were originally edged with granite curbs. Most have been replaced or encased with concrete. Others have been damaged by approximately one hundred years of use and are difficult to distinguish. The best remaining section of granite curb is located on the west side of the 700 block. Due to their lack of integrity, granite curbs should not be considered character-defining features of the district.

2. Changes in Boundaries of the Broadway Theater and Commercial District

Six buildings should be added to the Broadway Theater and Commercial District within expanded district boundaries. (See Appendix B for inventory forms for these buildings.) When the district was listed on the National Register in 1979, the boundaries were set at Third Street on the north and Ninth Street on the south. No justification for these boundaries was given at that time.

921-937 S. Broadway (United Artists Theater Building)

The United Artists Theater Building was determined eligible for listing in the National Register in 1982 through the Section 106 Review process and is listed in the California Inventory of Historic Resources as a 2S2.

- 249-251 S. Broadway (Pan American Building)
- 901 S. Broadway (Blackstone's Department Store)
- 908-910 S. Broadway
- 939-947 S. Broadway (Western Costume Building)

The four buildings listed above were evaluated as being individually eligible for the National Register as a part of the Historic Resource Survey of the Central Business District and are currently listed in the California Inventory of Historic Resources as a 3S.

242 S. Broadway (Victor Clothing Company)

The Victor Clothing Company building has not been previously surveyed. While it is not individually eligible listing in the National Register, it does contribute to the expanded district.

These six buildings should clearly be included in the district. They are not separated from the rest of the district by vacant parcels or unusually wide streets, they share the same historic uses as those buildings currently within the district, they were constructed within the district's period of

significance, and retain their architectural integrity.

The expanded district boundaries extend to the north property lines of 242 S. Broadway and 249-251 S. Broadway on the north and the south property lines of 939-947 S. Broadway and 908-910 S. Broadway on the south. The expanded district is bounded by vacant lots and by buildings which are outside the period of significance or clearly lack the integrity to be contributors.

3. Changes in Contributing and Noncontributing Buildings

Six buildings within the original 1979 boundaries should no longer be considered contributors to the district. One building, the Lankershim Hotel, was demolished in the mid-1980s. The remaining five buildings have been altered since they were listed on the National Register and now lack the integrity to be considered contributors, and should be removed from the National Register. (See Appendix B for individual forms for these buildings.)

700-708 S. Broadway

This is a seven-story parking garage which stands on the site of the demolished Lanksershim Hotel. The Lankershim Hotel was a district contributor (ID), but was demolished after the district was listed. The evaluation for this address therefore should be changed to 6Y2 to reflect the evaluation of the parking garage.

318-322 S. Broadway

Originally five stories high, this building lost much of the original ornamentation when it was reduced to three stories. The plain brick facade lacks a cornice, one of the major character-defining features which give the buildings in the district continuity. Since the ornamentation and massing of the building have been altered to such a great extent, the building is no longer a contributor to the Broadway Theater and Commercial District and should be removed from the National Register. It appears that these alterations were made prior to the district's listing in 1979. However, through reassessment of the district, it is clear that this building does not contribute to the district in its present form. The National Register form noted original appearance could be sufficiently documented for any such restoration.

• 341-345 S. Broadway

This building has been reduced to half its original height, and much ornamentation was removed in the process. The windows on the second story (the only story not removed or entirely altered) have been replaced with aluminum-frame windows.

- 350-354 S. Broadway
- 356-364 S. Broadway

These two neighboring buildings have been entirely covered in a metal siding which resembles wood shingles. It is unclear what remains of the original fabric beneath this cladding.

• 355-359 S. Broadway

This building retains almost no character-defining features from the district's period of significance. It appears to have been altered after the district was listed in 1979.

4. Clifton's Cafeteria

The terrazzo sidewalk in front of Clifton's Brookdale Cafeteria is individually eligible for listing in the National Register under Criterion C for its high artistic qualities. The sidewalk was constructed sometime between 1935 and 1939 and depicts scenes from Los Angeles. The Broadway eatery was the second in the Clifton's Cafeteria chain in the Los Angeles area. Clifton's was a combination of the first and last name of its founder, Clifford Clinton. Clinton brought his family and ideas to Los Angeles in 1931, after resigning from the presidents position of the San Francisco based Clinton Cafeterias chain. He opened his first restaurant in Downtown Los Angeles on Olive Street. Because of the increasing number of jobless people, Clinton opened up a Penny Cafeteria on Third and Hill Street which served meals for a penny a portion or nothing to those without funds. Both locations have since been redeveloped. In 1935, despite facing hard times, Clinton opened a third cafeteria at Broadway and Seventh Street. Another restaurant had been operating on the ground floor of the building at 648 S. Broadway which was constructed in 1916. While vacationing at this cabin in the Santa Cruz Mountains in the midst of a redwood forest, Clinton was struck with the idea of bringing some of the coolness of a forest into hot, dusty Los Angeles. Excitedly he ordered some logs to be hallowed out to match the columns in the restaurant. Over the next four years, Clinton had the restaurant complete remodeled into a redwood forest and named it Clifton's Brookdale Cafeteria. The interior, which still exists, is a composite of California redwoods, mountain streams, and murals of groves. Soon after the opening of the Brookdale Cafeteria, Clinton hired Welton Becket Associates to remodel his Olive Street location into a south seas paradise. Danish-born muralist Einar Petersen painted two scenes in the restaurant. Renamed Clifton's Pacific Seas, the building was razed in 1960.

The sidewalk in front of the Brookdale Cafeteria was created sometime between 1935 and 1939 when the restaurant was remodeled. The idea of featuring landmarks and scenic images from Southern California was conceived by Clinton. Installed by the Venetian Terrazzo Company the name of the artist who designed the sidewalk is unknown. The terrazzo sidewalk is one of the best examples of the use of this material on Broadway, if not Los Angeles. Other notable examples are associated with theaters including the Los Angeles, Academy, and Wiltern. The Brookdale Cafeteria terrazzo is distinct from other examples in two respects. First, it is not associated with a theater or a public building. Second, it features representational images similar to those found in PWA murals.

Ineligible Buildings Within the APE

The following buildings within the APE are fifty years old or older and are located outside of the expanded boundaries of the Broadway Theater and Commercial District:

- 201-206 S. Broadway
- 235 S. Broadway

.8

- 950 S. Broadway • 952-956 S. Broadway
- 952-956 S. Broadway
- Broadway

None of these buildings are currently listed in the California Inventory of Historic Resources.

237-241 S. Broadway

This building, the former Boston Dry Goods store, is listed in the California Inventory of Historic Resources with a 1992 evaluation of 5S3. However, the building does not reflect its historic appearance. Due to alterations and lack of integrity, the building does not appear eligible for local or National Register listing. The evaluation therefore should be changed to 6Y2.

None of these six buildings appear eligible for the National Register either individually or as a contributor to this or any potential historic district.

6. Findings of No Adverse Effect

The first phase of the project will not involve the alteration of any buildings contributing to the National Register district or otherwise. The terrazzo sidewalk in front of Clifton's Brookdale Cafeteria is individually eligible for listing in the National Register. Located in the 600 block of Broadway, it will not be effected by the first phase of the project and the improvement plan specifies Standards in that historic fabric will be preserved in place or removed, stored, and incorporated into the new streetscape whenever possible. The recommendations in Appendix C have been incorporated into historic fabric can not be anticipated in the plan; as such some decisions will need to be made in the historic fabric can not be anticipated in the plan; as such some decisions will need to be made in the field during construction. The proposed undertaking will result in no adverse effect as it will not alter the characteristics of the district and properties therein that qualify them for listing in the National Register. Any effects the project will have on the character-defining features of the district will be mitigated to the level of insignificance by the measures described below. Following is an analysis of how various aspects of the project will effect the character-defining features of the district.

Street Lighting - The restoration of the historic light fixtures will have a positive effect on the character of the district. The existing bases will be renovated with new foundations which will not be visible from grade and will be fit with new lanterns replicated from historic designs. The selective

removal of historic street light at the intersections is an acceptable change. However, it appears that there are a few situations in which the execution of this aspect of the project will have an adverse effect on historic sidewalks. Removal of some historic sidewalk material may be permissible in a few instances, but only with a qualified historic architect on site to monitor the work (see mitigation measures below.)

Street Trees - The project calls for the removal of the ficus trees that were introduced a few decades ago as well as the introduction of trees at new locations. Queen palms will be planted in a series of groupings and spaced 25 feet from center to center. The introduction of street trees will have no effect as they will not alter the characteristics of the historic district which qualify it for listing in the National Register.

Sidewalks - Broadway is characterized by a variety of sidewalk materials including terrazzo, glass blocks, ceramic tile, and marble. Sidewalks which are considered character-defining features of the district and the buildings with which they are associated are listed in Appendix A. The project entails the full-scale reconstruction of the sidewalks as well as the reinforcement of basement ceilings. Black concrete with mica cut into a checkerboard will be used as the replacement material. While this material is compatible with the historic district, the selective removal of the historic sidewalk will affect the setting of the district and the associated buildings. As improving the sidewalks and making the basements below water tight will be of benefit to the historic buildings on Broadway, some historic sidewalk may be removed if it lacks integrity and if it is infeasible to retain in place (see mitigation measures below.)

Basement Vents - Cast iron basement vents are a character-defining feature of the district. They will be carefully removed during construction, tagged to identify their location, and incorporated into the new sidewalk in approximately the same location. This aspect of the project will have no effect on historic properties.

Basement Hatches and Doors - The basement hatches and doors in front of the street-facing facades of the Bradbury Building are the only ones in the APE which appear to date from the period of significance and are in fair condition. The removal of these character-defining features will affect the integrity of the setting of the Bradbury Building, a National Historic Landmark (see mitigation measures below.)

Public Utility Hardware - Cast iron water meter plates and flag pole plates are a character-defining feature of the district. They will be carefully removed during construction, tagged to identify their location, and incorporated into the new sidewalk in approximately the same location. This aspect of the project will have no affect on historic properties.

Construction Monitor - Work which may affect the character-defining features of the district and related properties shall be monitored by a qualified historic preservation professional ("Coordinator") selected by the State Office of Historic Preservation (SOHP), Community Redevelopment Agency and the Cultural Affairs Department to ensure compliance with the improvement plan, the Secretary of the Interior's Standards, and the following mitigation measures. The Coordinator shall meet the minimum qualifications for historic preservation architects established by the Secretary of the Interior. The Coordinator shall report to SOHP issues which may arise during construction.

Recordation - Historic sidewalks listed in Appendix A which cannot be preserved either in place or removed and incorporated into the new sidewalk shall be photo documented using large format photography and archival materials. The large-format photography will consist of use of 4×5 negatives (or larger), a scaling stick for representative shots, lenses to allow proper composition, and panchromatic, continuous-tone black and white moderate speed film. Photographs shall be keyed to a drawing depicting the pre-construction location of the sidewalk material. Copies of the photo documentation as well as small samples of the material shall be given to the Cultural Affairs Department and/or the Los Angeles Central Library.

Public Education Program - The lead agency shall create a program to educate and inform the public about the historic streetscape of Broadway. The program may include, but not be limited to, the display of didactic panels in the Central Library, City Hall, or some other publicly accessible space. The program should utilize historic as well as current images of the streetscape.

Restoration - If historic fabric is inadvertently damaged or destroyed during construction, it shall be replaced in kind by a qualified contractor.

Protection - Historic fabric, including building facades, pavement in building lobbies, sidewalks, and street lights, shall be protected as required to prevent damage while work is in progress. Protective measures may include, but are not limited to, the spanning of sidewalks, temporary covering, or the use of barricades. Adjacent historic building facades shall also be protected from flying debris. Temporary covering is required in the event that any machinery or vehicular traffic must traverse sidewalk areas which contain historic fabric; when adjacent construction has a potential to damage, through machinery or hand labor, any historic fabric; and when adjacent curb and gutter work is being performed. Temporary protection may include, but not be limited to, the application of felt and plywood.

Job Conditions - The job site shall be kept clean and orderly at all times to prevent damage to historic fabric. Loose material and debris shall be removed on a daily basis.

Appropriate Equipment - Vibrating machinery shall not be used in the vicinity of historic sidewalk pavement. Chemicals including concrete washing shall not come into contact with historic fabric.

If necessary, portions of historic fabric shall be carefully sawcut and removed. Cutting tools are to be fitted with diamond blades of a quality that will incise the terrazzo without causing chips. It is understood that since terrazzo is composed of stone fragments, some chipping may not be avoidable depending on the condition of the surface.

Cleaning - Upon completion of the project, the terrazzo sidewalks shall be steam cleaned by a qualified contractor. No abrasive cleaning products or methods shall be used.

VIII. BIBLIOGRAPHY

Gebhard, David and Robert Winter. Los Angeles: an Architectural Guide. Salt Lake City: Gibbs Smith, Publisher, 1994.

Gleye, Paul. The Architecture of Los Angeles. Los Angeles: Rosebud Books, 1981.

Longstreth, Richard. City Center to Regional Mall: Architecture, the Automobile, and Retailing in Los Angeles, 1920-1950. Boston: MIT Press, 1997

Los Angeles Department of Building and Safety Records, Historical Building Permits.

National Register of Historic Places - Nomination Form for *Broadway Theater and Commercial District*, 1979.

Sanborn Fire Insurance Maps, 1953.

ILLUSTRATIONS

For contemporary views of buildings within the Area of Potential Effects, see Appendix D, DPR Forms.

Historic Post Card Views, approximately 1907-1940s

- 1. Broadway South from First, "Best Lighted Street in the World," 1908
 - 2. Broadway Looking North from Fourth Street
 - 3. Looking up Broadway from Fifth Street, 1910
 - 4. Broadway near Sixth Street, 1907
- 5. Corner Seventh and Broadway, showing demolished Lankershim Hotel 6. Broadway looking North from Eighth Street

Historic Sidewalk Features

•Commemorative and Decorative Features

• Public Utility Vents and Manhole Covers

•Features Associated with Basement Storage Areas


Mer of a Committee of the state of the state

The control of the co


Now the same is a state of the same of the

Million and the 200

1. Broadway South from First, "Best Lighted Street in the World," 1908




2. Broadway Looking North from Fourth Street




BROADWAY STREETSCAPE IMPROVEMENT PROJECT

3. Looking up Broadway from Fifth Street, 1910



4. Broadway near Sixth Street, 1907




BROADWAY STREETSCAPE IMPROVEMENT PROJECT HISTORIC POST CARD VIEWS

5. Corner Seventh and Broadway, showing demolished Lankershim Hotel



6. Broadway looking North from Eighth Street



COMMEMORATIVE AND DECORATIVE FEATURES:

B'nai B'rith. Plaque commemorating the historic location of Congregation



features scenes of California. Brookdale Cafeteria., 648 S. Broadway, which Details of terrazzo in front of Cliffon's












718 and 820 S. Broadway Terrazzo examples in front of stores:






533 S. Broadway



at 844 S. Broadway. they are located, as in this example in front of an optician's office Some terrazzo patterns advertise the businesses in front of which





direction as well. pedestrians approaching from the opposite building; it is repeated in mirror image for announces the name of the adjacent This tile mosaic signage (a rare example)




BROADWAY STPEETSCAPE IMPROVEMENT PLAN HISTORIC SIDEWALK FEATURES


PUBLIC UTILITY PLATES AND MANHOLE COVERS:






These are examples of public utility features, many of which have text on them denoting which utility they are associated with, such as sewer, electricity, water, etc.








This is an example of a plate in the sidewalk into which a flagpole would be inserted. These features are located throughout the project area and would have been used on holidays to line the street with flags, a common practice along major urban streets at the turn of the century.


BROADWAY STREETSCAPE IMPROVEMENT PLAN

LEVINKES VSSOCIVIED MITH BASEMENT STORAGE AREAS:

Banks of glass block such as this example are also located throughout the district. They light the basement storage areas which extend from the basements of the buildings into the area beneath the sidewalks.




Steel doors in the sidewalk provide access for the delivery of goods directly into basement storage areas. These are two examples of historic patterns.







This is an example of a more recent pattern which is not historic; doors with such a pattern need not be salvaged.





BROADWAY STREETSCAPE IMPROVEMENT PROJECT HISTORIC SIDEWALK FEATURES





Basement vents such as thesa, which are located throughout the project area, are also historic features of the sidewalks. These examples are usually stamped with the name of the foundry.












HISTORIC SIDEWALK FEATURES BROADWAY STREETSCAPE IMPROVEMENT PLAN


EXYMPLES OF FEATURES IN POOR CONDITION AND NON-HISTORIC FEATURES:

In some instances, the holes of vents have been plugged up with asphalt. Such examples are considered in poor condition and need not be salvaged.






Some manhole covers are so worn that the pattern has become indistinguishable. Examples such as this one are in poor condition and need not be salvaged.



This is an example of a non-historic basement vent which need not be salvaged.




Example of a recent, non-historic sidewalk treatment, this one in marble.




BROADWAY STREETSCAPE IMPROVEMENT PROJECT HISTORIC SIDEWALK FEATURES

LIGHT STANDARDS:








Two examples of historic cast iron bases.

Example of a full light standard with historic lamps, Third Street west of Broadway.



All original bases on Broadway are mounted with nonhistoric poles and lamps, while those on the side streets and Hill Street (above, left) retain original features.

yda — mag

The final winds with the second of the secon

Project Vicinity Map


Project Location Map

Area of Potential Effects Map

The late of the purpose and the

Page Tail The Makedial


Latting a fall or a collinsia



PROJECT VICINITY MAP

Broadway Streetscape Improvement Project

source: Automobile Club of Southern California



PROJECT LOCATION MAP

Broadway Streetscape Improvement Project

source: USGS, Hollywood and Los Angeles Quadrangles

APPENDIX A

NATIONAL REGISTER OF HISTORIC PLACES NOMINATION FORM

Broadway Theater and Commercial District, 1979

TO THE PROPERTY OF THE PROPERT

Department Theater and immercial links in 1999

m No. 10-300 REV. (9/77)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES **INVENTORY -- NOMINATION FORM**

RECEIVED SEP 12 1978

DATE ENTERED

MAY

9 1979

	COMPLETE APPLICA	BLE SECTIONS)	•
NAME			
HISTORIC			
BROADWAY THEATER AND COMMERCIAL I	DISTRICT	den bes nåperak (se	
AND/OR COMMON		James . nolinge.	
LOCATION	Wat a second	China Leteven vd fo	
STREET & NUMBER 9			
300-849 South Broadway	= 10 t = 10 t = 2.2	_NOT FOR PUBLICATION	1 100 2550
CITY, TOWN	-	CONGRESSIONAL DIST	RICT
Los Angeles	_ VICINITY OF .	25	LALLECT CONTROL
STATE	CODE	COUNTY	CODE
California	06	Los Angeles	037 ·
CLASSIFICATION	negating [ord processes A		
CATEGORY OWNERSHIP	STATUS	PRES	SENT USE
X DISTRICTPUBLIC	X OCCUPIED	AGRICULTURE	MUSEUM
BUILDING(S)PRIVATE	UNOCCUPIED	XCOMMERCIAL.	PARK
STRUCTURE XBOTH	WORK IN PROGRESS	EDUCATIONAL	PRIVATE RESIDENCE
_SITE PUBLIC ACQUISITION	ACCESSIBLE	XENTERTAINMENT	
_OBJECT _IN PROCESS	XYES: RESTRICTED	GOVERNMENT	SCIENTIFIC
BEING CONSIDERED	YES: UNRESTRICTED	_INDUSTRIAL	_TRANSPORTATION
BEING CONSIDERED	_NO	_MILITARY	_OTHER:
OWNER OF PROPERTY NAME Multiple Ownership (see list) STREET & NUMBER	a construction description	To miles constants	
SIREE! & NOMBER	s of the habitation , it.	Lok atemicia in by a	79
CITY, TOWN	VICINITY OF	STATE	ASSESSED IN CONTRACTOR OF THE PARTY OF THE P
VOCATION OF LEGAL DESC		** UNIVERSE TRAILER	
LOCATION OF LEGAL DESC	WIL TIOIA	wio Affica street di	
COURTHOUSE. REGISTRY OF DEEDS, ETC. Los Angeles Count	ty Hall of Records	lift annihilly water	17. ca
STREET & NUMBER 320 West Temple 3	Street	unded corner glass	
CITY, TOWN		STATE	
Los Angeles		Californ	ia ·
REPRESENTATION IN EXIST	TING SURVEYS		
TÎTLE			
California Historic Resources In	ventory		
DATE			
July 1977	FEDERAL	XSTATE _COUNTY _LOCA	AL .
DEPOSITORY FOR			
	TARATURITA CO		
SURVEY RECORDS Office of Historic P.		07475	
CITY. TOWN Los Angeles	10801740101	STATE Cali:	fornia

NOLIZION IN DESCRIBLION

			UNEXPOSED	81A3
3TA0	-WOVED	X_ALTERED	รผเบษ—	@ 0009 X
SITE	XORIGINAL:	Q3R3TJANU	DETERIORATED	EXCELLENT
3N6	CHECK	CHECK ONE	NOITIO	CONE

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Broadway Theater and Commercial District is a six-block complex of predominalely commercial and entertainment atructures done in a variety of architectural styles. The district extends along both sides of Broadway from Third to Ninth Streets and exhibits a number of atructures in varying condition and degree of alteration. General styles include a variety of commercial buildings in Classical and Commercial styles, Art Deco, Moderne, and others, and many theaters in more sand Commercial styles, Art Deco, Moderne, and others, and many theaters in more spotted by several parking lots and a few structures built after 1930. Most of the structures range in construction date from 1894 to 1931, although several have received new facades since the latter date.

Buildings contributing to the character of the district:

- 1. Bradbury Building (304.5. Broadway): 1893; five-story brick and stone commercial structure designed by George Wyman; has ornate iron balconies and elevators now famous; completely restored (on National Register).

 AHL

 Amount of Amou
- 6. Trustee Building (340 5. Broadway): 1905; 4-story brick and concrete shop and office structure by Parkinson & Bergstrom; tiled facade has been altered and part of cornice removed.
- 8. 0.T. Johnson Block (350 S. Broadway): 1895; 3-story brick and iron structure by R.B. Young; Italianate design with fluted columns and arched windows; parapet with ballastrade removed.
- 9. 0.T. Johnson Building (356 S. Broadway): 1902; 7-story brick structure in Romanesque design by John Parkinson; glazed presed-brick facade with little alteration.
- 11. Judson-Rives Building (424 S. Broadway): 1906; 10-story reinforced concrete and brick structure by C.R. Aldrich with a granite and terra cotta facade; theater installed on first floor in 1924 and lobby remodeled in 1929.
- 12. Bumiller Building (430 S. Broadway): 1906; 6-story reinforced concrete structure with terra cotta ornamentation by Morgan & Walls; iron grillwork added to facade.
- L7. Chester Williams Building (215 W. 5th Street): 1926; 12-story reinforced concrete on steel frame structure by Curlett & Beelman with ornamental bands and a rounded corner, glazed cotta facade designed to look like cut stone.
- 18. Jewelry Trades Building (220 W. 5th Street): 1912; 8-story concrete structure by Morgan, Walls and Morgan; Romanesque design with terra cotta facade and ornamentation including arched windows and heavy cornice.


NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM



CONTINUATION SHEET

ITEM NUMBER 7 PAGE 2

- O.T. Johnson Building #2 (510 S. Broadway): 1905; 5-story brick building with pressed-brick facade by R.B. Young; upper windows form almost solid bands, cornice removed and first floor altered.
- Roxie Theater (518 S. Broadway): 1931; 2-story concrete and brick theater with shops on facade flanks; designed in Art Deco style by J.M. Cooper with floral patterns and grillwork on facade; marquee is new.
- 21. Cameo Theater (528 S. Broadway): 1910; 2-story brick and concrete theater by A.F. Rosenheim; facade features a large rounded pediment above entrance; remodeled in 1924 and some alterations since then.
- 22. Arcade Theater (534 S. Broadway): 1910; 7-story office and theater building of reinforced concrete with grey stucco facade by Morgan & Walls; facade shows Renaissance influence with Grecian columns.
- 23. Arcade Building (540 S. Broadway): 1924; 12-story concrete office structure with two wings connected by inner connection by Kenneth MacDonald; designed to resemble Burlington Arcade in London.
- 24. Hubert-Thom McAn Building (546 S. Broadway): 1900; 3-story brick building in Italianate style with decorative arched windows by John Parkinson, facade is of pressed brick, alterations include removal of original parapet.
- 25. Silverwood's Building (558 S. Broadway): 1920; 5-story reinforced concrete building with terra cotta details by Walker & Eisen, first floor alterations.
- 26. Finney's Cafeteria (217 W. 6th Street): 1904; 4-story brick structure with very plain facade; interior redesigned in 1913 by Plummer and Feil to Dutch motif with tiles by Ernest Bachelder.
- 27. Walter P. Story Building (610 S. Broadway): 1908; 11-story office building of reinforced concrete by Morgan & Walls; terra cotta facade with heavy cornice, decorative bands, arched windows, etc.
- 28. Desmond's Building (614 S. Broadway): 1924; 6-story concrete structure in Spanish Baroque styling by A.C. Martin; has a polychrome terra cotta facade with twisting columns, balconies, and ornamental pediment.
- 29. Broadway Cafeteria (618 S. Broadway): 1928; 2-story Spanish Colonial restaurant of concrete by Charles F. Plummer with terra cotta and wrought iron facade.



NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

little alteration.

on corner.



Chapman Building (756 S. Broadway): 19i1, 13-story concrete structure with three sections above first two floors by Ernest McConnell, terra cotta and brick facade has fluted columns, ornamental moldings, heavy cornice, and ornamental bands.	· lþ
Globe Theater (744 S. Broadway): 10-story concrete theater and office building with stone and brick facade by Morgan, Walls, & Morgan, and many ornamental features such as arched windows, cornice, and ornamental bands with gargoyles.	.04
Barker Brothers Building (722 S. Broadway): 1909, 7-story concrete and brick structure by R.B. Young; original pressed-brick facade features cornice and lugsills but these were removed and building is now plain but restorable.	.8£
Parmelee Building (716 S. Broadway): c. 1907; 6-story concrete structure with facade stuccoed but potentially restorable; cornice and other features removed.	.75
Yorkshire Hotel (710-14 S. Broadway): 1909; 6-story brick and concrete structure by Parkinson & Bergstrom with facade of pressed brick and terra cotta with tile; has tile cornice and arched windows.	.36.
Lankershim Hotel (700 S. Broadway): 1902; 9-story brick hotel by R.B. Young; thr sections with stone and pressed brick facade; most ornamentation removed.	.35.
J.E. Carr Building (644 S. Broadway): 1908; 8-story concrete structure by R.B. Young with enamelled terra cotta and brick facade featuring heavy cornice and arched windows, facade covering extends across lower four floors.	32.
Forrester Building (638 S. Broadway): 1907; 8-story concrete structure by C.F. Whittlesey with terra cotta and stone facade including heavy cornice and arched windows; facade covering on first three stories.	.18
Palace Theater (636 S. Broadway): 1910; 5-story brick and concrete theater and office structure by G. Albert Landsburgh in French Renaissance styling; terra cotta facade features arched windows, heavy cornice, and carved figures.	-30
E 3DA9 7 RABMUM MATI . TEAM WONTAUNITHO	00

Singer Building (806 S. Broadway): 1922; 7-story concrete structure in Italian Renaissance style by Meyer & Holler; has a terra cotta and pressed-brick with

Tower Theater (802 S. Broadway): 1927; 4-story theater building with shops on 8th St. side by S. Charles Lee in French Renaissance styling, terra cotta facade includes many details such as urns, stained-glass window, and a large clock tower

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM



CONTINUATION SHEET

ITEM NUMBER

PAGE 4

- 44. Rialto Theater (812 S. Broadway): 1917, 2-story theater building with pink stucco facade, by O.P. Dennis; has many alterations including removal of original triangular pediment and interior remodeling.
- 45. Apparel Center Building (814 S. Broadway): 1923; 12-story concrete structure in Spanish Renaissannce styling by Walker & Eisen, colorful terra cotta facade with decorative cornice and arched windows; alterations to first floor.
- 46. Braun Building (820-22 S. Broadway): 1913, 6-story reinforced concrete building by W.J. Saunders, glazed brick and terra cotta facade with some ornamentation and alteration to the first floor interior and exterior.
- 48. Anjac Fashion Building (830 S. Broadway): 1927; 12-story concrete structure in Gothic Revival styling by Walker & Eisen with terra cotta facade, almost matches the Orpheum Theater next door in style.
- 49. Orpheum Theater (842 S. Broadway): 1925; 13-story concrete theater and office structures in Spanish Renaissance styling by Schultze & Weaver and G.A. Landsburgh; brick and terra cotta facade includes rows of urns and ornamental bands with brackets.
- 50. Ninth and Broadway Building (NW 9th & Broadway): 1929; 13-story concrete structure in Zig Zag Moderne style by Claude Beelman with terra cotta facade and very little alteration.
- 51. Eastern Columbia Building (849 S. Broadway): 1930; 14-story concrete structure in Moderne styling with terra cotta exterior of turquoise with gold trim; designed by Claude Beelman with a large clock tower that is still operative.
- 54. May Company (SW 8th & Broadway): 1906; 5-story department store of concrete with terra cotta ornamentation, designed by A.F. Rosenheim in Classical styling with a heavy cornice and decorative garlands; the major addition on the south side of the structure (1929) is of the same style with two additional stories; there have been many alterations to the interior.
- 55. Merritt Building (301 W. Eighth Street): 1914; 5-story concrete structure with stone facade by the Reid Brothers (San Francisco); Italian Renaissance style with Ionic columns and heavy cornice; many alterations on first two levels.
- 57. Issacs Building (737-47 S. Broadway): 1913; 8-story concrete structure with Gothic details and a glazed and molded terra cotta facade; has a large facade covering on most of the northern half and other alterations to first floor.
- 59. Cheney Block (731 S. Broadway): 1913; 4-story brick and concrete structure with a remodeled facade of the 1940's; blends very well with the district.

NATIONAL PARK SERVICE UNITED STATES DEPARTMENT OF THE INTERIOR

INVENTORY -- NOMINATION FORM NATIONAL REGISTER OF HISTORIC PLACES

Hartfields (537 S. Broadway): 1931; 6-story reinforced concrete and brick structure in Art Deco styling; very little alteration.	. [
Metropolitan Annex (553 S. Broadway): c. 1923; 6-story concrete and brick structure with terra cotta details; alterations to the street-level frontage.	·94
Swelldom Building (NW 6th and Broadway): 1920; 3-story retail building in Italian Renaissance design by Pierpont and Walter S. Davis, reinforced concrete With glazed terra cotta facade; cast iron roof trim removed.	5
Wood Brothers Building (315 W. 6th Street): c. 1922; 3-story concrete and brick structure with terra cotta decoration which blends very well with the district.	. 27
Norton Building (601-5 S. Broadway): 1906; 6-story brick and concrete office building; the facade was completely altered in 1940 with new design but the structure blends very well with the district and is not out of the time period.	Lost to the
os Angeles Theater (615 S. Broadway); 2-story theater of concrete and terra cotta in French Renaissance design by S. Charles Lee; features fluted columns with urns, gagles, etc.; has a new marquee.	_
lailing's (617-19 S. Broadway): 1930; 2-story concrete structure in French tenaissance design by S. Charles Lee that was the southern flank of the Los Angeles Theater next door; alterations to street level.	1
ullocks-Hollenbeck (639 S. Broadway): 1912; 10-story brick and concrete structure by Morgan & Walls with a brick and terra cotta facade that is almost identical to bullocks next door.	1 6
ullock's (641 S. Broadway): 1906; 7-story brick structure by Parkinson & ergstrom with terra cotta facade details including a heavy cornice; has several dditions and the interior has been completely remodeled.	Β)
nited Building (703 S. Broadway): 1920; 12-story concrete theater and office building by Weeks & Day in Spanish Renaissance styling with patterned brick and serva cotta ornamentation including Moorish windows and a rounded building corner.	4)
oolworth's (719 S, Broadway); 1920; 3-story reinforced concrete structure by eeks & Day, facade altered to an Art Deco-Zig Zag Moderne style in 1941 and uilding next door added to it.	M :
C 3DA9 \ R38MUM M3TI . T33H2 WOITAUNITI	СОИ

a "marble" facade with reliefs; little apparent alteration.

79. Reed's (533 S. Broadway): 1931; 2-story reinforced concrete structure features

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form



Continuation sheet

Item number

Page 5A

Addendum: Description of additional buildings comprising the Bullock's complex.

The buildings are all united by historical function and internal circulation.

Buildings comprising the complex are coded under the number (62) assigned to the original Bullock's Building in the National Register nomination. The added letters are assigned in the order in which the buildings were acquired by Bullock's as part of its department store operations. The ealiest expansion was into the adjacent Hollenbeck Building, already designated as #63 in the district nomination. Subsequent additions, in order, are as follows:

62A. Pease Building (1906) Hudson/Munsel

Originally used as a furniture store, this 8 story building was acquired by Bullock's in 1917. A bridge was constructed over St. Vincent Place and a tunnel beneath at that time to connect the building with the Hollenbeck Building (#63).

62B. Eshman Building (1909) Morgan/Walls

This 7 story building in characteristic Beaux Arts 3-part vertical division became part of Bullock's in or before 1919.

62C. Bridge (1921) ----

The bridge was constructed to connect the Eshman Building with the original Bullock's Department Store. It spans St. Vincent Place, connecting the upper 6 stories of both buildings, creating internal circulation between the two on all levels. Stylistically it repeats the design of the earlier Bullock's building, creating the appearance of a skillfully integrated addition. A tunnel below St. Vincent Place also connects the two buildings.

62D. Gennet Building (1922) Parkinson/Hubbard

The next addition to the Bullock's complex was this tall, slender Beaux Arts building-10 stories tall and only two bays wide. The lower two stories were remodeled in 1934
to create the appearance of a unified design with the adjacent Mackey Building.

62E. Hart Building/Hart '24 (1924) Parkinson/Parkinson

This building duplicated the nearby Gennet Building in height, width and styling. It is now indistinguishable from the adjacent 1928 Hart Building.

62F. Hart Building/Hart '28 (1928) Parkinson/Parkinson

The design of the earlier 1924 Hart Building was expanded to fill out the block by adding five more bays on the Hill Street side and four bays on Seventh Street in Beaux Arts styling. Fenestration is dominated by 3-part Chicago windows.

United States Department of the Interior Mational Park Service

Mational Register of Historic Places Inventory—Nomination Form

paugus estil

Page 5B

item number

Continuation sheet

62G. Mackey Building (1934) Parkinson/Parkinson

The upper six stories of the Mackey Building repeat the appearance of the adjacent Gennet Building. The lower two floors are Moderne in styling; this design was expanded across the base of the Gennet Building, uniting the two buildings visually in 1934, Internal circulation exists between the buildings.

The state of the s

AULTS THE TANK THE STATE THE SHIP STATE OF THE STATE OF T

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM



CONTINUATION SHEET

ITEM NUMBER 7

PAGE 6

- 80. Broadway Interiors (529 S. Broadway): c. 1928; 5-story brick and concrete building with a flat facade and some remaining terra cotta ornamentation; street-level frontage modification.
- 83. Remick Building (517-19 S. Broadway): c. 1902; 6-story brick structure with decorative facade including arched windows and twisting columns between window openings.
- 84. Fifth Street Store (501-515 S. Broadway): 1927; 11-story concrete structure with terra cotta and brick facade by A.E. Curlett; a minor amount of ornamentation has been removed.
- 85. Metropolitan Building (315 W. Fifth Street): 1913; 9-story concrete and terra cotta structure by Parkinson & Bergstrom with ornamental features including a heavy cornice, etc.; major alteration to street-level frontage on both sides.
- 88. Wilson Building (431 S. Broadway): c. 1909; 3-story brick and concrete structure with massive alteration in 1932; facade ornament includes heavy cornice with brackets, columns topped by capitals, and floral designs on the surface.
- 90. Broadway Mart Center (401-23 S. Broadway): 1913; 10-story concrete structure by Parkinson & Bergstrom with a brick and terra cotta facade including many ornamental details.
- 91 Nelson Building (355 S. Broadway): 1897; 7-story brick and plaster structure originally by Frank Van Trees with a mass of ornamentation; alterations removed all ornament and left flat plaster surface with a rounded corner; still blends with the district although very plain now.
- 94. Karl's (341-45 S. Broadway): 1903; originally a four-story brick structure by A.M. Edelman, the building was altered to two stories but much of the original terra cotta decoration remains.
- 98. Grand Central Market (315 S. Broadway): 1897; Broadway elevation is a 6-story brick structure with terra cotta ornamentation including heavy cornice and arched entrance; large facade covering now hides much of it; Hill St. addition by Thornton Fitzhugh in 1905 is 8 stories with little alteration to it, mostly concrete with brick.
- 99. Million Dollar Theater (307 S. Broadway): 1917; 12-story concrete theater and office building by A.C. Martin in Spanish Renaissance design, theater interior by W.C. Woolett; much ornamentation with little alteration. (Nominated to National Register in September, 1977.)

NATIONAL PARK SERVICE UNITED STATES DEPARTMENT OF THE INTERIOR



L

INVENTORY -- NOMINATION FORM NATIONAL REGISTER OF HISTORIC PLACES

CONTINUATION SHEET ITEM NUMBER \ PAGE

Monconforming Intrusions Detracting From the Integrity of the District:

- alteration and most ornament removed; is potentially restorable. basement reinforced concrete and brick structure, now three stories with much Blackstone Building (318-322 S. Broadway): c. 1907; originally a 5-story and
- arched facade of stucco recently applied. Shannon Building (326 S. Broadway): c. 1912; 2-story brick structure with an
- Joe's Coffee Shop (328 S. Broadway): 1-story cement structure of recent vintage.
- awning; very recent origin. MGM Photographia (336 S. Broadway): 1-story cement structure in gold with an
- facade completely cluttered with signs. Judson's (346-8 S. Broadway): c. 1907; 1-story brick building divided in half;
- Licha's (412 S. Broadway): 1-story food stand of cement blocks, very contemporary. .01
- A & M Sportswear (438 S. Broadway): 1-story cement structure of contemporary design .ET
- . Ar (Food Stand) (444 S. Broadway): one-story structure of contemporary style.
- contemporary origin. California Imports (446 S. Broadway): 2-story cement block structure of .61
- Young with a new facade that completely covers the original. Gebhard Building (450 S. Broadway): c. 1900; 2-story brick structure by R.B. .91
- should be relatively easy to remove. windows and reliefs on facade; facade now completely covered by metal grate but Cliftons Cafeteria (648 S. Broadway): c. 1916; 4-story brick building with arched .55
- in 1974 left the building completely "modernized" with typical tile and glass facade. with a mass of terra cotta ornamentation by Morgan, Walls, & Morgan; alteration Haas Building (660 S. Broadway): 1914; a 12-story concrete structure originally
- concrete and steel in contemporary design with several stores below. Parking Structure (730 S. Broadway): c. 1967; multi-level parking structure of 36°
- "Burgers" (828 S. Broadway): one-story, concrete-block structure of recent origin
- .nigino Maggy's Clothing (847 S. Broadway): 1-story cement block structure of recent .23

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM



CONTINUATION SHEET

ITEM NUMBER 7

PAGE

- 53. Wig House (845 S. Broadway): 1-story cement block structure of contemporary origin.
- 56. Hartfield's (749 S. Broadway): c. 1912; 4-story brick structure with a very modern stucco facade.
- 58. Rowley Building (735 S. Broadway): c. 1908; 4-story brick building with a very modern "marble" facade.
- 64. Hoffman Building (635-37 S. Broadway): c. 1906; 4-story brick business building, although facade is fairly new it is potentially restorable and still similar to the original.
- 65. Baker Building (633 S. Broadway): c. 1911; 4-story brick structure with a newer facade that blends very well with the district.
- 66. C.H. Baker's (629 S. Broadway): c. 1911; northern half of the Baker Building, 4-story brick and concrete structure with facade completely remodeled in contemporary design.
- 67. Kress Building (621 S. Broadway): c. 1919; 5-story concrete and brick structure with new facade.
- 69. Eastman's (611 S. Broadway): 1930; part of the nortern flank of the Los Angeles Theater, 2-story concrete with facade of recent vintage.
- 71. Young Age Shop (609 S. Broadway): 1930; part of northern flank of Los Angeles Theater, 2-story concrete with new facade.
- 76. Barry's (543 S. Broadway): c. 1901; 4-story brick structure with 2 modern facades, 1 on each side.
- 78. Emperor Building (535 S. Broadway): c. 1903; 5-story brick structure with a contemporary, flat facade.
- 81. Reeves Building (525 S. Broadway): 1903; 5-story brick building by John Parkinson with a glazed metal and synthetic stone facade; very little original ornament which included a balcony and pediment was removed but facade is potentially restorable.
- 82. "Levis" (521 S. Broadway): c. 1903; 2-story brick structure with a flat stucco facade of recent origin.

86

':b

.96

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

The second of the second of the

blends somewhat with the district.



with facade stuccoed over the original ornamentation removed. Wise Shop (337-39 S. Broadway): c. 1900; 2-story (originally 4) brick structure . 66 stucco facade of recent origin. (Building) (347-9 S. Broadway): c. 1908; 2-story brick structure with a flat .56 flat stucco facade. Zobel Building (351 S. Broadway): c. 1912; 6-story brick structure with a new .26 Wise Shop #2 (425 S. Broadway): 3-story brick building with flat, modernized . 68 of recent design. Zody's (437 S. Broadway): c. 1942; 3-story structure with a flat stucco facade .78 .obsosf bezinrebom Newberry's Annex (443 S. Broadway): 4-story brick structure with flat, . 98 CONTINUATION SHEET R38MUM M3TI .

heavy cornice; altered in recent years to a flat stucco facade.

Broadway Market (329 S. Broadway): c. 1900; 3-story brick building that originally had an ornamental facade including arched window openings and a

Jacoby Brothers Building (333 S. Broadway): c. 1900; originally a 4-story brick structure with decorative cornice, this building was altered to two stories and some of the facade stuccoed flat; it is still similar to the original however and

PERIOD	, AR	EAS OF SIGNIFICANCE CH	ECK AND JUSTIFY BELOW	
PREHISTORIC 1400-1499 1500-1599 1600-1699 1700-1799	ARCHEOLOGY-PREHISTORICARCHEOLOGY-HISTORICAGRICULTURE XARCHITECTUREART	COMMUNITY PLANNINGCONSERVATIONECONOMICSEDUCATIONENGINEERING	LANDSCAPE ARCHITECTURELAWLITERATUREMILITARYMUSIC	RELIGIONSCIENCESCULPTURESOCIAL/HUMANITARIAN %_THEATER
<u>X</u> 1800-1899 <u>X</u> 1900-	XCOMMERCECOMMUNICATIONS	EXPLORATION/SETTLEMENTINDUSTRYINVENTION	PHILOSOPHYPOLITICS/GOVERNMENT	TRANSPORTATIONOTHER (SPECIFY)

SPECIFIC DATES

1893

BUILDER/ARCHITECT

various


STATEMENT OF SIGNIFICANCE

The Broadway Theater and Commercial District is a six-block thoroughfare containing the vestiges of the Los Angeles theater and commercial center developed from the early 1890's to the early 1930's. The area is significant not only for this activity, but also for the high concentration of important architectural creations which document the development of both commercial and theater growth in Los Angeles, and the evolution, of progressive design for these types of structures.

Prior to the turn of the century the commercial center in Los Angeles was located near the intersection of Spring and First Streets. The area of Broadway below Third Street was primarily residential until small businesses located there in the 1890's. Construction of the new city hall in the late 1880's on Broadway between Second and Third Streets was a primary impetus in turning the commercial district southward to take advantage of the close proximity of municipal headquarters. By 1900, several large business structures including the Bradbury Building (1893), the Grand Central Market (Homer Laughlin Block in 1897), the Nelson Building (Grant Building in 1897), and several smaller blocks, the O.T. Johnson Block (1895), the Hubert-Thom McAn Building (1900), and the Jacoby Brothers store (1900) began to change the Broadway skyline and pulled the business center further south.

The 1900-1910 period was a decade of rapid development in Los Angeles, as well as all of southern California. Broadway was a perfect example of this growth along just one street. Although many small blocks were built to about Sixth Street at this time, including the large O.T. Johnson Building (1902), Finney's Cafeteria (Gebhart Building in 1904), the Reeves Block (1903), the Remick Block (1902), Karl's Shoes (1903), and a number of small brick structures, the dramatic turning point in this development was the announcement that Hamberger's (now the May Company) was going to build a large department store at Broadway and Eighth Street, then generally considered too far south of the business district. This statement by one of the city's largest retailers was met with skepticism by local businessmen. However, as construction of Hamberger's began in 1905, many investors followed suit so that before the end of the decade a number of important structures were added to the district including the Trustee Building and O.T. Johnson Building #2 in 1905, the Judson-Rives, Bumiller, Hoffman, Norton, and Bullock's buildings in 1906, the Blackstone, Forrester, and Parmelee buildings in 1907, the W.P. Story and J.E. Carr structures in 1908, and the Barker Brothers and Wilson Buildings in 190

NATIONAL PARK SERVICE UNITED STATES DEPARTMENT OF THE INTERIOR



NATIONAL REGISTER OF HISTORIC PLACES

INVENTORY -- NOMINATION FORM

PAGE 1 S REMUMBER 8

CONTINUATION SHEET

retail trade and office space in the district. The Chapman Building and In the next decade still more new structures appeared which increased 1910, Broadway was the commercial and retail thoroughlare of the city.

1909) were built during this period to help support the district. By The Lankershim Hotel (1902) and the Yorkshire Hotel (J.D. Hooker Building in


theatrical center of Southern California. at this time, as were many of the theaters that eventually made broadway the area. Clifton's Cafeteria (Boos Brothers Restaurant in 1916) was also built (1912), the Metropolitan, Issacs, Cheney, and Broadway Mart Center buildings (1913), and the Merritt Building (1914) provided additional growth in this Baker Building (1911), the Jewelry Trades Building and Bullock's-Hollenbeck

parking structures and small food stands. of facade alterations and the addition of several intrusions which include and Reed's (1931), the only major changes since that time have been a number appears today was substantially complete by 1930. Other than Hartfield's Broadway Cafeteria (1928) and several more theaters, the district as it buildings (1929-30) were all completed during this decade. Along with the (1924), the Chester Williams Building (1926), the Anjac Fashion Building and the Fifth Street Store (1927), and the Winth & Broadway and Eastern-Columbia Apparel Center Building (originally the Wurlitzer Building) in 1923, Desmond's buildings (1922), the Metropolitan Theater Annex and the highly colorful worth's, and the Swelldom Building (1920), the Singer and Wood Brothers this decade. A number of notable structures including Silverwood's, Woolis probably best illustrated in the further development of Broadway during The real estate and building boom of Southern California in the 1920's

serves a clientele that, for the most part, resides in and near the downtown centers diminished the trade that once came to Broadway. The area now Los Angeles. Along with other factors, the increase of these shopping these centers to attract customers living a good distance from downtown retailers along Broadway found it convenient to place regional stores in suburban shopping centers began to increase in number and popularity, major continued to function in this capacity until well after World War II. As As the commercial center of the Southland, the Broadway district

ment of the theatrical district on this street. The Orpheum (now the Palace), House (now demolished) opened on Broadway and began the accelerated developand the Burbank) were located along Main Street. In 1903 the Mason Opera emergence as the theatrical center for the Southland. At the turn of the century the major theaters of Los Angeles (the Merced, Grand Opera House, The development of broadway as a commercial district coincides with its

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM



CONTINUATION SHEET

ITEM NUMBER &

PAGE 2


Clume's (now the Cameo), and the Pantages (now the Arcade) opened in 1911 and were the first theaters to locate within the present district. Following these pioneers were the Morosco (Globe) in 1912, the Rialto in 1917, the Million Dollar in 1918, Loew's State Theater (United Building) in 1920, the Metropolitan in 1923, the new Orpheum in 1925, the Tower in 1928, the Los Angeles in 1930, and finally the Roxie in 1931. Of these, only the Metropolitan has since been razed.

The importance of the theater district in the home of the motion picture industry is clearly evident. The theaters provided drama, comedy, and vaudeville presentations until full-length motion pictures became popular. Thomas Tally, Sid Grauman, Oliver Morosco, and others vied for the honor of city impresario as the theaters along Broadway became larger and more numerous. Theater architecture was more flamboyant than commercial styles and the influx of theatrical structures helped to provide variety for the Broadway streetscape. In all, theater development along Broadway provided a major source of revenue and a location for premieres for the movie industry, an important form of entertainment for Southern Californians, and a variety of architectural designs which gave a unique character to Broadway.

The xenith of the Broadway theater district was in the 1920's. In 1922 the Egyptian Theater was built on Hollywood Boulevard in the midst of movie studios, and in 1926 Sid Grauman's Chinese Theater opened further down the street. The major theater chains were now beginning to establish Hollywood as the center for motion picture theaters. Although several Broadway theaters were built as late as 1931, the new trend had already been clearly established.

It is surprising now that so many of the theaters built on Broadway have survived even though the theatrical center moved so long ago. The structures that remain on Broadway, typically flamboyant in design both inside and out, are still viable movie houses from both economic and functional standpoints. As older theatrical sections of many cities have since been leveled for new use, the Broadway theater network continues to provide motion picture entertainment in buildings that are remarkably intact considering their uninterrupted use over so many years.

Architecturally, the Broadway district contains some of the best examples of commercial and theater architecture in Southern California. The Bradbury Building, Million Dollar Theater, and Eastern-Columbia Building are well-known, and the Los Angeles Theater is considered to be the best example of theater architecture in the entire Southland. The district is represented by a number of important styles including American Commercial, Sullivanesque, Italianate (O.T. Johnson Block), Romanesque (Jewelry Trades Building and the



INVENTORY -- NOMINATION FORM INVENTORY -- NOMINATION FORM

ITEM NUMBER 8 PAGE 3

CONTINUATION SHEET

O.T. Johnson Building), Spanish Rensissance (United Building, Apparel Center Building, Million Dollar Theater, etc.), French Rensissance (Tower and Los Angeles theaters), Italian Rensissance (Merritt Building and Swelldom Building), Spanish Baroque (Desmond's), Cothic Revival (Anjac Reshion Building), Spanish Baroque (Desmond's), Cothic Revival (Anjac Reshion Building), and Isascs), Art Deco (Woolworth's, Hartfield's, and the Broadway buildings), among others. Architects from New York (Schultze & Weaver), Duildings), among others. Architects from New York (Schultze & Weaver), Welle (B. Marcus Pritects), Oakland (Weeks & Day), and San Francisco Gesttle (B. Marcus Pritects) Malla, R.B. Young, George Wyman, A.F. Well as local architects Morgan & Walls, R.B. Young, George Wyman, A.F. Aldrich, Walker & Eisen, Curlett & Beelman, S. Charles Lee, C. F. Whittlesey, and others have contributed to the architectural integrity of the street. Although not always consistent in scale, Broadway as a whole contains some of the best examples of commercial and theater architecture in Southern Of the best examples of commercial and theater architecture in Southern Scalifornia that could possibly be integrated in such a compact area.

County Archives.	County, 1900-1940. Los Angeles
	uildings & Safety. Los Angeles City Hall.
Greene and Behrendt Photograph Coll Natural History Archives. (see	lections. Los Angeles County Museum of continuation sheet)
10 GEOGPAPHICAL DATA ACREAGE OF NOMINATED PROPERTY 27 +	
QUADRANGLE NAME UTM REFERENCES 8 20 A / / / 3 8 9 8 7 0 3.7 6.8 3.4.6 ZONE EASTING NORTHING C / / 3 8 9 20 0 3.7 6.7 3.5.6	ZONE EASTING NORTHING
EL LILLI LILI	_ F
G VERBAL BOUNDARY DESCRIPTION	
(See Continuation Sheet)	The same of the property of the same of th
LIST ALL STATES AND COUNTIES FOR PROP	PERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES
STATE CODE	COUNTY
STATE CODE	COUNTY · CODE
11 FORM PREPARED BY	M. Deministrativa A. notour end demonstrate
NAME/TITLE Tom Sitton Curatorial Assistant	
Tom Sitton Curatorial Assistant ORGANIZATION	DATE
Tom Sitton Curatorial Assistant ORGANIZATION Los Angeles County Museum of Natura	DATE 1 History October 20, 1977
Tom Sitton Curatorial Assistant ORGANIZATION Los Angeles County Museum of Natura STREET & NUMBER	DATE 1 History October 20, 1977 TELEPHONE
Tom Sitton Curatorial Assistant ORGANIZATION Los Angeles County Museum of Natura STREET & NUMBER 900 Exposition Blvd.	DATE 1 History October 20, 1977 TELEPHONE 213-746-0410 x 241
Tom Sitton Curatorial Assistant ORGANIZATION Los Angeles County Museum of Natura STREET & NUMBER 900 Exposition Blvd. CITY OR TOWN	DATE 1 History October 20, 1977 TELEPHONE 213-746-0410 x 241 STATE
Tom Sitton Curatorial Assistant ORGANIZATION Los Angeles County Museum of Natura STREET & NUMBER 900 Exposition Blvd. CITY OR TOWN Los Angeles	DATE October 20, 1977 TELEPHONE 213-746-0410 x 241 STATE California
Tom Sitton Curatorial Assistant ORGANIZATION Los Angeles County Museum of Natura STREET & NUMBER 900 Exposition Blvd. CITY OR TOWN Los Angeles 12 STATE HISTORIC PRESERVATION	DATE October 20, 1977 TELEPHONE 213-746-0410 x 241 STATE California ION OFFICER CERTIFICATION
Tom Sitton Curatorial Assistant ORGANIZATION Los Angeles County Museum of Natura STREET & NUMBER 900 Exposition Blvd. CITY OR TOWN Los Angeles 12 STATE HISTORIC PRESERVATI THE EVALUATED SIGNIFICANCE	DATE October 20, 1977 TELEPHONE 213-746-0410 x 241 STATE California ION OFFICER CERTIFICATION E OF THIS PROPERTY WITHIN THE STATE IS:
Tom Sitton Curatorial Assistant ORGANIZATION Los Angeles County Museum of Natura STREET & NUMBER 900 Exposition Blvd. CITY OR TOWN Los Angeles 12 STATE HISTORIC PRESERVATI THE EVALUATED SIGNIFICANCE	DATE October 20, 1977 TELEPHONE 213-746-0410 x 241 STATE California ION OFFICER CERTIFICATION
Tom Sitton Curatorial Assistant ORGANIZATION LOS Angeles County Museum of Natura STREET & NUMBER 900 Exposition Blvd. CITY OR TOWN LOS Angeles 12 STATE HISTORIC PRESERVAT THE EVALUATED SIGNIFICANCE NATIONAL	DATE October 20, 1977 TELEPHONE 213-746-0410 x 241 STATE California ION OFFICER CERTIFICATION E OF THIS PROPERTY WITHIN THE STATE IS: LOCAL the National Historic Preservation Act of 1966 (Public Law 89-665). I nal Register and certify that it has been evaluated according to the vice.
Tom Sitton Curatorial Assistant ORGANIZATION Los Angeles County Museum of Natura STREET & NUMBER 900 Exposition Blvd. CITY OR TOWN Los Angeles THE EVALUATED SIGNIFICANCE NATIONAL	DATE October 20, 1977 TELEPHONE 213-746-0410 x 241 STATE California ION OFFICER CERTIFICATION E OF THIS PROPERTY WITHIN THE STATE IS: LOCAL the National Historic Preservation Act of 1966 (Public Law 89-665), I anal Register and certify that it has been evaluated according to the
Tom Sitton Curatorial Assistant ORGANIZATION LOS Angeles County Museum of Natura STREET & NUMBER 900 Exposition Blvd. CITY OR TOWN LOS Angeles 12 STATE HISTORIC PRESERVATI THE EVALUATED SIGNIFICANCE NATIONAL	DATE October 20, 1977 TELEPHONE 213-746-0410 x 241 STATE California ION OFFICER CERTIFICATION E OF THIS PROPERTY WITHIN THE STATE IS: STATE LOCAL the National Historic Preservation Act of 1966 (Public Law 89-665), I anal Register and certify that it has been evaluated according to the vice. Many M Eloc SHPO DATE SEP 7 1978

9 MAJOR BIBLIOGRAPHICAL REFERENCES

NATIONAL REGISTER OF HISTORIC PLACES

INVENTORY -- NOMINATION FORM

I TEM NUMBER 9 PAGE 1

CONTINUATION SHEET

Insurance Maps of Los Angeles, California. New York: Sanborn Map Company, 1906-37.

Los Angeles Daily Journal, October 4, 1895, 8; October 11, 1895, 8; May 7, 1897, 4; October 22, 1900, 4; Movember 2, 1900, 4.

Los Angeles Evening Express, November 21, 1927, p. 8.

.7 .q .4981 ,1 sanuar, .1seles Herald . J. 1894, p. 7.

Los Angeles Times, 1894-1977. (Articles on specific buildings are too numerous to list. See individual site survey sheets available at the California State Office of Historic Preservation or at the Natural History Museum of Los Angeles County.)

Exhibitor's Herald, April 28, 1928, p. 86; May 12, 1928, pil23.

Southwest Contractor & Manufacturer, May 11, 1912, p. 40; June 1, 1912, p. 40; June 1, 1912, p. 8.

Southwest Builder & Contractor, October 17, 1919, p. 17; January 9, 1920;

May 17, 1920, p. 10; July 16, 1920, p. 11; July 23, 1920, p. 16;

August 27, 1920, p. 13; September 3, 1920, p. 18; February 3, 1922,
p. 29; November 3, 1922, p. 14; January 21, 1924, p. 12; July 4, 1924,
p. 50; December 26, 1924, p. 51; May 20, 1927, p. 56; July 12, 1928, pp.
41-3; June 26, 1929, p. 56; May 31, 1929, p. 57; July 12, 1929, p. 67;
February 14, 1930, p. 19; February 28, 1930, p. 5; May 2, 1930,
p. 45; May 30, 1930, p. 25; January 24, 1941, p. 30; April 25, 1941, p. 40.

Architectural Digest, V, no. 2 (1926), 82-3; VI, no. 3 (1928), 31-3; VII, no. 2 (1931), 56-9.

Architect & Engineer, September 1911, pp. 34-50; May 1918, pp. 80-6; February 1923, pp. 60-70; June 1926, pp. 18-20, 67; July 1927, p. 77.

Boyarski, Bill & Mancy, "Picture Palace Splendor," Westways, September, 1971, pp. 11-17+.

"In Winter's Outdoor Land," Sunset, XX, n. 3 (January, 1908), 212-58.

Owen, J. Thomas, "The Theater in Los Angeles," Los Angeles County Museum Quarterly, Vol. I, no. 3-4 (Winter-Spring, 1962-3), 32-7.

Western Architect, Vol. 33, no. 9 (September, 1924), 105-6.

NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM




CONTINUATION SHEET

ITEM NUMBER Q

PAGE 2

- Gebhard, David, & Winter, Robert. A Guide to Architecture in Southern California. Los Angeles: Los Angeles County Museum of Art, 1965.
- Hall, Ben. The Best Remaining Seats. New York: Branhall House, 1961.
- Hill, Laurence L. <u>La Reina</u>: <u>Los Angeles in Three Centuries</u>. Los Angeles: Security Trust and Savings Bank, 1929.
- Scott, J.E. <u>Los Angeles</u>, the Old and the New. Los Angeles: Western Insurance News, 1911.
- Souvenir Office and Buildings Directory. Los Angeles: Howes & LeBerthnon, 1903.
- Vision. Los Angeles: Sun Drug Company, c. 1926.
- Works Projects Administration. Los Angeles: A Guide to the City and its Environs. New York: Hastings House, 1941.




NATIONAL REGISTER OF HISTORIC PLACES


ILEM NUMBER TO PAGE T.


CONTINUATION SHEET


then 120' northward to Third St., then 194'eastward to the original point. northward, then 166' westward to Hill St., then 121' northward, then 132' eastward, Street, then 59' eastward, then 125' northward, then 40' westward, then 240' eastward, then 80' northward, then 16' westward, then J22' northward to Fourth eastward, then 80' northward, then 16' westward, then 39' northward, then 42'northward, then 165' eastward, then 120' northward, then 42' westward, then 39' to Fifth St., then 200' northward, then 165' westward to Hill St., then 41' to Sixth St., then 29' eastward to Lindley Place, then north along Lindley Place northward to Sixth St., then 125' northward, then 138' eastward, then 80' morthward then 50' westward, then 470' northward to 7th St., then 10' eastward, then 80' northward to Eighth St., then 212' Eastward along Eighth St., then 116' northward St., then westward along Minth St. to a point 165' west pf Broadway, then 236' southward to Sixth St., then 15' westward, then southward along an alley to Ninth then 165' eastward to Spring St., then 120' southward on Spring St., then 117' Frank Court, to Fifth St., then 31' westward, then 100' southward, then 35' eastward southward, 23' eastward, 363' southward to Fourth St., then 39' westward to .8.67 ,biswits 186' eastward along Third St., 170' southward, 44' westward, 79.6' sides of Broadway beginning at the intersection of Broadway and Third Street, An irregular area in the downtown business district generally following both





ERIA JAOSE DIAMPIC 49. 83. 74 77. 54. 3 57 58 57. 60. ٠5٠٠ 34L 33. 62. 3. 65.























TTI - m104 OSAW (A881 anul "A")

Doundary selection

NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

volved ovitrasfedby

riginal (if known) physical appe	sous	
betsnoireteb sniur bezogxenu	Check one unaltered altered	Check one original site
say 🗌 Saldigila banimta	ou 🗀	
ng Surveys		
notiqi		
Ownership noisisionAbilduq	autst 2 eldisssooA	esU inesenq
working the hi suice proposity course	when descrip	Recom./Criteria Reviewer Assignment Discipline Date See continuation sheet
rsaupar 🗌 alqmas 🗀	I appear	noisiosh RM □
er and Commercial or local government		Working No. Fed. Reg. Date: Date Due: Action:
s gni	The frequest and the frequest frequency frequest frequency frequest frequency f	imple request appeal with property deauty was a second below technical corrections cited below substantive reasons discussed below Public Acquisition Public Acquisition Public Acquisition Check one Check one Instructions Check one Instructions Check one Instructions Check one Instructions Instruct

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form



Continuation sneet

Item number


10


Page]


VERBAL BOUNDARY DESCRIPTION (Revised 12/26/85)

(Note: All changes in direction are at a right angle from the previous direction.)

The boundary encompasses an irregular area in the downtown business district generally following both sides of Broadway beginning at the southeast corner of the intersection of Broadway and Third Street, extending 185.53' eastward along Third Street, then approximately 161' southward, 44.4' westward, 79.6' southward, 23' eastward, approximately 365' southward to Fourth Street, then continuing 60' southward across Fourth Street to Frank Court, then continuing southward along Frank court to the south side of Fifth Street, then 40' westward, then 100' southward, then 40' eastward, then 260' southward, then 165' eastward to Spring Street, then 119.6' southward on Spring Street, then 165.18' westward, then 120.5' southward to Sixth Street, then continuing southward 60' across Sixth Street, then continuing southward along an alley to the northern edge of Ninth Street, then westward approximately 163' along Ninth Street, then continuing 80' across Broadway, then continuing 165' westward, then approximately 235' northward, then 159.5' westward to Hill Street, then 363.5' northward along Hill Street to Eighth Street, then 212' eastward along Eighth Street, then 185.6' northward, then 50' westward, then approximately 550' northward to intersection of the northern edge of Seventh Street and St. Vincent Court, then approximately 158.5' westward to Hill Street, then 312' northward along Hill Street, then 138.4' eastward to St. Vincent Court, then 74.44' northward, then 138.37' westward, then 125' northward, then 158.34' eastward, then 140' northward to northern edge of Sixth Street at its intersection with Lindley Place, then northward along Lindley Place to northern edge of Fifth Street, then continuing approximately 201' northward, then 165.18' westward to Hill Street, then 41.87' northward, then 165.18' eastward, then 120.4' northward, then 12.82' westward, then 0.9' northward, then 13.71' westward, then 39.34' northward, then 42.41' eastward, then 79.56' northward, then 16.19' westward, then 0.14' northward, then 79.32' westward, then 123.6' northward, then 78.99' eastward, then 60' northward across Fourth Street, then 40.09' eastward, then approximately 124' northward, then 39.96' westward, then approximately 239' northward, then 165.88' westward to Hill Street, then 121.34' northward, then 132.5' eastward, then 120.36' northward to Third Street, then approximately 279' eastward to the point of beginning.







APPENDIX B

Department of Parks and Recreation Inventory Forms for Buildings within the Area of Potential Effects

THE REPORT OF THE

to a critical participation of the control of the property of the con-

PRIMARY RECORD E ET

☐ Artifact Record

DPR 523A (1/95) HRG

☐ Photograph Record ☐ Other:

Primary #
HRI#
Trinomial
Intervieus Code 1S

NRHP Status Code 1S Other Listings at the opportunities of the Review Code Reviewer Page 1 of 14 Resource Name or #: Broadway Theater and Commercial District P1 Other Identifier: P2. Location: Not for Publication Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; City c. Address d. UTM: Zone; mE/ e. Other Locational Data: P3a. Description: P3b. Resources Attributes: P4. Resources Present: □ Building □ Structure □ Object □ Site ■ District □ Element of District □ Other P5b. Description of Photo: P5a. Photo or Drawing P6. Date Constructed/Age and Sources: M Historic ☐ Both ☐ Prehistoric 1894-1931 P7. Owner and Address: unknown P8. Recorded by: Christy Johnson McAvoy Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028 P9. Date Recorded: 6/1/98 P10. Survey Type: Section 106 Review P11. Report Citation: None. Attachments:

NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record ☐ Rock Art Record Archaeological Record District Record ☐ Linear Feature Record ☐ Milling Station Record

Trinomial HRI# Brimary #

State of California - The Resources Agency DEPARTMENT OF PARKS AND RECREATION

DISTRICT RECORD

4 to Sage

NRHP Status Code 15

Resource Name or #: Broadway Theater and Commercial District

D1. Historic Name:

D3. Detailed Description:

D2. Соттоп Name:

The Broadway Theater and Commercial District is a densely developed section of Broadway stretching approximately seven blocks from Second Street on the north to Olympic Boulevard on the south. The buildings within the district are mostly one-story to twelve-story commercial buildings and motion picture theaters designed in a variety of Beaux Arts and period revival styles. Most contain street-level storefronts.

The district consists of sixty contributors, thirty-eight non-contributors, and three vacant lots. The district's high level of coherence can be attributed to several factors. First, the buildings all conform to a common setback, abutting the sidewalk. (see Continuation Sheet, p. 3)

D4. Boundary Description:

The district is bounded by the north of the property lines of 242 S. Broadway to the north, the south property line of 939-947 M. Broadway to the south, and by the rear property lines of all buildings facing Broadway to the east and west.

D5. Boundary Justification:

Changes of use and changes of density determine the borders of the district. While shopping and movie-going define the historic context of the Broadway district, Hill Street to the west and Spring Street to the east have historic uses different from those of Broadway. An adjacent stretch of S. Spring Street is listed in the National Register as a separate historic financial district.

(see Continuation Sheet, p. 4)

D6. Significance: Theme Architecture; Entertainment/Recreation; Commerce Area City of Los Angeles Period of Significance 1894-1931 Applicable Criteria A, C

The Broadway Theater and Commercial District is listed in the National Register of Historic Places. The district is significant under Criteria A and C. The area was the premiere shopping and moviegoing destination for Los Angeles residents and tourists through several periods of major growth during which the city became a major metropolis. The variety and quality of architecture on Broadway is evidence of its important place in the regional economy in the first decades of the twentieth architecture on Broadway is evidence of its important place in the regional economy in the first decades of the twentieth century. Some of the most prominent architects working in Los Angeles are represented within the district, which contains many important examples of movie palaces and retail and commercial architecture within a dense urban area.

Broadway first became a prominent street late in the 1880s, when proximity to the city's new municipal headquarters attracted major businesses to the street. The earliest retailers to establish stores on Broadway included Boston Dry Goods, Coulter's Dry Goods, Silverwood's, the Broadway Department Store, Bullock's Department Store, and Hamburger's (later the May Company). Through the first decades after the turn of the century, business on Broadway continued to boom.

(see Continuation Sheet, p. 4)

D7. References:

Community Redevelopment Agency. Broadway Theaters Entertainment District Study. May, 1995.

Gebhard, David and Robert Winter. Los Angeles: an Architectural Guide. Salt Lake City: Gibbs Smith, Publisher, 1994.

(see Continuation Sheet, p. 5)

D8. Evaluator: Christy Johnson McAvoy

Affiliation and Address: Historic Resources Group, 1728 Whitley Ave., Hollywood

State of California – The Resources Agency DEPARTMENT OF PARKS AND RECREATION CONTINUATION SHEET

Primary #
HRY#**/
Trinomial

Page 3 of 14

Resource Name or #: Broadway Theater and Commercial District

Recorded by: Historic Resources Group

Date: 6/1/98

Continuation Update

D3. Description, continued.

Second, while the styles of the buildings vary, the buildings are clad in many of the same materials, notably cast and glazed terra cotta, glazed brick, and cast stone.

The buildings range in size from small, one or two story retail buildings to large, 150-foot office buildings, and department stores with very large footprints. The range also includes mid-size loft buildings which were designed with large, open upper floors for several possible uses. Many of the most architecturally distinct or unusual buildings are designed as the flagship stores of retailers, such as the stores built for Silverwood's (558 S. Broadway), and Desmond's (614 S. Broadway).

The buildings in the district are all designed in traditional architectural styles. The most common style is the Beaux Arts, which in commercial buildings usually exhibits a division of the building's elevation into three horizontal zones based on the parts of a column in Classical architecture. This consists of a "base," composed of a first floor and mezzanine level, a relatively unornamented "shaft," composed of repeated floors containing offices, and a "capital," the ornamented and often projecting cornice or elaborated top floor of the building. Most of the buildings are further articulated with the use of classical elements such as pilasters, engaged columns, floral swags, and escutcheons. Such ornamentation is often executed in glazed terra cotta.

The second most common architectural style of Broadway buildings is Art Deco, or Zig-Zag Moderne. The most noted examples of this style are the green and blue glazed terra cotta Eastern Columbia Building, and the Ninth and Broadway Building, clad largely in cast stone with ornamental bronze panels. Also present on Broadway are styles such as Gothic Revival in buildings from the 1920s and late Streamline Moderne buildings, mostly from the 1930s and 1940s.

In addition to the buildings, streetscape features such as sidewalks and streetlights have been determined character-defining features of the Broadway Theater and Commercial District since they contribute to the sense of historic time and place.

All of the streetlights on Broadway between Second Street and Olympic Boulevard have original bases, but their poles and lamps have been replaced. There are two styles of historic bases, both of which were installed in 1920. These lamps were elaborately ornamented with stylized motifs from nature. Like many of the Beaux Arts buildings on the street, the lights consisted of a tripartite composition, with base, shaft, and capital. The bases, which still remain, are covered with ornament of stylized leaves and flowers. The shaft, or pole, consisted of a climbing vine with two lanterns forming the capital. The acorn-shaped lanterns branch off from the shaft in an elaborate scroll.

Broadway's sidewalks are characterized by a variety of materials, patterns, and colors. Sidewalks often extended beyond the property line into the foyer of the buildings providing a visual link between interior and exterior, and encouraging pedestrian traffic to enter theaters and department stores. Stamped, stained concrete is the most common form of sidewalk material on the street. The basements of most of the buildings extend out to the street line below the sidewalk. In several places, cast iron vents and glass blocks are inserted into the sidewalks to light these below-grade storage areas, which are accessed by way of cast steel doors in the sidewalk.

The district is notable, however, for the quality and variety of its terrazzo sidewalks, present in front of some stores and most theaters on Broadway. These sidewalks often extend from the lobbies to the curb. The elaborate patterns seen at Clifton's Cafeteria, the Eastern Columbia Building, and the Los Angeles Theater are some of the most important examples. Each represents a particular style of terrazzo ornamentation: the sidewalk at Clifton's depicts scenes of California, that in front of the Eastern Columbia Building is an abstract, geometric Art Deco design, and the fleur-de-lis motif in front of the Los Angeles Theater enhances the more traditional revival style of the theater. Other notable terrazzo sidewalks include the sunburst pattern in front of the Roxie Theater.

(see Continuation Sheet, p. 4)

Trinomial #IAH Primary #

Date: 6/1/98

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

CONTINUATION SHEET

Resource Name or #: Broadway Theater and Commercial District

■ Continuation □ Update

Recorded by: Historic Resources Group

D3. Description, continued

floors of the vast majority of the buildings remain intact. design meant to "update" the buildings as the district fell out of favor with new generations of shoppers. However, the upper mezzanine or second floor) of the buildings have been stripped of their original features and/or reclad with a new, incompatible The most severe alterations to the district are the modification of storefronts. In many cases, the entire bases (ground floor and

DS. Boundary Justification, continued

parking. in the north towards Second Street. In the south toward Olympic Boulevard, a large amount of land is now used for surface the northern and southern boundaries. Surface parking lots, parking garages, and large, newer office buildings begin to dominate main use shifts to the light industrial garment district. Changes in density due to the demolition of the historic fabric also define North of Second Street, the main use changes to governmental offices as one approaches the Civic Center. South of Olympic, the

D6. Significance, continued

stores aspired. could recognize them when they arrived on Broadway to shop, and to communicate the level of taste and prestige to which the flagship stores of retailers. These buildings were commonly featured in the advertisements for the stores, both so that people when they built a new store at Minth Street. Many of the most architecturally distinct or unusual buildings are designed as the and Hamburger's at Minth Street. In 1918, Blackstone's Dry Goods joined the department stores at the south end of Broadway retail establishments. Both companies built major buildings in 1906 to serve as their flagship stores, Bullock's at Seventh Street structures. Pioneering the south end of Broadway were Bullock's and Hamburger's Department Stores, two of the region's largest Many commercial establishments outgrew their original small-scale headquarters and began to develop large, multi-story

character as a destination for the disparate regions of the city. Angeles. Two major street car lines carried passengers from throughout Los Angeles to shop on Broadway, increasing its The intersection of Seventh Street and Broadway, near the center of the district, was the major crossroads of downtown Los

Theater, which is now the Globe. Palace. A few years later, full-scale dramatic productions were brought to Broadway with the construction of the Morosco Orpheum and the Pantages, to locate there. In 1910, the Orpheum circuit constructed a theater on Broadway now named the Broadway's status as the new theater district was boosted by the decision of the West Coast's two major vaudeville circuits, the region. Around 1910, nickelodeons and vaudeville theaters began to appear on Broadway, drawing business downtown. Broadway's preeminence as the commercial core of Los Angeles was matched by its growth as the leading theater district for the

the State Theater in 1921. theaters on the street. Loew's became the first national film house chain to establish a presence on Broadway with the opening of considered the city's first movie palace. Graumann quickly added the nearby Rialto and Paramount to his growing chain of Sid Graumann built the first theater on Broadway specifically designed for film exhibition in 1918. His Million Dollar Theater is

palaces in the world and a combined seating capacity of more than 15,000. downtown Los Angeles. With a dozen major theaters in a six block area, Broadway contained the highest concentration of movie new Orpheum Theater was constructed farther south on Broadway. By 1930, every major film studio had secured an outlet in The vaudeville theaters were forced to upgrade their facilities in an effort to compete with expanding movie audiences. In 1925, a

CONTINUATION SHEET

Primary # HRI# Trinomial

Page 5 of 14

Resource Name or #: Broadway Theater and Commercial District

Recorded by: Historic Resources Group

Date: 6/1/98

■ Continuation □ Update

D6. Significance, continued

In the next several decades after 1930, Broadway began to lose its central role as the theater and commercial core of the city. As the white clientele moved away from downtown into the suburbs, so did the lavish movie theaters and department stores. The demise of a city-wide public transit system and the rise of automobile ownership also contributed to the dispersal of white, middle class audiences from the downtown area.

After World War II, the patronage of the Mexican-American population living close to downtown transformed Broadway into a Latino-oriented shopping district. While the ground floors of many buildings have been altered (see Description), most buildings remain essentially intact. Unlike other parts of downtown Los Angeles which have completely lost their historic character through demolition of buildings and alteration of street patterns, Broadway remains in many ways the street that it was in the 1920s and 1930s.

D7. References, continued

Gleye, Paul. The Architecture of Los Angeles. Los Angeles: Rosebud Books, 1981.

Longstreth, Richard. City Center to Regional Mall: Architecture, the Automobile, and Retailing in Los Angeles, 1920-1950. Boston: MIT Press, 1997.

Los Angeles Department of Building and Safety Records, historical building permits.

National Register of Historic Places Registration Form, Broadway Theater and Commercial District, 1979.

Sanborn Fire Insurance Maps, 1953

42) 731 S. Broadway 41) 722 S. Broadway

27) 558 S. Broadway

25) 553 S. Broadway

20) 533 S. Broadway

22) 537-541 S. Broadway

16) 517-519 S. Broadway 15) 510 S. Broadway 14) 501-515 S. Broadway

11) 451-457 S. Broadway

39) 714-720 S. Broadway

(Continued on next Continuation Sheet)

40) 719 S. Broadway (Woolworth's)

38) 710 S. Broadway (Yorkshire Apartments)

36) 644 S. Broadway (J. E. Carr Building)

34) 638 S. Broadway (Forrester Building) 33) 626-636 S. Broadway (Palace Theater)

30) 612-616 S. Broadway (Desmond's)

24) 548 S. Broadway (Eden Hotel)

28) 601-605 S. Broadway (Norton Building)

31) 609-619 S. Broadway (Los Angeles Theater)

29) 600-610 S. Broadway (Walter P. Story Building)

26) 555-559 S. Broadway (Swelldom Department Store)

21) 534 S. Broadway (Arcade (formerly Pantages) Theater)

19) 527-531 S. Broadway (Schulte United/Broadway Interiors) 18) 528 S. Broadway (Clune's Broadway/Cameo Theater)

23) 540 S. Broadway (Broadway Arcade Building)

13) 500-508 S. Broadway (Jewelry Trades Building) 12) 452-460 S. Broadway (Chester Williams Building)

17) 516-522 S. Broadway (Roxie Theater)

10) 431-435 S. Broadway (Wilson Building)

6) 340-344 S. Broadway (Trustee Building) 5) 315 S. Broadway (Grand Central Market)

3) 300-310 S. Broadway (Bradbury Building)

1) 242 S. Broadway (Victor Clothing Company)

8) 424 S. Broadway (Broadway Central Block)

7) 401-423 S. Broadway (Broadway Department Store)

2) 249-251 S. Broadway (Irvine Block/Pan American Building)

37) 701-717 S. Broadway (Loew's State Theater Building)

35) 639-657 S. Broadway (Hollenbeck Block/Bullock's Department Store)

32) 618-622 S. Broadway (Schaber's Cafeteria/Broadway Cafeteria)

#IAH Primary #

DEPARTMENT OF PARKS AND RECREATION

State of California -- The Resources Agency

9) 430 S. Broadway (Bumiller Building/Campbell W. Blake Building)

4) 301-313 S. Broadway (Million Dollar Theater/Metropolitan Water District Building)

CONTINUATION SHEET

Resource Name or #: Broadway Theater and Commercial District

Recorded by: Historic Resources Group

List of Contributing Buildings:

Page 6 of 14

Date: 6/1/98

■ Continuation □ Update

Primary # HRI# Trinomial

CONTINUATION SHEET

Page 7 of 14

Resource Name or #: Broadway Theater and Commercial District

Recorded by: Historic Resources Group

Date: 6/1/98

Continuation Update

List of Contributing Buildings, continued:

- 43) 737-747 S. Broadway
- 44) 744-748 S. Broadway (Globe Theater)
- 45) 750-758 S. Broadway
- 46) 757-761 S. Broadway
- 47) 801-835 S. Broadway (Hamburger's/May Co. Department Store)
- 48) 800-804 S. Broadway (Tower Theater)
- 49) 806-808 S. Broadway (Singer Building)
- 50) 812 S. Broadway (Rialto Theater)
- 51) 814-818 S. Broadway
- 52) 820-824 S. Broadway
- 53) 830-834S. Broadway
- 54) 842-848 S. Broadway (Orpheum Theater)
- 55) 849 S. Broadway (Eastern Columbia Building)
- 56) 850-860 S. Broadway (Ninth and Broadway Building)
- 57) 901 S. Broadway (Blackstone's Department Store/U.S. Post Office)
- 58) 908-910 S. Broadway
- 59) 921-937 S. Broadway (United Artists Theater/Texas Oil Company Building)
- 60) 939-947 S. Broadway (Western Costume Building)

CONTINUATION SHEET

Page 8 of 14 Resource Name or #: Broadway Theater and Commercial District

■ Continuation □ Update Date: 6/1/98 Recorded by: Historic Resources Group

_
II) 900-906 S. Broadway
kk) 839-847 S. Broadway
ii) 828 S. Broadway
Vision of the Street of the St
gg) 730 S. Broadway hh) 735 S. Broadway
ff) 700-708 S. Broadway 22) 730 S. Broadway
ee) 660 S. Broadway Olympia S. Broadway
dd) 648 S. Broadway
cc) 635 S. Broadway
bb) 633 S. Broadway
aa) 629 S. Broadway
z) 621-625 S. Broadway
y) 543-547 S. Broadway
x) 535 S. Broadway
w) 523-525 S. Broadway
v) 450 S. Broadway
u) 443-445 S. Broadway
the Street Stree
s) 437 S. Broadway
q) 400-422 S. Broadwayr) 425-429 S. Broadway
p) 356-364 S. Broadwayq) 400-422 S. Broadway
o) 355-359 S. Broadway
n) 351-353 S. Broadway
m) 350-354 S. Broadway
I) 347-349 S. Broadway
k) 346 S. Broadway
j) 341-343 S. Broadway
i) 337-339 S. Broadway
h) 336 S. Broadway
g) 331-335 S. Broadway
f) 327-329 S. Broadway
e) 328-330 S. Broadway
d) 324-326 S. Broadway
c) 318-322 S. Broadway
a) 248-200 S. Broadway b) 312 S. Broadway
a) 248-260 S. Broadway
List of Non-Contributing Buildings:
Litting anitudiated and 30 toi 1
./

Primary # HRI# Trinomial

CONTINUATION SHEET


Page 9 of 14

Resource Name or #: Broadway Theater and Commercial District

Recorded by: Historic Resources Group

Date: 6/1/98

200 block of S. Broadway, view north



300 block of S. Broadway, view north



Trinomial HBI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

CONTINUATION SHEET


Page 10 of 14 Resource Name or #: Broadway Theater and Commercial District

■ Continuation □ Update


Date: 6/1/98

Recorded by: Historic Resources Group

400 block of S. Broadway, view north



500 block of S. Broadway, view north



Primary # HRI# Trinomial

CONTINUATION SHEET


Page 11 of 14

Resource Name or #: Broadway Theater and Commercial District


Recorded by: Historic Resources Group

Date: 6/1/98





700 block of S. Broadway, view north



Trinomial HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

CONTINUATION SHEET


Page 12 of 14 Resource Name or #: Broadway Theater and Commercial District

Date: 6/1/98 ■ Continuation □ Update

Recorded by: Historic Resources Group



900 block of S. Broadway, view north



MAP SHEET

Primary #	alloger is or seem a transport of the
HRI#/Trinomial	

Page _13_ of _14_

Resource Identifier: Broadway Theater and Commercial District

Map Name: District Boundaries Scale: none Date: 1990/1998

Northern portion of the district, Second Street to Sixth Street.

Contributors to the district are indicated by lighter shade and marked with numbers.

Non-Contributors are indicated by darker shade and marked with letters.

Numbers and letters coordinate with the list on Continuation Sheets, pages 6 though 8.

Vacant (parking) lots are indicated with:



Proposed District Boundary

Existing District Boundary

2ND STREET 4TH STREET 5TH STREE PERSHING SQUARE

Source for base map: Community Redevelopment Agency, Broadway Theater Entertainment District Study, 1990.

Primary #

DEPARTMENT OF PARKS AND RECREATION State of California - The Resources Agency

MAP SHEET

Isimonin™HRI#IRH

Resource Identifier: Page 14 of 14

Map Name: District Boundaries

BEATS HIT by lighter shade and marked with numbers. Contributors to the district are indicated HILL STREET 2csle: auou 8661/0661 Date:_ Broadway Theater and Commercial District

09

65

THEFT STREET

Sixth Street to Olympic Boulevard. Southern portion of the district,

and marked with letters. Non-Contributors are indicated by darker shade

Continuation Sheets, pages 6 though 8. Numbers and letters coordinate with the list on

Vacant (parking) lots are indicated with:

District Boundary

Existing District Boundary

PRIMARY RECORD

Primary #

HKI#	
Trinomial	
NRHP Status Code	.6

Page 1 of 1

Resource Name or #: Broadway Streetscape Improvement Project

P1. Other Identifier:

P2. Location: Not for Publication III Unrestricted

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

Other Listings

b. USGS 7.5' Quad T; R; 1/4 of 1/4 of Sec; Date

c. Address 200-206 S BROADWAY City Los Angeles Zip 90012

Review Code _____ Reviewer


d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

This one-story commercial building has been completely altered. The building appears to have originally been three stories, but its height was modified. Located on a corner, the building has a square plan covered by a flat roof with a parapet. Storefronts open on to Broadway, and the building is clad mostly in metal siding. It is in fair to good condition, and retains almost no outwardly visible original fabric.

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories P4. Resources Present: ■ Building □ Structure □ Object □ Site □ District □ Element of District □ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic □ Both ☐ Prehistoric Pre-1905 (F) Building Permit

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave., Hollywood

P9. Date Recorded:

P10. Survey Type: Section 106 Review

P11. Report Citation: None.

Attachments:	M NONE	□ Location Map		Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
☐ Archaeologica	I Record	☐ District Reco	rd	☐ Linear F	eatu	re Record	☐ Milli	ng	Station Record	Rock Art Record
Artifact Record	☐ Phot	ograph Record		Other:						- E
DPR 523A (1/95) H	IRG									

HBI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code	6 K 5
Trinonial	
403111	

	196	e Improvement Proje	or #: Broadway Streetscape	Resource Name
1 2 8 1	_ Date		Reviewer	Review Code
	1.50			Other Listings
		710 anno smp	ועעווג פר	and the second of the second of

Page I of I

P2. Location: 🗆 Not for Publication 📓 Unrestricted a. County Los Angeles P1. Other Identifier: Goodwill Industries

T; R; 1, of 1, of Sec; and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 235 S BROADWAY City Los Angeles Zip 90012 b. USGS 7.5' Quad Date B.M.

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

P3a. Description:

the south have adjacent, recessed entrance bays. The building is in good condition, but retains almost no original fabric. central portion has a series of three storefronts constructed of metal and glass panels with metal enframements. The storefronts to This one-story commercial building has been completely altered, and only the side walls remain from the original structure. The

P5b. Description of Photo: ■ Building □ Structure □ Object □ Site □ District □ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

Attachments:

NONE | Location Map | Sketch Map | Continuation Sheet | Building, Structure, and Object Record

Pre-1905 (F) Building Permit □ Prehistoric Sources: Mistoric □ Both P6. Date Constructed/Age and

P7. Owner and Address:

пикпочп

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Rock Art Record

☐ Milling Station Record

					,,-,,0 ,	
		_ 1 = =				
	and the second second					
	e e e e e e e e e e e e			· · · · · · · · · · · · · · · · · · ·	7 - 1	ne de la companya de La companya de la co
				•i;		
3,11	4	j = 3			i	
源						-0551
	- 	В	TILMGOOD	6	7.63 B	3qU. IBYAH
	7	1 .		連盟		
1	d 1, 5	2				
7 8					Ļ	
Ā					· ·	
				IJ	niwerA to o	PES DPOF

Citation	Report	116

Ofher:		thy Record	otogra	U bp	D Artifact Record
☐ Linear Feature Record	ord	District Rec		Record	□ Archaeological

DPR 523A (1/95) HRG

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

District Record

PRIMARY RECORD

Primary # HRI# Trinomial

NRHP Status Code 553

	-	NRHP Sta	atus Code 553		
	Other Listings				
	Review Code	Reviewer		Date _	
Page 1 of 1	Resource Name	or #: Broadway Streetscape	Improvement P	Project Project	
and (P2b and P2C b. USGS 7.5' Qua	I S BROADWAY City L	a. county	Los Angeles		ž
e. Other Locationa	I Data:				

P3a. Description:

P11. Report Citation:

DPR 523A (1/95) HRG

☐ Archaeological Record

☐ Artifact Record ☐ Photograph Record

One-story concrete frame commercial building. The storefronts have been completely altered, and the upper half of the structure has been covered by signage. Formerly the Boston Dry Goods store, the building retains little original fabric visible on the primary facade. The building was evaluated as a 5S3 in 1992, presumably due to the historic significance of its original use, and does not contribute to the Broadway Theater and Commercial District.

Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other P4. Resources Present: P5b. Description of Photo: P6. Date Constructed/Age and Sources: M Historic □ Both ☐ Prehistoric 1895 (E) State Inventory P7. Owner and Address: W: DUING CHAPEL unknown ENTOS CASAMIENTOS LEGALES P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028 P9. Date Recorded: P10. Survey Type: Section 106 Review

Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record

☐ Milling Station Record

☐ Rock Art Record

☐ Linear Feature Record

PRIMARY RECORD

Primary # HRI# Trinomial

NRHP Status Code 2D2

Other Listings Review Code Reviewer Page 1 of 2 Resource Name or #: Broadway Theater and Commercial District P1. Other identifier: Victor Clothing Company P2. Location: Not for Publication Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; c. Address 242 S BROADWAY City Los Angeles Zip 90012 d. UTM: Zone: mE/ mN e. Other Locational Data:


P3a. Description:

This five-story building was constructed of masonry in an early 20th century commercial vernacular style with some elements of Beaux Arts massing and detailing. The flat roof is surrounded by a parapet. Following design conventions common for multi-story commercial buildings, the facade is anchored by a base which consists of the first-story retail spaces and the mezzanine level above. This base has been altered: the original fenestration has been replaced with large, plate glass windows with thin metal frames. A continuous white brick string course separates the base from the remainder of the facade. The second through fourth floors form the main body of the building, which features three bays of paired window openings with contrasting, white brick sills. The fenestration of these openings is very broad, wood frame, single pane, double-hung windows. A fire escape of ornamental iron work is affixed to the central bay. The south of the building is devoid of fenestration, having been intended to abut the neighboring building. Terminating the primary facade is an overhanging cornice, which is punctuated by four corbels corresponding to the division of the three bays. The cornice contains the best remaining examples of the building's original ornamentation, since the first-story base is altered. Monumental public murals cover the north and south walls of the building, by artists Eloy Torrez, Frank Romero, and Kent Twichell. Interior murals are by John Valadez and John Garduno. Murals were executed between 1977 and 1985. The condition and integrity of the building are fair to good.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present:

Building Structure Object Site District Element of District Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

1914 (F) Building Permit

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson McAvoy Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded: 6/1/98 P10. Survey Type: Section 106 Review

Attachments:	□ NONE	☐ Location Map	☐ Sketch Map	□ Continuation	Sheet 🖪	Building, Structure,	and Object Record
		District Reco		eature Record	☐Milling	Station Record	☐ Rock Art Record
☐ Artifact Record	d Photo	ograph Record	☐ Other:				
DPR 523A (1/95) H	HRG						

HINH Primary #

B4. Present Use: retail/offices

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

BUILDING, STRUCTURE, AND OBJECT RECORD

NRHP Status Code 2D2

Page 2 of 2

Resource Name or #: Broadway Theater and Commercial District

B1. Historic Name:

B2. Common Name: Victor Clothing Company

B3. Original Use: retail/offices

B5. Architectural Style: Late 19th and 20th Century Revivals: Beaux Arts

B6. Construction History:

B8. Related Features: BY. Moved? Mo U Yes U Unknown Date: Original Location:

B9a. Architect: b. Builder:

Period of Significance Property Type Applicable Criteria A, C B10. Significance: Theme Architecture; Entertainment/Recreation; Commerce Area City of Los Angeles

buildings, and office buildings thoughout Southern California. Arroyo Guild of Fellow Craftsmen around 1909. Their work includes many residences, churches, government and institutional Monrovia. Robert F. Train and Robert E. Williams began their architectural partnership in 1900, and were associated with the Commercial Historic District. It was designed by architects Train and Williams for original owner Mrs. J. F. Hoeffeld of This commercial building is eligible for listing in the National Register as a contributor to the Broadway Theater and

number of uses which might occupy the building during its lifetime. street, with retail spaces opening on the sidewalks. The loft spaces on the upper floors were intended to be flexible for any the century until the decades following World War II. Buildings such as this contributed to the lively retail atmosphere of the for storage, and loft spaces on the upper floors. Broadway was the principal shopping district of Los Angeles from the turn of Commercial buildings such as this property were built with retail spaces on the first story, corresponding mezzanines above

Broadway is one of the features which greatly contributes to the coherence of the district. tall building, is characteristic of the other buildings in the district. Collectively, the repetition of this pattern down the length of The Beaux Arts massing of the building into a base, shaft, and capital, a design convention which helps to visually organize a

B11. Additional Resource Attributes: 07 Commercial Building, over 3 stories

Automobile, and Retailing in Los Angeles, 1920-1950. Boston: MIT Longstreth, Richard. City Center to Regional Mall: Architecture, the Form, Broadway Theater and Commercial District, 1978.

B12. References: National Register of Historic Places Nomination

Building Permits. Los Angeles Department of Building and Safety Records, Historic

1728 Whitley Ave., Los Angeles, CA 90028 B14. Evaluator: Christy Johnson McAvoy, Historic Resources Group,

Date of Evaluation:

Press, 1997.

YTTEL TREE! 5 20 3

242

S. BROADWAY

(This space reserved for official comments.)

PRIMARY RECORD

P3a. Description:

Primary #
HRI#
Trinomial

		NRHP Status Code 6 Y 2						
	Other Listings							
	Review Code	Reviewer	maddesk sales	Date				
Page I of I	Resource Name	or #: Broadway Theater a	nd Commercial Dist	riet				
P1. Other Identifier: P2. Location: Not	for Publication 🛮 Unrestrict	ted a. Count	y Los Angeles					
and (P2b and P20	C or P2d. Attach a Location Ma	p as necessary.)	nalay	A ROLL LID				
b. USGS 7.5' Qua c. Address 248-2 d. UTM: Zone;	60 S BROADWAY City Lo	of 1/4 of Sec; B.M. os Angeles Zip 90012		Medical Secret				
e. Other Locations	al Data:							

This two-story, concrete frame commercial building is clad in stucco and tile with metal ornamentation. All of the exterior finishes and design are not original to the building, which now contains a restaurant space on the ground floor. Most of the roof is flat, and a sloping roof clad in red clay tile is attached to the parapet along the Third Street and Broadway facades. The roof is punctuated by hipped-roof towers at the corners of the plan. One of these towers faces a chamfered corner at Third Street and Broadway. The building was originally three stories high, and has been completely altered. It is in fair to good condition.

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

P4. Resources Present: Building Structure Object Site District Element of District Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

P11. Report Citation:

Attachments: NONE	☐ Location Map	Sketch Map	Continuation Sheet	t 🛮 Building, Structur	e, and Object Record
☐ Archaeological Record ☐ Artifact Record ☐ Photo DPR 523A (1/95) HRG			ire Record ☐M	lilling Station Record	Rock Art Record

					1
Date(s) of enclosed photograph(s) April 1983	721				
Frontage 119.96 Depth 110.06					
Approx. property size (in feet)	111				
Builder	10.				
			SOLOHED PHOTOS	EE	
ellsw & nagroM restirenA	.6			Marie Bull you	
Estimated Factual 1894					
Construction date:	.8		eneH (2)otoff rostA		
any major alterations from its y commercial district, th structure influenced by the rises in three tiers. The he detailing of the office A decorated arch accente e Pan American Building burth floor bays, faced with urth floor bays, faced with ow and one, two window bays	f the Broadwar enth century s the building ust visible th the east, ntified as the nd through for	ion of the site or sur- in north edge or in late nineteed construction, id, leaving ju the north on ilding is iden if, The secon	Located at the gramps of the story start of the story yle. Of brick of fronts are altered by the story inguishes the entituded by lonic pillined by lonic pi	Architectural style: Briefly describe the original condition: cal Revival at level store a keystone, a keystone, a letters, dist rick, are def	7b. Pan Am Classi street buildi with raised
sal/ Offices	use: Commerci:	SeniginO	mercial/ Offices		
X systim	wnership is: Public	Zip 90216 o	Hills, Ca.	CILA BEVETLY	
ss: 9879 Santa Monica Bl.	earbbA		Lerner, Moses	Present Owner:	·9
Parcel 2.	,06 of Lot 1,	Jock 5, SE 110	Ord's Survey, B	Parcel number:	' p
Los Angeles	County	1006 diZ	ejea	City Los Ang	
ga wallanga.		En Broadeay	nos 657-677 :ssa.	Street or rural add	10
gnibling na:	3; Pan Americ	1 4	5 036 076		. €
Residen			Itaine Block;	Historic name:	3.
		Byrne Building		막님님	.i 2
0 _		Byrne Building	Pan American Bu	FICATION Common name: —	IDENTI 1.
- 207 - 1H2 - RH - 8 - RH - 0		Syrne Building	Itajue Block;	HISTORIC RESOL	IDENTI 1.

13.	Condition: ExcellentGoodY Fair Deterior	ated No longer in existence
14.	Alterations: Minor to street level frontage	; repair work resulting from fire damage
15.		d Scattered hulldland B 1 1 11
16.	Threats to site: None known Private development Public Works project Other:	Zoning '/andalism
17.	Is the structure: On its original site? Moved?	Unknown?
18.	Related features:None	The state of the s
The Brother the was rep wer Bui Angits exa	Irvine Block. The prominent Los Angeles as edifice. James W. Byrne purchased the sknown as the Byrne Building. An importanized structural elements of the building e necessary after fire damage. The struct lding during the World War II period, wheles. The Pan American Building is signification by a prominent local architectural	de dates, events, and persons associated with the site.) northwest corner of the West Third Street and structed in 1894, and was originally known as architectural firm of Morgan & Walls designed structure c.1905. Subsequently the structure ant Los Angeles contractor, Carl Leonardt, using reinforced concrete in 1911. Repairs ture became identifiable as the Pan American aren it housed the Mexican Consulate in Los cant for its age, its architectural quality, firm, and as a stylistic and representative ageles' Central Business District during the
20.	Main theme of the historic resource: (If more than one is checked, number in order of importance.) Architecture Arts & Leisure Economic/Industrial Exploration/Settlement Government Military Religion Social/Education	Locational sketch map (draw and label site and surrounding streets, roads, and prominent landmarks): NORTH
21.	Sources (List books, documents, surveys, personal interviews and their dates).	
	SEE BIBLIOGRAPHY	SEE ATTACHED MAP
22.	Date form preparedIanuary_ 1983 By (name)Richard Starzak, Leslie Heumann OrganizationHarheway & Associates Address:1633 Westwood BlSte203 CityLos Angeles _ CaZip90024 Phone:(213) 478-1176	

Trinomial HRI# # Yramin9

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

CONTINUATION SHEET


Resource Name or #: Broadway Theater and Commercial District

Date: 6/1/98 □ Continuation ■ Update

Recorded by: Historic Resources Group

building is eligible as a contributor to the district as well as individually eligible, and its new status code is 2B2. Register (3S) in 1983. It is now included within the expanded boundaries of the Broadway Theater and Commercial District. The erroneously listed as Morgan and Walls on the 1983 Primary Record. The building appeared individually eligible for the National The Pan American Building (249-259 S. Broadway) was built in 1894 and designed by Sumner Hunt. The architect is

1998 photograph



PRIMARY RECORD

Primary # HRI#

[rinomial	
VRHP Status Code	1

Other Listings NHL Review Code Reviewer Date Page 1 of 1 Resource Name or #: Broadway Theater and Commercial District P1. Other Identifier: Bradbury Building P2. Location: Not for Publication Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad T; R; 1/4 of 1/4 of Sec; Date c. Address 300-310 S BROADWAY (216-226 W. 3RD STREET) City Los Angeles Zip 90013 d. UTM: Zone; mE/ e. Other Locational Data:

P3a. Description:

P4. Resources Present:

Five-story commercial building, designed by George Wyman, clad in stone and pressed brick. Storefronts open to the sidewalk. A glazed interior atrium includes ornate iron balconies and elevators. The building has been completely restored.

Building ☐ Structure ☐ Object ☐ Site ☐ District ☑ Element of District ☐ Other

PHARIO

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic ☐ Both Prehistoric 1894 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

P11. Report Citation:

Attachments:	■ NONE	□ Location Map	☐ Sketch Map		Continuation	Sheet [Building, Struc	cture, and Object Record
☐ Archaeological	Record	District Recor	rd Linear F	eatu	ure Record	☐ Millin	g Station Record	☐ Rock Art Record
☐ Artifact Record	☐ Photo	ograph Record	Other:				10100 == 111	birce Theorem
DPR 523A (1/95) H	RG							

Trinomial HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code ID

	Commercial District	or #: Broadway Theater and	Resource Name
 Date		Теуіемет	Review Code
			Other Listings
		22 (2000) (2000)	The second secon

Page I of I

a. County Los Angeles P1. Other Identifier: Million Dollar Theater/Metropolitan Water District Building

and (P2b and P2C or P2d. Attach a Location Map as necessary.) P2. Location: 🗆 Not for Publication 🖼 Unrestricted

b. USGS 7.5' Quad Date T; R; 1, of 1, of Sec;

Nm c. Address 301-313 S BROADWAY (306-316 W. 3RD STREET) City Los Angeles Zip 90013

d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

lobby/entrance. much ornamentation. Most of the exterior of the building has been restored, with the exception of the theater's exterior Twelve-story concrete theater and office building by A. C. Martin in Spanish Renaissance design with a stone and brick facade and

Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories/10 Theater

□ Prehistoric Sources: 🖪 Historic □ Both P6. Date Constructed/Age and

1917 (E) National Register form

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

	Perort Citation:	FFG
P10. Survey Type: Section Review		Man I market
Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028		1
P8. Recorded by: Christy J		Ī
имоиуип		
P7. Owner and Address:		=
☐ Prehistoric ☐ Pethistoric I917 (E) National Register f		
P6. Date Constructed/Age a Sources: Mistoric D		
P5b. Description of Photo:	EEE	, , d

7000		
rt Citation:	Kebo	.11.

			Ofher:	выр Весога	togra	оча 🗆	D Artifact Record
□ Воск Ап Весога	☐ Milling Station Record	sture Record					□ Archaeological
ure, and Object Record	Sheet 🗖 Building, Structu	Confinuation 2	Sketch Map	Location Mal		□ NONE	:stnemdosttA

DPR 523A (1/95) HRG

PRIMARY RECORD

Primary # HRI# Trinomial

NRHP Status Code 1D Listings

Other Listings
Review Code

_ Reviewer _____ Date

Page I of I

Resource Name or #: Broadway Theater and Commercial District

P1. Other Identifier: Grand Central Market

P2. Location: Not for Publication 🛮 Unrestricted

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/4 o

T; R; 1/4 of 1/4 of Sec; B.M.

c. Address 315 S BROADWAY City Los Angeles Zip 90013

d. UTM: Zone; mE/ mN

e. Other Locational Data:


P3a. Description:

This market building with offices on the upper floors stretches through the block from Hill Street to Broadway. The Broadway elevation is six stories high and divided into six bays. A plain parapet terminates the facade. The building has been rehabilitated, and the previously altered, lower portion of the facade redesigned.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present:

Building Structure Object Site District Element of District Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic Both Prehistoric

1897 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

P11. Report Citation:

Attachments:	□ NONE	☐ Location Map		Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
Archaeologica		District Record			eatu	ire Record	Milli	ing :	Station Record	☐ Rock Art Record
DPR 523A (1/95) H	The state of the s	ograph record	П	Other.						

Trinomial HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

		# # B B	PIMIA
	ואר.		
uuv	$\mathbf{v} = \mathbf{v}$		

This one-and-one-half story commercial building is a Post-Modern interpretation of Streamline Moderne and Art Deco. The primary facade is symmetrical about the recessed entrance. Curving glass leads to the entrance and over-scaled curving and steppo elements crown the upper part of the facade.
P3a. Description:
e. Other Locational Data:
d. UTM: Zone ; mE/ mM
and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; '/, of '/, of Sec; B.M. c. Address 312 S BROADWAY City Los Angeles Zip 90013
P1. Other Identifier: Rocation: Not for Publication Unrestricted a. County Los Angeles
Page 1 of 1 Resource Name or #: Broadway Theater and Commercial District
Other Listings Reviewer Date
NRHP Status Code 6X3

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

□ Prehistoric Sources: Mistoric D Both P6. Date Constructed/Age and

Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106 P9. Date Recorded:

P9. Date Recorded: P10. Survey Type: Section Review	
Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028	San San
P8. Recorded by: Christy J	Obexuf & lobind ni llo
пикиоми	100 M
P7. Owner and Address:	
☐ Prehistoric ☐ Prehistoric ☐ Parenit	Table COCANED
Sources: Historic DB	
P6. Date Constructed/Age	
P5b. Description of Photo:	P5a. Photo or Drawing

P11. Report Citation: None.

DPR 523A (1/95) HRG					
□ Artifact Record	Photograph Record	l Ofher:			
Archaeological Record	cord 🖪 District Record	☐ Linear Feat	ure Record	☐ Milling Station Reco	Sock Art Record
Attachments: □ NONE	NONE Cocation Map [2 Sketch Map	Continuation S	Sheet 🛮 Building, St	and Object Record

PRIMARY RECORD

Primary # HRI# Trinomial

NRHP Status Code 6Y2

	Other Listings	NKH	Status Code 6 Y 2		
	Review Code	Reviewer		Date	
Page I of I	Resource Name	or #: Broadway Theater	r and Commercial Distric	t	,

P1. Other Identifier:

P2. Location: ☐ Not for Publication ☐ Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M. c. Address 318-322 S BROADWAY City Los Angeles Zip 90013

d. UTM: Zone; mE/ mN

e. Other Locational Data:

P3a. Description:

Three-story and basement reinforced concrete and brick structure. The building was originally a five-story structure, but it has been altered and much of the ornamentation removed. When the building was reduced in size, much of the original ornamentation was removed. The plain brick facade is missing the cornice, one of the major character-defining features which gives the buildings in the district continuity. Since the ornamentation and massing of the building have been altered to such a great extent, the building is no longer a contributor to the Broadway Theater and Commercial District.

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

P4. Resources Present: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic Both Prehistoric

1907 (E) National Register Form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson McAvoy Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded: 6/1/98 P10. Survey Type: Section 106 Review

P11. Report Citation

Attachments:	□ NONE	☐ Location Map	☐ Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
Archaeological		District Reco		eatu	ure Record	Millin	ng :	Station Record	☐ Rock Art Record
☐ Artifact Record DPR 523A (1/95) HI	V. 1000	graph Record	Uther:						

Trinomial HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code 6X3

istrict	dway Theater and Commercial D	Resource Name or #: Broa
PO	eviewer	A eboO weives
		Other Listings

Page I of I

a. County Los Angeles

P2. Location: 🗆 Not for Publication 🖼 Unrestricted P1. Other identifier:

T; R; 1, of 1, of Sec; Date b. USGS 7.5' Quad and (P2b and P2C or P2d. Attach a Location Map as necessary.)

ΝW d. UTM: Sone; mE/ c. Address 324-326 S BROADWAY City Los Angeles Zip 90013

e. Other Locational Data:

P3a. Description:

DPR 523A (1/95) HRG

☐ Archaeological Record

☐ Artifact Record ☐ Photograph Record

One-and-one-half story brick commercial building. A stuccoed facade with a series of arches dates to an alteration in approximately

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

P5b. Description of Photo:

□ Prehistoric □ Both Sources: M Historic P6. Date Constructed/Age and

1912 (E) National Register form

P7. Owner and Address:

nuknown

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Rock Art Record

☐ Milling Station Record

	11. Report Citation:
SHOES SH	797
	Wiwerd so otode sag

:nether:

☐ Linear Feature Record

Attachments:

UONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record

District Record

PRIMARY RECORD

Primary # HRI# Trinomial


NRHP Status Code 6X3 Other Listings Review Code _ Reviewer Date Page 1 of 1 Resource Name or #: Broadway Theater and Commercial District P1. Other Identifier: P2. Location:

Not for Publication

Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M. c. Address 327-329 S BROADWAY City Los Angeles Zip 90013 d. UTM: Zone; mE/ e. Other Locational Data: P3a. Description: Formerly a three-story brick building, this building is now one story high. It has been completely altered to a largely unarticulated, stuccoed facade.

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

P4. Resources Present: Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic ☐ Both ☐ Prehistoric 1900 (E) National Register Form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	■ NONE	□ Location Map	☐ Sketch Map		Continuation	Sheet	Building, Structure,	and Object Record
☐ Archaeologica				eatu	ure Record	□Milling	Station Record	☐ Rock Art Record
☐ Artifact Record	☐ Phote	ograph Record	☐ Other:					- Channell
DPR 523A (1/95) H	RG							

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

KX0 eboO susts 9HRN

a. County Los Angeles

-				
OKD	SEC	ł k	AR	RIM

ercial District	or#: Broadway Theater and Comm	Resource Name
Date	Reviewer	Review Code
		Other Listings
		THE RESERVE OF THE PERSON NAMED IN

P1. Other Identifier:

Page I of I

P2. Location: 🗆 Not for Publication 📓 Unrestricted

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

Date b. USGS 7.5' Quad

c. Address 328-330 S BROADWAY City Los Angeles Zip 90013

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

P3a. Description:

One-and-one-half story commercial building with arched window openings on the facade.

T; R; 1, of 1, of Sec;

P4. Resources Present: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

☐ Linear Feature Record

P2b. Description of Photo:

□ Prehistoric □ Both Sources: Mistoric P6. Date Constructed/Age and

nuknown P7. Owner and Address:

☐ Milling Station Record

P10. Survey Type: Section 106 P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

☐ Rock Art Record

Review

McDonald's Photo or Drawing

Attachments:

| NONE | Location Map | Sketch Map | Continuation Sheet | Building, Structure, and Object Record P11. Report Citation:

☐ Artifact Record ☐ Photograph Record □ Ofher: District Record ☐ Archaeological Record

DPR 523A (1/95) HRG

PRIMARY RECORD

Primary #
HRI#
Trinomial
NRHP Status Code 6X


		NRHP :	Status Code 6X3	
erija. N	Other Listings			
	Review Code	Reviewer	was in washing M	Date
Page 1 of 1	Resource Name or #	: Broadway Theater a	and Commercial Di	strict
P1. Uther Identifie	· ·			
P2. Location:	Not for Publication 📓 Unrestricted	a. Coun	ty Los Angeles	
and (P2b and	P2C or P2d. Attach a Location Map as	s necessary.)		
b. USGS 7.5'	Quad Date T; R; 1/4 of	1/4 of Sec ; B.M.		
c. Address 33	1-335 S BROADWAY City Los A	ngeles Zip 90013		
d. UTM: Zone	; mE/ mN			
e. Other Locat	onal Data:			

P3a. Description:

P4. Resources Present:

Two story commercial building which was originally a four-story brick building by A. M. Edelman. The building has been altered to two stories with alterations made to the first floor. The articulation and window openings of the second floor are also altered and have been refinished in stucco.

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other



P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

1900 (F) Building Permit

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

P1	1	Re	por	1 (Ci	ta	ti	O	n
			po.		٠.		٠.	٠.	

Attachments:	NONE	_ocation Map	☐ Sketch Map	Continuation	Sheet 🗖	Building, Structure,	and Object Record
Archaeological Re	ecord	District Record	d ☐ Linear F	eature Record	☐ Milling	Station Record	☐ Rock Art Record
Artifact Record	☐ Photogra	ph Record	Other:				and the line
DPR 523A (1/95) HRG							

Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

Trinomial

Reviewer	ahon waivas
	Other Listings
NKHP Status Code 0X3	

Resource Name or #: Broadway Theater and Commercial District

Page I of I

a. County Los Angeles

P2. Location: 🗆 Not for Publication 🖼 Unrestricted Pi. Other Identifier:

T; R; 1, of 1, of Sec; B.M. Date b. USGS 7.5' Quad and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 336 S BROADWAY City Los Angeles Zip 90013

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

P3a. Description:

large, glass storefronts and projecting canopies. One-story retail building designed as a part of the adjacent vest-pocket park. The building is constructed of concrete block with

P4. Resources Present:

Building

Structure

Object

Object

Other

District

Element of District

Other P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

□ Prehistoric □ Both Sources: 📓 Historic P6. Date Constructed/Age and

Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106 P9. Date Recorded:

Review			
P10. Survey Type: Section		a grown - a construction	
P9. Date Recorded:	appropriate the second	at orbitation and account	A disease
Hollywood, CA 90028	9	A CONTRACTOR OF THE PARTY OF TH	
1728 Whitley Ave.	Bloom St.		
P8. Recorded by: Christy J. Historic Resources Group			
1 repired by: Christer I			
nuknown			
P7. Owner and Address:		上,并在14条件	المرائز
		<u> مواديد</u>	
□ Prehistoric		Treated Process	
Sources: Historic D	THE PARTY OF THE P	SUBSECTION OF THE PARTY OF THE	and the same of th
P6. Date Constructed/Age a			De la
		and the second	
	-1. m		
P5b. Description of Photo:			P5a. Photo or Drawing

1 (391f) AESS A9G	SG						
Necora Recora	D Photo	odusph Record	Other:				
☐ Archaeologica	Record	District Reco	d □ Linear F	sture Record	tS gnilliM □	tation Record	Rock Art Record
Attachments:	□ NONE	☐ Location Map	🛘 әкерси мар	□ Continuation	Sheet [E	Building, Structure,	and Object Record

PRIMARY RECORD

Primary # HRI# Trinomial

I IZHANZIZI	KLOOKD	NRHP :	Status Code 6X3	
	Other Listings			
	Review Code	Reviewer	all two to	Date
Page 1 of 1	Resource Name	or #: Broadway Theater a	and Commercial Di	strict
P1. Other Identif	ier:			
P2. Location: D	」Not for Publication 🛭 Unrestric	cted a. Coun	ty Los Angeles	
and (P2b an	d P2C or P2d. Attach a Location M	ap as necessary.)	of the sale of the	
b. USGS 7.5	G' Quad Date T; R; 1/4	of 1/4 of Sec; B.M.		
c. Address :	337-339 S BROADWAY City L	os Angeles Zip 90013		
d. UTM: Zor	ne; mE/ mN			
e. Other Loc	ational Data:			
55 5				

P3a. Description:

Originally a four-story brick structure, the building has been altered to two stories and the facade stuccoed over. The original ornamentation has been removed.

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other P4. Resources Present: P5b. Description of Photo: P6. Date Constructed/Age and ☐ Both Sources: Historic ☐ Prehistoric 1900 (E) National Register form P7. Owner and Address: unknown P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028 P9. Date Recorded: P10. Survey Type: Section 106 Review P11. Report Citation:

Attachments:	□ NONE	☐ Location Map		Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
☐ Archaeologica	Record	District Reco	rd	☐ Linear F	eatu	ire Record	☐ Milli	ng :	Station Record	Rock Art Record
☐ Artifact Record	☐ Phote	ograph Record		Other:						ATTENSION TO
DPR 523A (1/95) H	IRG									

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

MRHP Status Code ID

Resource Name or #: Broadway Theater and Commercial District Review Code Reviewer Date

Page I of I

a. County Los Angeles

P2. Location: 🗆 Not for Publication 🖪 Unrestricted P1. Other Identifier: Trustee Building

T; R; 1, of 1, of Sec; and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 340-344 S BROADWAY City Los Angeles Zip 90013 b. USGS 7.5' Quad Date

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

P3a. Description:

first floor has been altered and part of the cornice amy have been removed. Four-story brick and concrete retail and office building by Parkinson & Bergstrom. The facade has very wide window bays, and the

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P6. Date Constructed/Age and

P2b. Description of Photo:

□ Prehistoric Sources: 🖪 Historic □ Both

1905 (E) National Register Form

uwonan P7. Owner and Address:

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

	· •		
	E GALXIETA		
THE AL		- : 1	

						SB	H (36\r) ASSB A90
				☐ Ofper:	sph Record	Бороча 🗆	☐ Artifact Record
☐ Rock Art Record	ng Station Record	Secord [Milli	lear Feature f	ord 🔲 Lin	District Reco	Record	☐ Archaeological
ire, and Object Record	☐ Building, Structu	ntinuation Sheet	Wap Co	2 Refch	Location Map	O NONE	Attachments:

Primary # HRI# Trinomial

PRIMARY R	ECORD	MDU		
	Other Listings	NKI	P Status Code 6Y3	
	Review Code	Reviewer		_ Date
Page I of I	Resource Name or #:	Broadway Theate	er and Commercial Distric	: t
P1. Other Identifier:				
P2 Location: TNO	t for Publication I Unrestricted	a Cou	unter I on Angeles	

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec;

c. Address 341-345 S BROADWAY City Los Angeles Zip 90013

d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

This two-story commercial building was originally four stories high. The building has been altered to two stories, the mezzanine has been obscured, and all of the fenestration of the broad second floor window bays has been replaced by windows with thin, metal frames. A small amount of the original terra cotta decoration remains over the second floor windows in the north and south bays. Due to these alterations, the building is no longer a contributor to the Broadway Theater and Commercial District.

Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other P4. Resources Present:

P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic □ Both ☐ Prehistoric 1903 (E) National Register Form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

P11	F	Repo	ort (Cif	tati	on
		·cp	,,,	·		011

Attachments:	■ NONE	□ Location Map		Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
☐ Archaeological	Record	District Reco	rd	☐ Linear F	eatu	ire Record	☐ Mill	ing S	Station Record	☐ Rock Art Record
☐ Artifact Record	Photo	ograph Record		Other:						LAZ 53 99 1
DPR 523A (1/95) H	IRG									

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code 6X3

a. County Los Angeles

Date	ТемеіуеЯ	Review Code
		Other Listings

Resource Name or #: Broadway Theater and Commercial District

P1. Other Identifier:

Page I of I

P2. Location: 🗆 Not for Publication 🖼 Unrestricted

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date

c. Address 346 S BROADWAY City Los Angeles Zip 90013

d. UTM: Zone; niE/ Nm

e. Other Locational Data:

P3a. Description:

One-story brick building with a flat roof, consisting of two storefronts. The facade is completely obscured by signage.

T; R; 1, of 1, of Sec;

P5b. Description of Photo: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

□ Prehistoric Sources: 🖪 Historic □ Both P6. Date Constructed/Age and

1907 (E) National Register Form

пиклоwп P7. Owner and Address:

Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106 P9. Date Recorded:

				d Citation.	oded tto
			3		
COSWETICE COSWETICE	MENTED AND THE PROPERTY OF THE	SING I	FINO	Ropa par	v.mea =
IN (S)				or Drawing	

				1 Ofper:	Record E	tograp	оча 🗆	DAdifact Record
☐ Rock Art Record	g Station Record							☐ Archaeological
and Object Record	Building, Structure,	n Sheet 🛚	□ Continuatio	2 Sketch Map	cation Map [□ NONE	Attachments:

DPR 523A (1/95) HRG

PRIMARY RECORD

Primary # HRI# Trinomial

NIDHD	Status	Code	6V2

NRHP Status Code 6X3 Other Listings Review Code Reviewer Date Page I of I Resource Name or #: Broadway Theater and Commercial District P1. Other Identifier: P2. Location: Not for Publication Munrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M. c. Address 347-349 S BROADWAY City Los Angeles Zip 90013 d. UTM: Zone; mE/ mN e. Other Locational Data:

P3a. Description:

Two-story brick structure with a completely altered facade. The facade is a flat, stuccoed surface.

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other P4. Resources Present:



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic ☐ Both ☐ Prehistoric 1908 (E) National Register Form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	□ NONE	☐ Location Map	☐ Sketch Map	Continuation	Sheet	Building, Structure,	and Object Record
☐ Archaeological ☐ Artifact Record	Record	District Recor	rd Linear F				☐ Rock Art Record
DPR 523A (1/95) H	RG						

Isimoni1T #IAH Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

and Commercial District.

Altered three-story brick and iron structure of Italianate design by R. B. Young with fluted columns and arched windows. The parapet with balustrade has been temoved, and the entire facade has been covered with a metal siding which resembles wood shingles. Due to this alteration, which obscures the entire facade, the building is no longer a contributor to the Broadway Theater
P3a. Description:
e. Other Locational Data:
P1. Other identifier: P2. Location: Not for Publication Unrestricted
Page 1 of 1 Resource Name or #: Broadway Theater and Commercial District
Review Code Reviewer Date
Other Listings
NRHP Status Code 6Y2

P4. Resources Present:

Building
Structure
Object
Object
Object
Other P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

1895 (E) National Register Form □ Prehistoric Both Sources: Mistoric P6. Date Constructed/Age and

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

Year of the second seco			
P10. Survey Type: Section Review		- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
P9. Date Recorded:			
P8. Recorded by: Christy Jo Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028		HOLLEYGES SEVENCE SEVENCES WILLIAM SHELLIME OCCUPANT SELECTION OCCUPANT SELECTION	C.
пикиоми			112
P7. Owner and Address:	ARIAN MARINE		
1895 (E) National Register F	COLUMN TO THE PARTY OF THE PART		
P6. Date Constructed/Age a Sources: Historic			
P5b. Description of Photo:			PES Photo or Drawing

H (36\f) AESS A90	58							
☐ Artifact Record	D Phot	odusph Record		Other:				
☐ Archaeological	Record	☐ District Rec	rd	☐ Linear Fea	are Record	gnilliM 🗖	Station Record	☐ Rock Art Record
Attachments:	MONE NONE	☐ Location Mar	S	ketch Map [Continuation 3	Sheet 🗖	Building, Struc	and Object Record

PRIMARY RECORD

Primary # HRI# Trinomial

NRHP Status Code 6X3 Other Listings Review Code _____ Reviewer ___ Resource Name or #: Broadway Theater and Commercial District Page 1 of 1 P1. Other Identifier: P2. Location:

Not for Publication
Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M. c. Address 351-353 S BROADWAY City Los Angeles Zip 90015 d. UTM: Zone; mE/ e. Other Locational Data: P3a. Description: Six-story brick structure. The entire facade has been remodeled as a flat, stuccoed surface above a projecting canopy. There are no openings in the upper portion of the facade. P3b. Resources Attributes: 07 Commercial Building, over 3 stories ■ Building ☐ Structure ☐ Object ☐ Site ☐ District ■ Element of District ☐ Other P4. Resources Present: P5b. Description of Photo: P6. Date Constructed/Age and Sources: Historic ☐ Both ☐ Prehistoric 1912 (E) Building Permit P7. Owner and Address: unknown

P11. Report Citation:

Attachments:	□ NONE	☐ Location Map	Sketch	Мар 🗖	Continuation	n Sheet 🗖	Building, Struct	ure, and Object Record
☐ Archaeologica	l Record	District Recor	rd Lir	ear Fea	ture Record	Milling	Station Record	Rock Art Record
☐ Artifact Record	☐ Phote	ograph Record	□ Other					ra Amusel Rock
DPR 523A (1/95) H	IRG							

P8. Recorded by: Christy Johnson

P10. Survey Type: Section 106

Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028 P9. Date Recorded:

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

NRHP Status Code 6X3

RECORD	YAAMIA9
PLOODD	VICIABILICA

nd Commercial District	or #: Broadway Theater a	Resource Name
Date	Reviewer	eboO weive
		Other Listings

Page I of I

a. County Los Angeles

P2. Location: 🗆 Not for Publication 📓 Unrestricted P1. Other Identifier:

c. Address 355-359 S BROADWAY City Los Angeles Zip 90013 b. USGS 7.5' Quad Date T; R; 1, of 1, of Sec; B.M. and (P2b and P2C or P2d. Attach a Location Map as necessary.)

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

P3a. Description:

DPR 523A (1/95) HRG

☐ Archaeological Record

single panes surrounded by a slight relief in the flat facade. cornice elements which are located along the top of the parapet only above the window openings. Fenestration consists of fixed, and the corner of the building at Fourth Street and Broadway is curved in plan. The building has a flat roof and a series of thin This two-story commercial building was originally seven stories high, but has been thoroughly altered. It is located on a corner lot,

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

□ Both Sources: Mistoric P6. Date Constructed/Age and

1897 (E) National Register Form □ Prehistoric

P7. Owner and Address:

Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106 P9. Date Recorded:

☐ Rock Art Record

☐ Milling Station Record

M. A.T. D.	P11. Report Citation:
P10. Survey Type: Section Review	
P9. Date Recorded:	
P8. Recorded by: Christy J Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028	
P7. Owner and Address: unknown	
P6. Date Constructed/Age : Sources: Historic	
P5b. Description of Photo:	

District Record

Ofher:

☐ Linear Feature Record

Attachments:

NONE Location Map
Sketch Map
Continuation Sheet
Building, Structure, and Object Record

Primary # HRI# **Trinomial** NRHP Status Code 6Y2

D	R	M	AB	RY	/ R	F	20	RD	
B	B W.	8 B S	0 ti a-	# H W I		2 4			

Other Listings

Review Code Reviewer

Page 1 of 1

Resource Name or #: Broadway Theater and Commercial District

P1. Other Identifier:

P2. Location:

Not for Publication

Unrestricted

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad T; R; 1/4 of 1/4 of Sec; Date

B.M.

c. Address 356-364 S BROADWAY City Los Angeles Zip 90013

d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

This three-story commercial building has been heavily altered. Originally a seven-story brick structure designed by John Parkinson, the building was of Romanesque design with a glazed, pressed brick facade. The upper stories were removed, and the facade has been covered by metal siding, some of which resembles wood shingles. Due to this major alteration, which obscures the entire facade, the building is no longer a contributor to the Broadway Theater and Commercial District.

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

P4. Resources Present: Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: m Historic ☐ Both □ Prehistoric

1902 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	■ NONE	☐ Location Map		Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
☐ Archaeologica	l Record	District Reco	rd	☐ Linear F	eatu	ire Record	☐ Mill	ing :	Station Record	☐ Rock Art Record
Artifact Record	d ☐ Phot	ograph Record		Other:						Takilihan _
DPR 523A (1/95) H	IRG									

HBI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

Trinomial

a. County Los Angeles

Reviewer Other Listings NRHP Status Code 6ZI

T; R; '/, of '/, of Sec;

Review Code

Resource Name or #: Broadway Theater and Commercial District

P1. Other Identifier:

Page I of I

P2. Location: 🗆 Not for Publication 🖼 Unrestricted

Nm

b. USGS 7.5' Quad Date and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 400-422 S BROADWAY City Los Angeles Zip 90013

e. Other Locational Data: d. UTM: Zone; mE/

P3a. Description:

sidewalk. The corner of the plan at Fourth Street and Broadway is cut off at an angle. This recently-constructed, one-story commercial building has a flat roof and consists mainly of storefronts which open on to the

P4. Resources Present: Building D Structure Dobject District District Element of District Dother P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

☐ Linear Feature Record

□ Both Sources: Mistoric P6. Date Constructed/Age and

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Keview P10. Survey Type: Section 106

☐ Milling Station Record

☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record

☐ Rock Art Record

P10. Survey Type: Section Review		- 1		A STATE OF THE STA	
P9. Date Recorded:	ig.		X 2 1 1	1	4
P8. Recorded by: Christy J Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028			ر تر_ ترکد		
пикломп					en de la deservación de la companya
P7. Owner and Address:	di d		-1 / 11/1		
P6. Date Constructed/Age Sources: ■ Historic □ E					
				111 111	111
P2b. Description of Photo:					and no abaded a

P11. Report Citation:

☐ Artifact Record ☐ Photograph Record □ Ofher: District Record ☐ Archaeological Record

DPR 523A (1/95) HRG

Attachments: D NONE

Primary # HRI# Trinomial NRHP Status Code 1D

P	R	STATISTICS.	V	A	R	Y	R	E	C	0	R	D	
				4									

Other Listings Review Code Reviewer

Page 1 of 1

Resource Name or #: Broadway Theater and Commercial District

Pr. Other identifier: Broadway Department Store/State Office Building

P2. Location: Not for Publication I Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M.

c. Address 401-423 S BROADWAY City Los Angeles Zip 90013

d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

Ten-story concrete structure by Parkinson & Bergstrom with a brick and glazed terra cotta facade including many ornamental details. Originally a department store, the building is currently in the process of rehabilitation for use as State offices.

P3b. Resources Attributes: 14 Government Building

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present:



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: M Historic □ Both ☐ Prehistoric

1913 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	☐ NONE	☐ Location Map	Sketch Map		Continuation	Sheet [Building, Structure,	and Object Record
		District Recor		eatu	re Record	☐ Millin	g Station Record	☐ Rock Art Record
Artifact Record	☐ Photo	ograph Record	Other:					
DPR 523A (1/95) H	RG							

HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

IsimoninT

a. County Los Angeles

			dway Central Block
	d Commercial District	r #: Broadway Theater an	Resource Name c
Date		Reviewer	Review Code
			Other Listings
	atus Code ID	IS 9HRN	6110

Page I of I

T; R; 1, of 1, of Sec; B.M.

P2. Location: 🗆 Not for Publication 🖼 Unrestricted P1. Other Identifier: Broad

Date and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 424 S BROADWAY City Los Angeles Zip 90013 b. USGS 7.5' Quad

NW d. UTM: Sone; mE/

e. Other Locational Data:

P3a. Description:

the first floor in 1924, and the lobby was remodeled in 1929. The storefronts and mezzanine have been completely altered. Ten-story reinforced concrete and brick structure by C. R. Aldrich with a granite and terra cotta facade. A theater was installed on

P5b. Description of Photo: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

□ Prehistoric □ Both Sources: 🔞 Historic P6. Date Constructed/Age and

1906 (E) National Register form

nuknown P7. Owner and Address:

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Milling Station Record

☐ Rock Art Record

Tacitoti Danga bbc
NORG
Pas: Pigio or Drawing

P11. Report Citation:

□ Ofher: ☐ Artifact Record ☐ Photograph Record Linear Feature Record District Record Archaeological Record Attachments: 🗖 NONE 🗖 Location Map 🗖 Sketch Map 🗖 Continuation Sheet 🗖 Building, Structure, and Object Record

DPR 523A (1/95) HRG

PRIMARY RECORD

Primary # HRI# Trinomial NRHP Status Code 6Z1

O : 1	-	
-		
Oth	or Lietir	300
	-	Other Listin

Review Code

Page 1 of 1

Resource Name or #: Broadway Theater and Commercial District

Reviewer

P1. Other Identifier:

P2. Location: Not for Publication Unrestricted

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date

T; R; 1/4 of 1/4 of Sec; B.M.

c. Address 425-429 S BROADWAY City Los Angeles Zip 90013

d. UTM: Zone; mE/ mN

e. Other Locational Data:

P3a. Description:

Three-story commercial building, completely altered with a flat, stuccoed facade with no openings above the first floor.

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

P4. Resources Present:

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other

P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic ☐ Both ☐ Prehistoric

1905 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

50.5	
li l	
· · · · · · · · · · · · · · · · · · ·	
J.M. FAVILAS	
WHOLESALE WHOLESALE SPACE FOR RENT SOLVE	
ONE PUBLIC.	
	(B) (B)

Attachments:	□ NONE	☐ Location Map	Sketch Map		Continuation	Sheet		Building, Structure	e, and Object Record
	d ☐ Phot	District Reco ograph Record	_	eatu	ure Record	[] Mill	ing S	Station Record	☐ Rock Art Record

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

РЯІМАКУ RECORD

MRHP Status Code 1D

Dati	Reviewer	eboD weive.
,-u		ther Listings

.M.8

Resource Name or #: Broadway Theater and Commercial District

Page I of I

a. County Los Angeles

T; R; 1, of 1, of Sec; and (P2b and P2C or P2d. Attach a Location Map as necessary.) P2. Location: 🗆 Not for Publication 🖻 Unrestricted

b. USGS 7.5' Quad Date

P1. Other Identifier: Bumiller Building/Campbell W. Blake Building

Nm c. Address 430 S BROADWAY City Los Angeles Zip 90013

e. Other Locational Data: d. UTM: Zone; mE/

P3a. Description:

DPR 523A (1/95) HRG

☐ Archaeological Record

Artifact Record D Photograph Record

completely altered, and perforated metal screens have been added to shade the window openings on the lower part of the facade. Six-story reinforced concrete structure with a terra cotta comice, designed by Morgan & Walls. The base of the building has been

P5b. Description of Photo: Building 🗖 Structure 🗖 Object 🗖 Site 🗖 District 🔞 Element of District 🗖 Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

□ Both Sources: Mistoric P6. Date Constructed/Age and

1906 (E) National Register form □ Prehistoric

P7. Owner and Address:

nuknown

Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Keview P10. Survey Type: Section 106 P9. Date Recorded:

☐ Rock Art Record

☐ Milling Station Record

	:noitation:	Repor	.hlq
	A 리.		
P-CAR-ZUK-Y		3	
	<u> </u>		
A STATE OF THE PARTY OF THE PAR		_	
		-	
		•	
			1
dis and	द्रका, \ ः क्रु		
Charles paris 10, 20 mm			4 colte
Charles fair and a			4 PC J

District Record

:Tether:

☐ Linear Feature Record

Attachments:

UONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

■ District Record

PRIMARY RECORD

Primary #
HRI#
Trinomial
NRHP Status Code 1D

	Other Listings			
	Review Code	Review	/er	Date
Page 1 of 1	Resource N	Name or #: Broadway	Theater and Commercia	al District
P1. Other Identifier: Wilso P2. Location: Not for land (P2b and P2C or b. USGS 7.5' Quad c. Address 431-435 S d. UTM: Zone; mE e. Other Locational Da	Publication Bunne P2d. Attach a Locati Date T; R; BROADWAY C	on Map as necessary.) 1/4 of 1/4 of Sec;	a. County Los Angeles B.M. 90013	

P3a. Description:

P11. Report Citation:

DPR 523A (1/95) HRG

Archaeological Record

☐ Artifact Record ☐ Photograph Record

Three-story brick and concrete structure with a facade three bays wide. Facade ornamentation includes a cornice with brackets, columns topped by capitals, and a band of floral designs on the surface over the third floor windows. The first floor has been altered.

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P5b. Description of Photo: P6. Date Constructed/Age and Sources: Historic □ Both ☐ Prehistoric 1909 (E) National Register form P7. Owner and Address: unknown P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028 アルスをいる P9. Date Recorded: P10. Survey Type: Section 106 Review

Attachments:

NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record

☐ Milling Station Record

Rock Art Record

☐ Linear Feature Record

Other:

NRHP Status Code 6X3 Trinomial HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

Resource Mame or #: Broadway Theater and Commercial District						
Date		Reviewer	Review Code			
			Other Listings			

Page I of I

a. County Los Angeles

P2. Location: 🗆 Not for Publication 📓 Unrestricted P1. Other Identifier:

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date

c. Address 437 S BROADWAY City Los Angeles Zip 90013

e. Other Locational Data: Mm \3m; Sone; mTU.b

P3a. Description:

Altered three-story commercial building. The flat, stuccoed facade has no openings above the first floor.

1; R; 1, of 1, of Sec;

P5b. Description of Photo: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

☐ Linear Feature Record

Attachments:

NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record

□ Both Sources: Mistoric P6. Date Constructed/Age and

1942 (E) National Register form □ Prehistoric

nuknown P7. Owner and Address:

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Rock Art Record

☐ Milling Station Record

	P11 Report Citation:
ř.	
The state of the s	the second second

☐ Artifact Record ☐ Photograph Record District Record ☐ Archaeological Record

□ Ofher:

DPR 523A (1/95) HRG

Primary # HRI# Trinomial NRHP Status Code 6X3

PRIMARY RECORD

Other Listings Review Code Reviewer

Page 1 of 1

Resource Name or #: Broadway Theater and Commercial District

P1. Other Identifier:

P2. Location: Not for Publication I Unrestricted a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M.

c. Address 443-445 S BROADWAY City Los Angeles Zip 90013


d. UTM: Zone; mE/ mN

e. Other Locational Data:

P3a. Description:

Four-story concrete commercial building with a heavily altered, plain stuccoed facade.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories P4. Resources Present: ■ Building ☐ Structure ☐ Object ☐ Site ☐ District ■ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: M Historic ☐ Both ☐ Prehistoric

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	■ NONE	□ Location Map		Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
Archaeologica	Record	District Reco	rd	☐ Linear F	eatu	ire Record	☐ Mill	ing :	Station Record	Rock Art Record
☐ Artifact Record	I ☐ Phot	ograph Record		Other:						
DPR 523A (1/95) H	IRG									

HKI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

Trinomial

a. County Los Angeles

IZ3 aboO sufatS 9HRN

Other Listings

Review Code Reviewer

T; R; 1/, of 1/, of Sec;

Resource Name or #: Broadway Theater and Commercial District

Page I of I

P2. Location: 🗆 Not for Publication 🖪 Unrestricted P1. Other Identifier:

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date

d. UTM: Zone; mE/ c. Address 440 S BROADWAY City Los Angeles Zip 90013

e. Other Locational Data:

P3a. Description:

A three-story concrete parking structure, clad in brick, with four storefronts opening to the sidewalk.

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other 39 Other P3b. Resources Attributes: 39 Other/Parking Garage

☐ Linear Feature Record

Attachments: 🗖 NONE 🗖 Location Map 🗖 Sketch Map 🗖 Continuation Sheet 🗖 Building, Structure, and Object Record

☐ Prehistoric □ Both Sources: 🖀 Historic P6. Date Constructed/Age and

Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106 P9. Date Recorded:

☐ Rock Art Record

☐ Milling Station Record

					1000 PVC
P10. Survey Type: Section Review		; . !			ų.* ≥_ #
P9. Date Recorded:	olean in inggy	en de de la companya			
P8. Recorded by: Christy John Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028		VOTVNIS	克鲁 法门门		
P7. Owner and Address: unknown					
P6. Date Constructed/Age a Sources: Material Historic Defends Prehistoric Preh					
P2b. Description of Photo:			1.0	naimed to	-,-4a -3d

P11. Report Citation:

☐ Artifact Record ☐ Photograph Record District Record ☐ Archaeological Record

□ Ofher:

DPR 523A (1/95) HRG

PRIMARY RECORD

Primary # HRI# Trinomial

Trinomial
NRHP Status Code 6X3

	TEO OI TE	NRHP	NRHP Status Code 6X3				
	Other Listings						
	Review Code	Reviewer		Date			
Page I of I	Resource Name	or #: Broadway Theater	and Commercial D	istrict			
P1. Other Identifie							
P2. Location:	Not for Publication 📓 Unrestrict	ted a. Coun	ty Los Angeles				
and (P2b and	P2C or P2d. Attach a Location Ma	p as necessary.)					
b. USGS 7.5'	Quad Date T; R; 1/4 o	of 1/4 of Sec; B.M.					

City Los Angeles Zip 90013

c. Address 450 S BROADWAY d. UTM: Zone ; mE/ mN

e. Other Locational Data:

P3a. Description:

One-and-one-half-story brick structure by R. B. Young. No fabric from the original facade is visible.

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

P4. Resources Present: ☐ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic Both Prehistoric

1900 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	■ NONE	☐ Location Map	Sketch Map	□ Continuatio	n Sheet 🗖	Building, Structure	e, and Object Record
☐ Archaeologica ☐ Artifact Record DPR 523A (1/95) F	d ☐ Phot			eature Record	Milling	Station Record	☐ Rock Art Record

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

a. County Los Angeles

riet	and Commercial Dist	or#: Broadway Theater	Resource Name
 Date		Reviewer	Review Code
			Other Listings
	OI aboo sufated	ИВНЬ 3	avio

Page I of I

P1. Other Identifier:

and (P2b and P2C or P2d. Attach a Location Map as necessary.) P2. Location: 🗆 Not for Publication 🖼 Unrestricted

Date b. USGS 7.5' Quad

c. Address 451-457 S BROADWAY City Los Angeles Zip 90013

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

P3a. Description:

ornamental features include a heavy cornice. Major alterations made to the street-level frontage on both sides appear to date to the Nine-story concrete-frame commercial building designed by Parkinson and Bergstrom. The building is clad in terra cotta and its

T; R; 1, of 1, of Sec;

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P3b. Resources Attributes: 07 Commercial Building, over 3 stories

□ Prehistoric Sources: Mistoric □ Both P6. Date Constructed/Age and

P2b. Description of Photo:

P7. Owner and Address: 1913 (E) National Register form

nuknown

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

	Report Citation:	. llc
The state of the s	esonices Present	N .44

U (3016) ACCT GGG	50						
D Artifact Record	photo	ograph Record	l Other:				
☐ Archaeological	Record	District Record	☐ Linear Featu	re Record	☐ Milling Statio	ation Record	□ Воск Ай Весога
Attachments:		☐ Location Map ☐			sheet 🗖 Build	uilding, Structure,	and Object Record
					2010/00 0 0 20 202		

DPR 523A (1/95) HRG

PRIMARY RECORD

HRI# Trinomial

	7. 7. 5500 5.4. 900	NRHP	NRHP Status Code 1D					
	Other Listings							
ieulu Poeto	Review Code	Reviewer	Date					
Page 1 of 1	Resource Name of	or #: Broadway Theater a	and Commercial District					
	Chester Williams Building ot for Publication 🖼 Unrestrict	ed a. Coun	ty Los Angeles					
b. USGS 7.5' Q	460 S BROADWAY City Lo	o as necessary.) f ¹/₄ of Sec ; B.M.						
e. Other Location	nal Data:							
P3a. Description:								
Twelve-story reinforce facade designed to localtered and the mezzan	k like cut stone. Prominent strin	ure by Curlett & Beelman g courses divide the facado	with a rounded corner, and a glazed terra c e into four zones. The first floor has been sl	otta lightly				
P3b. Resources Attri P4. Resources Prese	butes: 07 Commercial Building tr: Building Structure		rict 🖪 Element of District 🗖 Other					
P	I 69	*****	P5b. Description of Photo:					
			☐ Prehistoric	Both				
		על שע עע	/ 1926 (E) National Register f	iorm				
			P7. Owner and Address: unknown					
			P8. Recorded by: Christy Jo Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028	ohnson				

P11. Report Citation:

Attachments:	□ NONE	☐ Location Map		Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
☐ Archaeologica	Record	District Reco	rd	☐ Linear F	eatu	re Record	☐ Mill	ing	Station Record	☐ Rock Art Record
☐ Artifact Record	Phot	ograph Record		Other:						- m= m
DPR 523A (1/95) H	IRG									

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Primary #

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Trinomial

Other Listings

Review Code

Resource Name or #: Broadway Theater and Commercial District

Reviewer

l lo [agsq

a. County Los Angeles

NRHP Status Code ID

P2. Location:

| Not for Publication | Dintestricted | Dintes

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M. c. Address 500-508 S BROADWAY (220 W. 5TH ST.) City Los Angeles Zip 90013

Mm \3m; Sone ; mE\ mV

P1. Other Identifier: Jewelry Trades Building

e. Other Locational Data:

P3a. Description:

DPR 523A (1/95) HRG

□ Archaeological Record

☐ Artifact Record ☐ Photograph Record

Eight-story concrete structure of Romanesque design by Morgan and Walls with terra cotta facade and ornamentation including segmental arched windows on the seventh story and a heavy cornice over the attic story. The first floor has been altered, and the mezzanine level has been obscured. The glass block sidewalk in front of the builliding is a character-defining feature of the property.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present:

Building
Structure
Object
Object
Object
Other

P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ■ Historic □ Both □ Prehistoric

1912 (E) National Register form


P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028 P9. Date Recorded:

P10. Survey Type: Section 106
Review

☐ Rock Art Record

☐ Milling Station Record



District Record

Other:

☐ Linear Feature Record

Attachments: \square NONE \square Location Map \square Sketch Map \square Continuation Sheet \square Building, Structure, and Object Record

PRIMARY RECORD

Primary #
HRI#
Trinomial
NRHP Status Code 1D

Other Listings Review Code Reviewer Page 1 of 1 Resource Name or #: Broadway Theater and Commercial District P1. Other !dentifier: P2. Location:

Not for Publication


Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M. c. Address 501-515 S BROADWAY City Los Angeles Zip 90013 d. UTM: Zone; mE/ e. Other Locational Data:

P3a. Description:

Eleven-story concrete structure with terra cotta and brick facade by A. E. Curlett. A minor amount of ornamentation has been removed, and the base has been badly remodeled.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric 1927 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	□ NONE	☐ Location Map	☐ Sketch Map		Continuation	Sheet	D B	Building, Structure,	and Object Record
☐ Archaeologica				=eatı	ure Record	☐ Milli	ing St	ation Record	☐ Rock Art Record
Artifact Record	Phot	ograph Record	☐ Other:						
DPR 523A (1/95) H	RG								

HRI# # Yrismin9

Resource Name or #: Broadway Theater and Commercial District

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

Trinomial

a. County Los Angeles

ARHP Status Code ID

Other Listings

Review Code Reviewer

T; R; 1, of 1, of Sec;

Page I of I

P1. Other Identifier:

P2. Location: 🗆 Not for Publication 🖼 Unrestricted

b. USGS 7.5' Quad and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 510 S BROADWAY City Los Angeles Zip 90013 Date

l∃m ; əno∑ :MTU .b Nm

e. Other Locational Data:

P3a. Description:

has been removed, and the first floor has been completely altered. Five-story brick building with pressed-brick facade by R. B. Young and upper windows that form almost solid bands. The cornice

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P5b. Description of Photo:

Date

□ Prehistoric □ Both Sources: Mistoric P6. Date Constructed/Age and

1905 (E) National Register form

nuknown P7. Owner and Address:

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Rock Art Record

☐ Milling Station Record

Building, Structure, and Object Record	Continuation Sheet	☐ Sketch Map	☐ Location Map	□ NONE	:stnemdosttA
					11. Report Cita

Office:	ph Record	Photograp	Atifact Record Additact Record Additact Record Additional Record
☐ Linear Feature Record	District Record	sord 🖾	D Archaeological Rec

DPR 523A (1/95) HRG

PRIMARY RECORD

Primary # HRI# Trinomial

NRHP Status Code 1D

Other Listings

Review Code Reviewer_

Page 1 of 1

Resource Name or #: Broadway Theater and Commercial District

P1. Other Identifier: Roxie Theater

P2. Location:

Not for Publication

Unrestricted

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec;

c. Address 516-522 S BROADWAY City Los Angeles Zip 90013

d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:


Two-story concrete and brick theater with shops on facade flanks, designed in Art Deco style by J. M. Cooper with floral patterns and grillwork on facade. There are currently five storefronts, two of which are located within the original entrance. The first floor storefronts have been completely altered, and the marquee appears to date to the 1960s or 1970s. The terrazzo sidewalk in front of the building is a character-defining feature of the property.

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories/10 Theater

P4. Resources Present:

Building ☐ Structure ☐ Object ☐ Site ☐ District ■ Element of District ☐ Other

P5b. Description of Photo:



P6. Date Constructed/Age and Sources: Historic ☐ Both ☐ Prehistoric 1931 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106

Review

P11	l. F	Re≀	oor	t Ci	tati	on

Attachments:	□ NONE	Loc	ation Map		Sketch Map		Continuation	Sheet		Building, Structure	, and Object Record	
☐ Archaeologica	I Record	Di:	strict Reco	rd	☐ Linear F	eatu	ire Record	☐ Millie	ng S	Station Record	☐ Rock Art Record	
☐ Artifact Record	d ☐ Photo	ograph	Record		Other:							
DPR 523A (1/95) H	IRG											

Primary # HRI# IsimoninT

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

OI Status Code ID

Other Listings

Review Code Reviewer Resource Name or #: Broadway Theater and Commercial District

Page I of I

a. County Los Angeles

P1. Other Identifier: Divot for Publication Bi Unrestricted

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/, of 1/, of Sec; B.M. c. Address 517-519 S BROADWAY City Los Angeles Zip 90013

d. UTM: Zone; mE/ mM

e. Other Locational Data:

P3a. Description:

DPR 523A (1/95) HRG

☐ Archaeological Record

☐ Artifact Record ☐ Photograph Record

Six-story brick structure with decorative facade including arched windows and twisted colonnettes between window openings. The first floor has been altered.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present:

Building
Ctructure
Object
Object
Object
Other

P5b. Description of Photo:

P6. Date Constructed\Age and Sources: ■ Historic □ Both □ Prehistoric

1902 (E) National Register form

P7. Owner and Address: unknown


P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded: P10. Survey Type: Section 106

☐ Rock Art Record

Review

☐ Milling Station Record



□ Offher:

☐ Linear Feature Record

Attachments:

NONE | Location Map | Sketch Map | Continuation Sheet | Building, Structure, and Object Record

District Record

PRIMARY RECORD

Primary # HRI# Trinomial

NRHP	Status Code	ID

Other Listings
Review Code ______ Reviewer ______ Date

Page 1 of 1 Resource Name or #: Broadway Theater and Commercial District

P1. Other Identifier: Clunes Broadway Theater/Cameo Theater

P2. Location: □ Not for Publication ☑ Unrestricted a. County Los Angeles
and (P2b and P2C or P2d. Attach a Location Map as necessary.)
b. USGS 7.5' Quad Date T; R; ¼ of ¼ of Sec; B.M.
c. Address 528 S BROADWAY City Los Angeles Zip 90013
d. UTM: Zone; mE/ mN
e. Other Locational Data:

P3a. Description:

Two-story brick and concrete theater building by A. F. Rosenheim, with a facade featuring a large rounded pediment above the entrance. Storefronts now fill the original entrance, and nothing is left of the first floor. The second story openings have been filled in and the facade re-stuccoed.

P3b. Resources Attributes: 10 Theater; 07 Commercial Building, over 3 stories
P4. Resources Present: Building Structure Object District Explanation Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

1910 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

P11	I. R	epor	t Ci	tat	on:

Attachments:	☐ NONE	☐ Location Map	Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
		District Reco		eatu	re Record	Mill	ing S	Station Record	Rock Art Record
Artifact Record	☐ Phot	ograph Record	Other:						
DPR 523A (1/95) H	RG								

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

РРІМАКУ КЕСОКО

MRHP Status Code ID

ТэмэіvэЯ	Peview Code
	Other Listings

Page 1 of 1

a. County Los Angeles

Resource Name or #: Broadway Theater and Commercial District

P2. Location: 🗆 Not for Publication 🖼 Unrestricted P1. Other Identifier:

b. USGS 7.5' Quad T; R; 1, of 36c; Date and (P2b and P2C or P2d. Attach a Location Map as necessary.)

d. UTM: Zone; mE/ Nm c. Address 533 S BROADWAY City Los Angeles Zip 90013

e. Other Locational Data:

P3a. Description:

DPR 523A (1/95) HRG

☐ Archaeological Record

Artifact Record D Photograph Record

terrazzo sidewalk in front of the building is a character-defining feature of the property. Two-story reinforced concrete building, its facade clad in white marble facade with low reliefs. The first floor has been altered. The

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

Date

1931 (E) National Register form □ Prehistoric □ Both Sources: Mistoric P6. Date Constructed/Age and

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Milling Station Record

Rock Art Record

			Report Citation:	.llq
P9. Date Recorded: P10. Survey Type: Section Review)	1 19	-3 · • • • • • • • • • • • • • • • • • •	
P8. Recorded by: Christy J Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028		os it	5.00 E.C	
P7. Owner and Address: unknown				
P6. Date Constructed/Age Sources: Historic D Prehistoric D	about the same of	THE THE		
P5b. Description of Photo:	***		Photo or Drawing	esq

□ Ofher:

☐ Linear Feature Record

Attachments: \square NONE \square Location Map \square Sketch Map \square Continuation Sheet \square Building, Structure, and Object Record

District Record

PRIMARY RECORD


Primary # HRI# Trinomial

NRHP Status Code 1D

Other Listings Review Code Reviewer Page 1 of 1 Resource Name or #: Broadway Theater and Commercial District P1. Other Identifier: Pantages Theater/Arcade Theater P2. Location: Not for Publication Durestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M. c. Address 534 S BROADWAY City Los Angeles Zip 90013 d. UTM: Zone; mE/ e. Other Locational Data: P3a. Description:

Seven-story office and theater building of reinforced concrete with gray stucco facade by Morgan & Walls, and the facade shows Renaissance influence with Grecian columns. The first floor has been completely altered with no entrance to the theater. The terrazzo sidewalk in front of the building is a character-defining feature of the property.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories/10 Theater
P4. Resources Present: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	☐ NONE	☐ Location Map	☐ Sketch Map	☐ Continuation	n Sheet 🔲 I	Building, Structure,	and Object Record
☐ Archaeologica	I Record	District Recor	rd Linear F	eature Record	Milling S	tation Record	☐ Rock Art Record
Artifact Record	☐ Phot	ograph Record	Other:		The state of the s		194- E. 1934
DPR 523A (1/95) H	IRG						

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORN

Formerly a five-story brick structure, this building has been reduced to one story. The facade is totally altered.	red.
P3a. Description:	
e. Other Locational Data:	
d. UTM: Zone ; mE/ mM	
c. Address 535 S BROADWAY City Los Angeles Zip 90013	
b. USGS 7.5' Quad Date T; R; 1, of 1, of Sec; B.M.	
and (P2b and P2C or P2d. Attach a Location Map as necessary.)	
P1. Other Identifier: R1. Other Identifier: R2. Location: R2. Location: R3. County Los Angeles	
Page 1 of 1	
Review Code Reviewer Date	Date
Other Listings	
NRHP Status Code 6X3	

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

DPH (20\1) ASS2 A9G

P11. Report Citation:

P4. Resources Present:

☐ Archaeological Record

☐ Artifact Record ☐ Photograph Record

P2b. Description of Photo:

☐ Prehistoric □ Both Sources: 📓 Historic P6. Date Constructed/Age and

1903 (E) National Register form

uwonanu P7. Owner and Address:

Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106 P9. Date Recorded:

☐ Rock Art Record

☐ Milling Station Record

DS 853 MITTON 1 1961 VIS CQ	SOURCE STORY AND ADDRESS OF THE PARTY OF THE
	(AIRET AGAS)
und only aproperty	FUIL PARIAME
304 3401	
	and the state of t

□ Ofher:

☐ Linear Feature Record

Attachments: \square NONE \square Location Map \square Sketch Map \square Continuation Sheet \square Building, Structure, and Object Record

District Record

PRIMARY RECORD

P3a. Description:


Primary #
HRI#
Trinomial
NRHP Status Code 1

	Other Listings	NKHP Status Code 1D	
	Review Code	Reviewer	Date
Page I of I	Resource Name of	or #: Broadway Theater and Commercial District	5
and (P2b and P2C or I b. USGS 7.5' Quad	BROADWAY City Lo	p as necessary.) of 1/4 of Sec; B.M.	

Six-story reinforced concrete and brick structure in Art Deco style. The first floor has been altered.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

1931 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	□ NONE	☐ Location Map	☐ Sketch N	Лар 🗖	Continuation	Sheet	Building, Structure,	and Object Record
☐ Archaeological ☐ Artifact Record				ar Feat	ure Record	Milling	Station Record	☐ Rock Art Record
DPR 523A (1/95) H		3						

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

DPR 523A (1/95) HRG

☐ Archaeological Record

☐ Artifact Record ☐ Photograph Record

avon	IVE	NA

Twelve-story concrete office building consisting of two parallel win MacDonald. A large, arched opening in the elaborate facade leads to	s connected by an inner atrium, designed by Kenn his atrium, or arcade.	gned by Kenneth	ij
P3a. Description:			
e. Other Locational Data:			
Mm \3m ; ano\2 :MTU b			
c. Address 540 S BROADWAY City Los Angeles Zip 90	13		
b. USGS 7.5' Quad Date T; R; 1, of Sec	.m.a		
and (P2b and P2C or P2d. Attach a Location Map as necessar			
P1. Other Identifier: Broadway Arcade Building P2. Location: Not for Publication Unrestricted	a. County Los Angeles		
Page of Resource Name or #: Broadwa	Theater and Commercial District		
Review Code Revie	let Date	aneu	_
Other Listings		0,50	
	UT and subsequent		

P5b. Description of Photo: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

1924 (E) National Register form □ Prehistoric Sources: Mistoric 🗖 Both P6. Date Constructed/Age and

uwonan P7. Owner and Address:

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Rock Art Record

☐ Milling Station Record

									:uc	t Citatio	Repor	.hlq
,	,	,	,	F		-				1417		e .
			5.12 <u>-</u>	arriffice	7- 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2							
The state of the s				أرده تحديا								(
						lan.	eine .	in a	edju			\

□ Ofher: District Record 🗖 Linear Feature Record

Attachments: \square NONE \square Location Map \square Sketch Map \square Continuation Sheet \square Building, Structure, and Object Record

PRIMARY RECORD

Primary #
HRI#
Trinomial
NRHP Status Code 67.1

	5	THE STATE OF THE OWNER OF THE	
	Other Listings		
	Review CodeR	eviewer	Date
Page 1 of 1	Resource Name or #: Broa	dway Theater and Commercial D	istrict
and (P2b and P2C or b. USGS 7.5' Quad	S BROADWAY City Los Angeles // mN	ec; B.M.	
P3a. Description:			


Three-story brick commercial building with a mostly unadorned facade, which is clad in different materials above each of two

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

stores. There are few window openings above the first story.

P4. Resources Present:

Building
Structure
Object
Site
District
Element of District
Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

1910 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	☐ NONE	☐ Location Map	☐ Sketch Map	Continuation	Sheet 🗖	Building, Structure,	and Object Record
☐ Archaeological	Record	District Reco	rd Linear F	eature Record	Milling	Station Record	Rock Art Record
☐ Artifact Record	☐ Phot	ograph Record	Other:		T-n		and the business of the
DPR 523A (1/95) H	RG						

Primary # HRI# Isimomisi

State of California -- The Resources Agency

SEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

P1. Other Identifier: Eden Hotel

Trinomial III Status Code

Listings	Other
	39

	taintaid leinnammo	or #: Proodust Theater and	omela contrace
Date	THE RESERVE TO SERVE THE PARTY OF THE PARTY	Raviewer	Review Code
			Other Elstings

B.M.

Page I of I

a. County Los Angeles

P2. Location: 🗆 Not for Publication 🖾 Unrestricted

and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/2 of 1/2 of Sec;

C. Address 548 S BROADWAY City Los Angeles Zip 90013

Mm \am ; ano\subset :MTU .b

e. Other Locational Data:

P3a. Description:

Three-story brick building in Italianate style with decorative arched windows by John Parkinson, with a facade of pressed brick. The first floor has been removed. The facade is in poor condition.

P5b. Description of Photo:

P6. Date Constructed\Age and Sources: ■ Historic □ Both □ Prehistoric

1900 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:
P10. Survey Type: Section 106
Review

		ingitatio trans	PPU
	ν (γ		

Commence of the Commence of th	ME FLA Notice to the second s		480
	HEAVS AND		
-			

									RG	H (36/1) ASSS A90
					Ofher:		гарћ Record	potog	D byo	D Artifact Record
☐ Rock Art Record	Station Record	BuilliN	e Record [N	eatur	☐ Linear F	bı	District Recor	×	Record	☐ Archaeological
and Object Record	Building, Structure,	□ te	Continuation Shee		Sketch Map		Location Map		□ NONE	Attachments:


PRIMARY RECORD

Primary #
HRI#
Trinomial
NRHP Status Code ID

	.00110	NRH	P Status Code ID	
	Other Listings			
	Review Code	Reviewer	the Twelval	Date
Page 1 of 1	Resource Nan	ne or #: Broadway Theate	r and Commercial District	
	BROADWAY City Los mE/ mN	a. 000	unty Los Angeles	
P3a. Description:				
Six-story concrete and b	rick commerical building v	vith terra cotta details. The	first floor has been altered.	

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic Both Prehistoric

1923 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

P11. Report C	itation
---------------	---------

Attachments:	☐ NONE	☐ Location Map		Sketch Map	Continuation	Sheet [Building, Structure,	and Object Record
☐ Archaeological	Record		d	☐ Linear F			g Station Record —	
DPR 523A (1/95) H	-	3	-					

HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code 1D Trinomial

Reviewer Review Code Other Listings

P1. Jther Identifier: Swelldom Department Store Resource Name or #: Broadway Theater and Commercial District Page I of I

a. County Los Angeles P2. Location: 🗆 Not for Publication 🖼 Unrestricted

T; R; 1/4 of 1/4 of Sec; Date b. USGS 7.5' Quad and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 555-559 S BROADWAY City Los Angeles Zip 90013

NW d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

changed to 1D. address of "6th and Broadway." The correct range of Broadway addresses is noted above on this form, and the evaluation should be While the State Historic Resources Inventory lists the building as 71, it was included in the original National Register form with an terra cotta facade. The store fronts have been altered, the mezzanine is obscured, and the cast iron roof trim has been removed. Three-story retail building of Italian Renaissance Revival design by Pierpont and Davis made of reinforced concrete with a glazed

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

P5b. Description of Photo:

Date

□ Prehistoric □ Both Sources: Mistoric P6. Date Constructed/Age and


1920 (E) National Register form

nuknown P7. Owner and Address:

Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group Christy Johnson McAvoy P8. Recorded by:

Section 106 Review P10. Survey Type: P9. Date Recorded: 6/1/98

> S. Harrison in the second ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present:



						ອ	DPP 5234 (1/05) HP
				:Dther:	by Record	☐ Photogra	D Artifact Record
-☐ Rock Art Record	Station Record	gnilliM 🗖	ature Record	☐ Linear Fe	District Record	Secord 🖼	Archaeological F
e, and Object Record	Building, Structur	□ Sheet □	Continuation	2 Sketch Map	ocation Map	NONE DE	Attachments: [

PRIMARY RECORD


Primary # HRI# Trinomial

1 I ZIIAIVALLE IVI	LOOKD	NRHP Status Code 1D	
	Other Listings		
	Review Code	Reviewer	Date
Page I of I	Resource Name or #:	Broadway Theater and Commercial Dist	rict
P1. Other Identifier:			
	t for Publication 📓 Unrestricted	a. County Los Angeles	
and (P2b and P2	C or P2d. Attach a Location Map as	necessary.)	
b. USGS 7.5' Qu	ad Date T; R; 1/4 of 1/	of Sec; B.M.	
c. Address 558 S	S BROADWAY City Los Angeles	Zip 90013	
d. UTM: Zone;	mE/ mN		
e. Other Location	nal Data:		

P3a. Description:

Five-story reinforced concrete building with terra cotta details by Walker & Eisen. The storefronts have been redesigned, but the distinctive upper stories of the facade are intact.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories
P4. Resources Present: ☐ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

1920 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	□ NONE	☐ Location Map	Sketch Map		Continuation	Sheet		Building, Structu	ure, and Object Recor	d
		District Reco		eatu	ire Record	☐ Milli	ng	Station Record	☐ Rock Art Reco	rd
☐ Artifact Record		ograph Record	Otner:							

Trinomial HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

a. County Los Angeles

KECOKD	YAAMIA9
DECODD	V. a A Baida

Date	Reviewer	Review Code
		Other Listings

P1. Other Identifier: Walter P. Story Building

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 600-610 S BROADWAY City Los Angeles Zip 90014 T; R; 1, of Sec; Date b. USGS 7.5' Quad

\∃rn ; enc≲ :MTU .b

e. Other Locational Data:

P3a. Description:

Page I of I

cornice, decorative bands, and arched attic story windows. The base has been completely altered, but the upper stories are intact. Eleven-story office building of reinforced concrete by Morgan & Walls with an unusually ornate terra cotta facade, with a heavy

Building □ Structure □ Object □ Site □ District B Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

□ Prehistoric Sources: Mistoric □ Both P6. Date Constructed/Age and

1908 (E) National Register form

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

	the state of the s	- 181 A - 181 W	100 mars -	Poport Citation:	FFG
P10. Survey Type: Section Review					
P9. Date Recorded:			12 - 12 - 12 - 12 - 12 - 12 - 12 - 12 -	PERSONAL PROPERTY.	
P8. Recorded by: Christy J Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028			Company of the Compan		
	1.3	111	- Jaconik sees		
P7. Owner and Address: unknown		The state of the s	Accomplete to		
1908 (E) National Register f		- Marie Caraca			
P6. Date Constructed/Age Sources: Mistoric D		The second			
P5b. Description of Photo:	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			Photo or Drawing	p5a

					56	DDD E22A (4/0E) !!
			□ Ofher:	alsph Record	□ Photo	DAdifact Record
□ Воск Ап Весога	☐ Milling Station Record	eature Record	d Linear F	District Recor	Record	☐ Archaeological
ure, and Object Record	Sheet 🛮 Building, Struct	□ Continuation	☐ Sketch Map	☐ Location Map	□ NONE	Attachments:

PRIMARY RECORD

Primary #
HRI#
Trinomial
NRHP Status Code ID

Other Listings	But II	infrience	
Review Code	Reviewer	Date	
D	#-D1 TI / 16		

Page 1 of 1

Resource Name or #: Broadway Theater and Commercial District

P1. Other Identifier: Norton Building

P2. Location: ☐ Not for Publication ☐ Unrestricted

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec;

c. Address 601-605 S BROADWAY City Los Angeles Zip 90014

d. UTM: Zone; mE/ mN

e. Other Locational Data:

P3a. Description:

Six-story brick and concrete office building. The facade and first floor have been altered, and the mezzanine has been obscured.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present: ☐ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

1906 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	☐ NONE	☐ Location Map	Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
		District Record	hand.	eatu	ire Record	Milli	ng :	Station Record	☐ Rock Art Record
DPR 523A (1/95) H	IRG								

HRI# Primary # DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code ID Trinomial

	7. 7. di	
Date	Деуіємет	Aeview Code
10 10		Other Listings

and the same of th	Los Angeles Theater	P1. Other Identifier: I
oadway i neater and commercial district	Resource Name or #: Bro	Page I of I

and (P2b and P2C or P2d. Attach a Location Map as necessary.) P2. Location: 🗆 Not for Publication 🛭 Unrestricted a, County Los Angeles

c. Address 609-619 S BROADWAY City Los Angeles Zip 90014 Date b. USGS 7.5' Quad T; R; 1, of 1, of Sec;

A. UTM: Zane ; mEV

e. Other Locational Data:

P3a. Description:

altered. The terrazzo sidewalk in front of the building is a character-defining feature of the property. two-story retail storefronts. The one to the south retains its terra cotta ornamentation, and the one to the north has been completely portion heavily ornamented with fluted columns, urns, eagles, and a nonoriginal marquee. The theater is flanked on both sides by Concrete theater building in French Renaissance Revival style, designed by S. Charles Lee. The facade features a tall, central

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 06 Commercial Building, 1-3 stories/10 Theater

P6. Date Constructed/Age and

□ Prehistoric Sources: E Historic □ Both

1930 (E) National Register form

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

¥				4 Citation.	P11 Repor
P10. Survey Type: Section Review			, i)	Albi iskila	
P9. Date Recorded:			and saling	TI ATION	
Hollywood, CA 90028			ssaping .	1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
P8. Recorded by: Christy J Historic Resources Group					
пикиоми					
P7. Owner and Address:	4.1				
□ Prehistoric 1930 (E) National Register f		2			
P6. Date Constructed/Age Sources: Mistoric D					
P5b. Description of Photo:	4		Marian (1)	nniwea() ag	atodg ead
DEP Description of Dhoto.					

DDD COSV (4/06)	Jen								
D Artifact Recon	р Пърод	ograph Record		Ofher:					
☐ Archaeologica	ll Record	District Reco	pı	☐ Linear Fe	sature F	B Record	3 gnilliM 🗖	Station Record	☐ Rock Art Record
Attachments:	□ NONE	☐ Location Map		sketch Map	D Col	Sontinuation Sh	peet 🗆	Building, Structure,	and Object Record

PRIMARY RECORD

Primary #
HRI#
Trinomial
NRHP Status Code 1D

Other Listings Review Code __ Reviewer _ Page I of I Resource Name or #: Broadway Theater and Commercial District P1. Other Identifier: Desmond's P2. Location: Not for Publication Mulli Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/4 of 1/5 of Sec; B.M. c. Address 612-616 S BROADWAY City Los Angeles Zip 90014 d. UTM: Zone; mE/ e. Other Locational Data:


P3a. Description:

Six-story concrete structure in Spanish Baroque Revival style by A. C. Martin including a polychrome terra cotta facade with twisting columns. balconies, and ornamental pediment. The first floor has been completely altered, but the upper stories are intact.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present:

Building Structure Object Site District Element of District Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

1924 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments.	- NONE		_	01 / 1 1 1					Daniel Marine	
Attachments:	- NONE	Location Map		Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
☐ Archaeological	Record	District Reco	rd	☐ Linear F	eatu	ure Record	ПMil	ling :	Station Record	Rock Art Record
		ograph Record					ш	3	necephal [3] Lagu	
DPR 523A (1/95) H	RG		_							

Trinomial HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code 1D

-:4-:	11	,,,					
	A Maria		-	-	B	10	п

				:uc	P3a. Descriptio
				coational Data:	e. Other L
				Zone; mE/ mN	A. UTM: Z
			Sec ; B.M.	and P2C or P2d. Attach a Location Map as necession Map as necession was a necession map as necession was a nec	P' N2G2
			a. County Los Angeles	itifier: Schaber Cafeteria/Broadway Cafeteria Not for Publication Unrestricted	P2. Location:
		District	adway Theater and Commercial I	Resource Name or #: Bro	Page l of l
	Date	-	Reviewer	Review Code	
	-			Other Listings	

reinstalled or replicated where missing. The integrity of the facade is high, and the building is in good condition. terra cotta which had been removed during earlier alterations was replaced, and original decorative wrought iron grillwork was wrought iron ornamentation. The interior was destroyed by fire and rebuilt, at which time the terra cotta facade was restored. The Two-story concrete Spanish Baroque Revival style cafeteria building by Charles F. Plummer. The facade is clad in terra cotta with

P5b. Description of Photo: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

□ Prehistoric □ Both Sources: Mistoric P6. Date Constructed/Age and

1928 (E) National Register form

P7. Owner and Address:

nuknown

Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106 P9. Date Recorded:

η
1dans 11 310-11
SIA91
PSa Photo of Drawing

DPR 523A (1/95) H	SG								
☐ Artifact Record	D Phot	odusbh Record		Other:					
☐ Archaeologica		■ District Re	prd	☐ Linear Fo	intse	re Record	S gnilliM □	Station Record	☐ Rock Art Record
Strachments:	□ NONE	☐ Location Ma		ketch Map		Continuation She	heet 🗖	Building, Structure, a	and Object Record

Primary # HRI# Trinomial NRHP Status Code 6X3

P	R	20000000	N	N	A	F	5,	Y	R	E	C	0	R	D
B	8 0		m v	F. DR.	w .	89	TO.		H 4	Section 2	-		E @	Description

Other Listings Review Code Reviewer

Page 1 of 1

Resource Name or #: Broadway Theater and Commercial District

P1. Other Identifier:

P2. Location: Not for Publication Unrestricted a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M. c. Address 621-625 S BROADWAY City Los Angeles Zip 90014

d. UTM: Zone; mE/


e. Other Locational Data:

P3a. Description:

The facade of this five-story concrete and brick structure appears to have been remodeled in the 1940s. The facade is clad in large, square, glazed terra cotta tiles. Six banks of horizontal awning windows light the top three floors.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present: Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: # Historic ☐ Both ☐ Prehistoric 1919 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	■ NONE	☐ Location Map	Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
		District Reco		eatu	re Record	Millin	ng S	Station Record	☐ Rock Art Record
Artifact Record	☐ Phote	ograph Record	Other:						
DPR 523A (1/95) H	RG								

Trinomial HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code 1D

Ded	 Reviewer	AboO waivaR
		Other Listings
		2241401 1 20-140

Resource Name or #: Broadway Theater and Commercial District

Page I of I

a. County Los Angeles

P2. Location: 🗆 Not for Publication 🖺 Unrestricted P1. Other identifier: Palace Theater

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 626-636 S BROADWAY City Los Angeles Zip 90014 b. USGS 7.5' Quad T; R; 1, of 1, of Sec; Date

d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

DPR 523A (1/95) HRG

☐ Archaeological Record

Artifact Record | Photograph Record

been obscured. The glass block sidewalk in front of the building is a character-defining feature of the property. facade that features arched windows, heavy cornice, and carved figures. The first floor has been altered, and the mezzanine has Five-story brick and concrete theater and office structure by G. Albert Landsburgh in French Renaissance style with a terra cotta

Building 🗖 Structure 🗖 Object 🗖 Site 🗖 District 📓 Element of District 🗖 Other PA Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories/10 Theater

☐ Rock Art Record

☐ Milling Station Record

Building, Structure, and Object Record	□ feet □	Map Contin	Wap □ Sketch	□ Location	□ NONE	Attachments:
300 (Car-1)						P11. Report Cita
P9. Date Recorded: P10. Survey Type: Section 106 Review	8)_ 	1	. ÷ d
P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028			1818 KHI			
P7. Owner and Address: unknown	1110100					
P6. Date Constructed/Age and Sources: Historic Definitionic Prehistoric Prehistoric Definional Register form						
P5b. Description of Photo:		V			naiwer	O a otodo or O

Offher:

District Record

☐ Linear Feature Record

Primary # HRI# Trinomial NRHP Status Code 6X3

P	R	IN	MA	RY	RF	CO	RD
8	B #	881	9 2 2 2		El & Elmon		

Other Listings Review Code Reviewer Resource Name or #: Broadway Theater and Commercial District

Page 1 of 1

P1. Other Identifier:

P2. Location: Not for Publication Durestricted a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M.

c. Address 629 S BROADWAY City Los Angeles Zip 90014


d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

Four-story brick and concrete structure. The facade has been completely remodeled in a contemporary design.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories P4. Resources Present: Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic ☐ Both ☐ Prehistoric 1911 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	☐ NONE	☐ Location Map		Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
☐ Archaeologica	I Record	District Reco	rd	☐ Linear F	eatu	ire Record	'J Milli	ng :	Station Record	☐ Rock Art Record
Artifact Record	d Phot	ograph Record		Other:		2000	3. 100			facilitat []
DPR 523A (1/95) H	IRG									

Trinomial HBI# Primary #

NRHP Status Code 6Z3

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

41401 1 44 440		
KECOVD	1	L

Seview Code
Other Listings

Resource Name or #: Broadway Theater and Commercial District

Reviewer

Page I of I

P1. Other Identifier:

P2. Location: 🗆 Not for Publication 🖼 Unrestricted a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 633 S BROADWAY City Los Angeles Zip 90014 b. USGS 7.5' Quad T; R; 1/4 of 1/4 of Sec; Date

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

DPR 523A (1/95) HRG

Artifact Record D Photograph Record

☐ Archaeological Record ☑ District Record

P3a. Description:

Four-story brick structure with a newer flat, stucco facade.

Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P5b. Description of Photo:

Date

D Rock Art Record

☐ Milling Station Record

Building, Structure, and Object Record	Continuation Sheet	☐ Sketch Map ☐	☐ Location Map	□ NONE	chments:	sttA
, , ,					Report Cita	.110
P9. Date Recorded: P10. Survey Type: Section 106 Review					-4	
1728 Whitley Ave. Hollywood, CA 90028				1 12	2 H	
P8. Recorded by: Christy Johnson Historic Resources Group						
P7. Owner and Address: unknown						
Sources: Historic Deoth Prehistoric Dath Prehistoric						
P6. Date Constructed/Age and		d Pass				
PSb. Description of Photo:				414		.,,

□ Ofher:

☐ Linear Feature Record

Primary # HRI# Trinomial

3	m	8 8	I All	A	DY	V	D	-	0	0	m	m
۳	K	H	۷I	A	K	Y	R		b	U	K	IJ

NRHP Status Code 6X3 Other Listings

Page 1 of 1

Resource Name or #: Broadway Theater and Commercial District

Reviewer

P1. Other Identifier:

P2. Location:

Not for Publication
Unrestricted a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

Review Code

Date b. USGS 7.5' Quad T; R; 1/4 of 1/4 of Sec; B.M.

c. Address 635 S BROADWAY City Los Angeles Zip 90014

d. UTM: Zone; mE/


e. Other Locational Data:

P3a. Description:

Four-story brick office building. The structure has been reduced to two stories, and the second floor has been completely obscured.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other P4. Resources Present:



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: M Historic □ Both ☐ Prehistoric 1906 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106

Review

P11. F	Report (Citatio	n
--------	----------	---------	---

Attachments:	□ NONE	☐ Location Map		Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record	
☐ Archaeologica	l Record	District Recor	ď	☐ Linear F	eatu	re Record	☐ Milli	ing :	Station Record	☐ Rock Art Record	
Artifact Record	d ☐ Phote	ograph Record		Other:						A transit of	
DPR 523A (1/95) H	IRG										

Irimonial HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

Other Listings

Date

Reviewer Review Code

Resource Name or #: Broadway Theater and Commercial District

Page I of I

a. County Los Angeles

NRHP Status Code 1D

P2. Location: 🗆 Not for Publication 🖪 Unrestricted P .. Other identifier: Forrester Building

T; R; 1, of 1, of Sec; Date and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 638 S BROADWAY City Los Angeles Zip 90014 b. USGS 7.5' Quad

d. UTM: Zone; mE/ NW

e. Other Locational Data:

P3a. Description:

The first three floors have been altered and covered by a newer facade. Eight-story concrete structure by C. F. Whittlesey with terra cotta and stone facade including heavy comice and arched windows.

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

Attachments: 🗖 NONE 🗖 Location Map 🗖 Sketch Map 🗖 Continuation Sheet 🗖 Building, Structure, and Object Record

□ Both Sources: Mistoric P6. Date Constructed/Age and

1907 (E) National Register form □ Prehistoric

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Milling Station Record

☐ Rock Art Record

				The Penetr Citation
P9. Date Recorded: P10. Survey Type: Section Review			71	
P8. Recorded by: Christy J Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028			5 5 3 3 5 5 5	
P7. Owner and Address: unknown		da d		
P6. Date Constructed/Age Sources: ■ Historic □ Prehistoric □ Prehistori		(Madeira)		
P5b. Description of Photo:	7		bu	P5a. Photo or Drawin

P11. Report Citation:

Ofher:		рр Record	otogra	U bp	Artifact Record
☐ Linear Feature Record	prd	District Reco	90	Record	☐ Archaeological

DPR 523A (1/95) HRG

PRIMARY RECORD

Primary #
HRI#
Trinomial
NRHP Status Code 1D

	Con Swarch Elling St. Hilling	NRHP	Status Code 1D	
	Other Listings			- 14 Miles
	Review Code	Reviewer	· subjects	Date
Page 1 of 1	Resource Name	or #: Broadway Theater	and Commercial Distr	rict
P2. Location: Not and (P2b and P2C b. USGS 7.5' Qua c. Address 639-6:		ted a. Cour	nty Los Angeles	
e. Other Locationa	l Data:			

P3a. Description:

P4. Resources Present:

Seven to ten story brick and concrete structure by Morgan & Walls with a brick and terra cotta facade. Built in stages, the building has portions of different heights which are united by continuous string courses. The windows of the top stories below the attic have segmental arched headers.

■ Building ☐ Structure ☐ Object ☐ Site ☐ District ■ Element of District ☐ Other

P5b. Desc P6. Date of Sources: 1912 (E) 1 P7. Owne unknown

P8. Record Historic R 1728 Whit Hollywood

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic Both Prehistoric

1912 (E) National Register form

P7. Owner and Address:

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	□ NONE	☐ Location Map	Sketch Map		Continuation	Sheet		Building, Structure	e, and Object Record
Archaeologica		District Reco	-	eatu	ire Record	□Milli	ing :	Station Record	☐ Rock Art Record
		ograph Record	Other:						al amad
DPR 523A (1/95) H	IRG								

HRI# Primary # DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code ID Trinomial

Resource Name or #: Broadway Theater and Commercial District Review Code Reviewer Date Other Listings Page I of I

a. County Los Angeles

P2. Location: 🗆 Not for Publication 🖼 Unrestricted P1. Other Identifier: J. E. Carr Building

b. USGS 7.5' Quad Date T; R; 1, of 1, of Sec; and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 644 S BROADWAY City Los Angeles Zip 90014

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

P3a. Description:

DPR 523A (1/95) HRG

P11. Report Citation:

☐ Archaeological Record

☐ Artifact Record ☐ Photograph Record

A newer brick facade covers the first four floors. Eight-story concrete structure by R. B. Young with glazed terra cotta and brick facade featuring heavy cornice and arched windows.

P4. Resources Present: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P3b. Resources Attributes: 07 Commercial Building, over 3 stories

□ Both Sources: Mistoric P6. Date Constructed/Age and

P2b. Description of Photo:

1908 (E) National Register form □ Prehistoric

nuknown P7. Owner and Address:

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Rock Art Record

P Milling Station Record

	TETO
THE PARTY OF THE P	
第二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十	man de la constancia de

□ Ofher:

District Record

☐ Linear Feature Record

Attachments: \square NONE \square Location Map \square Sketch Map \square Continuation Sheet \square Building, Structure, and Object Record

PRIMARY RECORD

Primary #
HRI#
Trinomial
NRHP Status Code 1S

Other Listings

Review Code Reviewer Date

Page 1 of 3

Resource Name or #: Clifton's Brookdale Cafeteria Terrazzo Sidewalk

P1. Other Identifier: Clifton's Brookdale Cafeteria Terrazzo Sidewalk

P2. Location:

Not for Publication
Unrestricted

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/4 of

T; R; 1/4 of 1/4 of Sec; B.M

c. Address 648 S BROADWAY City Los Angeles Zip 90014

d. UTM: Zone; mE/ mN

e. Other Locational Data:

P3a. Description:

The terrazzo sidewalk in front of Clifton's Brookdale Cafeteria spans the full forty-five-foot length of the building facade and extends approximately fifteen feet from the foyer to the curb. The stylized, curvilinear design features images of Los Angeles landmarks such as City Hall, the Hollywood Bowl, Griffith Park Observatory and the Colosseum, as well as themes and scenes associated with the area such as a sail boat, desert cacti, orange groves, musical notes, and film production. The colors include orange, red, yellow, blue, green, white. Each of these ten representational images are set in octagons in a line along the top of the composition (near the building itself) and have brass letters below naming the sites they depict. At the center of the design is a large sunburst set within a circle. Around the top of the circle bronze letters are set in the terrazzo and read "Clifton's Brookdale." The sidewalk is in excellent condition.

P3b. Resources Attributes:

P4. Resources Present: ☐ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic Both Prehistoric

c. 1935

0. 1755

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson McAvoy Historic Resources Group 1728 Whitley Ave., Hollywood

P9. Date Recorded: 7/1/98

P10. Survey Type: Section 106 Review

P11. Report Citation: None.

Attachments: NON	E Location Map	Sketch Map	Continuation Sheet	Building, Structu	ire, and Object Record
☐ Archaeological Record ☐ Artifact Record ☐ P DPR 523A (1/95) HRG	☐ District Record	☐ Linear Featu		ling Station Record	☐ Rock Art Record

Primary # HRI#

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

BUILDING, STRUCTURE, AND OBJECT RECORD

			mirant interior	Dec Beets	Tuteod botclod	80
:uc	Original Locatio	Date:	□ Unknown	S∌, □	Moved? ⊠ No	.78
.955 and 1939.	installed between	ewalk was	bis ozzanət ədl	listory:]	Construction P	.9B
	- 50 157				Architectural S	
sut nee: Sidewalk	B4. Prese			idewalk	Original Use: S	B3.
	Tazzo Sidewalk	Safeteria Ter	's Brookdale C	e: Clifton	Common Name	85
	azzo Sidewalk	rieteria Terr	s Brookdale Ca	Clifton	Historic Name:	.18
okdale Cafeteria Terrazzo Sidewalk	#: Clifton's Bro	зе Иате ог	Resourc			
RHP Status Code 15					6 30 S e	Ьяд

B9a. Architect:

B10. Significance: Theme Art

B10. Significance: Theme Art

Period of Significance Property Type Applicable Criteria C

Period of Significance Property Type Applicable Criteria C

The terrazzo sidewalk in front of Clifton's Brookdale Cafeteria is individually eligible for listing in the National Register under Criterion C for its high artistic value. The sidewalk is a fine example of the Moderne style that was associated with the example of a terrazzo mural would be those in the lobby of Santa Monica City Hall). Constructed sometime between 1935 and 1939, the sidewalk depicts scenes from the Los Angeles area such as Catalina Island, Los Angeles City Hall, and the Criffith Park Observatory as well as themes associated with the city such as music and film. The sidewalk was conceived by Clifford Park Observatory as well as themes associated with the city such as music and film. The sidewalk was conceived by Clifford Clinton and installed at the same time he was remodeling the restaurant, which was the third in his chain. The Venetian Terrazzo Company was hired to execute Clinton's idea.

Clifton's Brookdale Cafeteria is located in the ground floor of a four-story building in the Broadway Theater and Commercial District. Constructed in 1916, the building has been extensively altered and does not contribute to the significance of the

(see Continuation Sheet)

B11. Additional Resource Attributes: 39 Other, sidewalk

		···
(This space reserved for official comments.)		
B14. Evaluator: Christy Johnson McAvoy, Historic Resources Group, 1728 Whitley Ave., Hollywood Date of Evaluation: 7/1/98		
.os Angeles Public Library; "Life Visits Clifton's Cafeteria," Life, Vovember 27, 1944, pp. 102-105.		
312. References: Sylvia Johnson, "Cafeterias of the Golden Rule: Califon's Cafeteria," unpublished article in the California Vertical File, Architection, 1:65 Wiele, Cliffon's Cafeteria, 1:65 Wiele, 1:65 Wie		

CONTINUATION SHEET

Primary # HRI# Trinomial

Page 3 of 3

Resource Name or #: Clifton's Brookdale Cafeteria Terrazzo Sidewalk

Recorded by: Historic Resources Group

Date: 7/1/98

Continuation Update

B10. Significance continued

Terrazzo, an ancient material combining marble chips with white cement, was perfected by fifteenth century Venetian craftsmen to pave terraces, thus the name was derived. Terrazzo gained popularity in the 1920s, when architects began to use it to pave sidewalks, foyers, and lobbies to distinguish the buildings with which they were associated.

Terrazzo is used extensively throughout the district to pave sidewalks and foyers. The sidewalk in front of Clifton's is one of the largest examples in the district, and is distinct from other examples in its curvilinear, streamlined design and use of figural, representational images and bold, simple, abstracted forms. The images in the sidewalk tell a story about the unique features of the cityscape, natural features, cultural activities and industries of Los Angeles both to regular patrons of the city's then-largest shopping district and to visiting tourists.

The colors in the sidewalk were created with different colors of dyed marble aggregate and tinted cement.

Most of the other examples in the district were installed during the 1920s and early 1930s and reflect the designs of this era with sharp, rectilinear, non-figural designs. Other notable examples of terrazzo in Los Angeles occur in front of major theaters such as the Wiltern.

Trinomial Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

a. County Los Angeles

	eater and Commercial District	Thompsond	
 Date		Reviewer	Review Code
			Other Listings

Page I of I

Pí. Other identifier: Clifton's Cafeteria

Date

and (P2b and P2C or P2d. Attach a Location Map as necessary.) P2. Location: 🗆 Not for Publication 🗃 Unrestricted

b. USGS 7.5' Quad

Nm d. UTM: Zone; mE/ c. Address 648 S BROADWAY City Los Angeles Zip 90014

e. Other Locational Data:

P3a. Description:

building, featuring pictorial scenes of California, is individually significant. though the building itself is not a contributor to the Broadway Theater and Commercial District, the terrazzo sidewalk in front of the Four-story brick building with arched windows and reliefs on facade. The facade is now completely covered by a metal screen.

P2b. Description of Photo: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

T; R; 1, of 1, of Sec;

□ Prehistoric Sources: Mistoric □ Both P6. Date Constructed/Age and

1916 (E) National Register form

nuknown P7. Owner and Address:

Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group Christy Johnson McAvoy P8. Recorded by:

Section 106 Review P10. Survey Type: P9. Date Recorded: 6/1/98

☐ Rock Art Record

☐ Milling Station Record

	NROY WEN	
	Contraction of the second	
	RIA	72-
	CAFETE	
HHHHHH HHHHH		P5a. Photo or Drawing

□ Ofher:

☐ Linear Feature Record

Attachments:

NONE Location Map Sketch Map
Continuation Sheet
Building, Structure, and Object Record

P11. Report Citation:

☐ Artifact Record ☐ Photograph Record District Record Prchaeological Record

DPR 523A (1/95) HRG

PRIMARY RECORD

Primary # HRI# Trinomial

No. 12 Martin Co. 191 Dec. 2	Trinomial
25 11 - 4 - 21 - 2 - 2	NRHP Status

	Other Listings				
	Review Code	Reviewer		Date	
Page I of I	Resource Name	or # Broadway Theater a	nd Commonaid District		

P1. Other Identifier: Haas Building

P2. Location: ☐ Not for Publication ☐ Unrestricted

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M.

c. Address 660 S BROADWAY City Los Angeles Zip 90014

d. UTM: Zone; mE/ mN


e. Other Locational Data:

P3a. Description:

Twelve-story concrete office building. Drastic alterations in 1974 left the building completely "modernized" with a typical tile and glass facade. Originally, it was heavily ornamented in white glazed terra cotta ornamentation, designed by Morgan, Walls & Morgan.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present: ☐ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

1914 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

T Archaeological Pecord District Description	Attachments:	■ NONE	□ Location Map	☐ Sketch N	lap 🗖	Continuation	Sheet	Building,	Structure.	and Object Reco	rd
DPR 523A (1/95) HRG	☐ Archaeological ☐ Artifact Record	Record	District Recor	rd 🔲 Line						☐ Rock Art Reco	

HKI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

Trinomial

- 15 - 25 m	672	NRHP Status Code

Reviewer Other Listings

Resource Name or #: Broadway Theater and Commercial District Review Code Page I of I

P1. Other Identifier:

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.) P2. Location:

□ Not for Publication

□ Unrestricted

c. Address 700-708 S BROADWAY City 1.os Angeles Zip 90014 b. USGS 7.5' Quad Date T; R; 1, of 1, of Sec;

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

P3a. Description:

district contributor (ID), which was demolished. This is a seven-story concrete parking garage with storefronts on the first story. Formerly on this site was the Lankershim Hotel, a

Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories/39 Other - Parking Garage

Sources: Mistoric □ Both P6. Date Constructed/Age and

☐ Milling Station Record Map

Continuation Sheet

Building, Structure, and Object Record

☐ Rock Art Record

				Report Citation:	P11. F
P10. Survey Type: Section 106 Review	. 1	- 1			12
P9. Date Recorded: 6/1/98		The second			
Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028		11 1 2 1 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4			_
P8. Recorded by: Christy Johnson McAvoy		ib sita)	And the second		
пикиоми				. Sikub	
P7. Owner and Address:					-
□ Prehistoric					
Sources: Mistoric D				Albert Street	
P6. Date Constructed/Age	The same of the sa	and the second	Same and St.	THE TANK AND THE T	
P2b. Description of Photo:	4		THE STATE OF THE S		

ature Record	☐ Linear Fe	District Record	國	al Record	D Archaeologics
				□ NONE	:etnemdostA

Other:

DPR 523A (1/95) HRG

PRIMARY RECORD

e. Other Locational Data:

Primary # HRi# Trinomial


ח	Trinomial
	NRHP Status Code 1D
er Listings	

	Review Code	Reviewer	alya 2 watisana	Date
Page I of I	Resource Name	e or #: Broadway Theater	and Commercial District	Acres in grad
b. USGS 7.5' Quad	Publication © Unrestrict P2d. Attach a Location M Date T; R; 1/4 BROADWAY City L	cted a. Coun lap as necessary.)	ty Los Angeles	

P3a. Description:

Twelve-story concrete theater and office building by Weeks & Day in Spanish Renaissance style with patterned brick and terra cotta ornamentation including windows with ogee arched headers on the top story. The corner of the building at Seventh Street is rounded in plan. The first floor has been altered, and projecting canopies have been added.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories/10 Theater
P4. Resources Present: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric 1920 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	☐ NONE	☐ Location Map	Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
☐ Archaeologica		District Reco		eatu	re Record	☐ Mill	ing :	Station Record	☐ Rock Art Record
Artifact Record	☐ Phot	ograph Record	Other:						E PRINA E
DPR 523A (1/95) H	IRG								

HKI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code 1D Trinomial

a. County Los Angeles

strict	or #: Broadway Theater and Commercial D	Resource Name
— Date —	Reviewer	Review Code
		Other Listings

P1. Other Identifier: Yorkshire Apartments

P2. Location: 🗆 Not for Publication 🖪 Unrestricted

c. Address 710 S BROADWAY City Los Angeles Zip 90014 b. USGS 7.5' Quad T; R; 1, of 1, of Sec; Date and (P2b and P2C or P2d. Attach a Location Map as necessary.)

\∃m ; əno∑ :MTU .b Nm

e. Other Locational Data:

P3a. Description:

Page I of I

windows, and tile cornice. The first floor has been altered. Six-story brick and concrete structure by Parkinson & Bergstrom with facade of pressed brick and terra cotta with tile, arched

P4. Resources Present:

Building
Structure
Object
Object
District
Element of District
Other P3b. Resources Attributes: 07 Commercial Building, over 3 stories

Sources: Mistoric □ Both P6. Date Constructed/Age and

1909 (E) National Register form □ Prehistoric

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Milling Station Record

Rock Art Record

	11. Report Citation:
P8. Recorded by: Christy J Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028 P9. Date Recorded: P10. Survey Type: Section Review	DITE TO THE TOTAL THE TOTA
Sources: Mistoric Developments Drehistoric Developments Mational Register for Owner and Address: Unknown	
P5b. Description of Photo:	

□ Ofher:

District Record

☐ Linear Feature Record

Attachments: \square NONE \square Location Map \square Sketch Map \square Continuation Sheet \square Building, Structure, and Object Record

DPR 523A (1/95) HRG

☐ Archaeological Record

☐ Artifact Record ☐ Photograph Record


PRIMARY RECORD

Primary #
HRI#
Trinomial
NRHP Status Code 1D

	Other Listings				
	Review Code	Reviewer	off warright	Date	
Page 1 of 1	Resource Name	or#: Broadway Theater and	Commercial District	176 (30)	67
Pi. Other Identifie	r: Not for Publication 國 Unrestric	ted a County I	and American		
	P2C or P2d. Attach a Location Ma	a. County 1	Los Angeles		
b. USGS 7.5'		of 1/4 of Sec; B.M.			
		os Angeles Zip 90014			
d. UTM: Zone	; mE/ mN				
e. Other Locat	ional Data:				
D0 - D - : //					
P3a. Description:					

Six-story concrete commercial building. Windows bays and piers and spandrel panels themselves are intact, though the entire facade has been stuccoed, and the cornice and all other ornamentation has been removed. The terrazzo sidewalk in front of the building is a character-defining feature of the property.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories
P4. Resources Present: ☐ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic Both Prehistoric

1907 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

P11.	Report	Citation

Attachments:	□ NONE	☐ Location Map		Sketch Map		Continuation	Sheet	П	Building, Structure,	and Object Record
☐ Archaeologica	Record	District Reco	rd	☐ Linear F	eatu	ire Record				Rock Art Record
	Charles	ograph Record		Other:			- 3/1			
DPR 523A (1/95) H	RG									

HRI# Primary # DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

Trinomial

NRHP Status Code 1D

Review Code Other Listings

Resource Name or #: Broadway Theater and Commercial District

Reviewer

Page I of I

a. County Los Angeles

P2. Location: 🗖 Not for Publication 🖼 Unrestricted P1. Other Identifier: Woolworth's

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 719 S BROADWAY City Los Angeles Zip 90014 T; R; 1, of 1, of Sec; Date b. USGS 7.5' Quad .M.A

d. UTM: Sone; mE/ ИШ

e. Other Locational Data:

P3a. Description:

neighboring building was incorporated. Three-story commercial building by Weeks & Day. When the Art Deco style alterations to the facade were completed, a

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

P5b. Description of Photo:

Date

□ Prehistoric □ Both Sources: Mistoric P6. Date Constructed/Age and

1920 (E) National Register form

nuknown P7. Owner and Address:

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

TIME	SIART SILNVE
	Sammarad Age

P11. Report Citation:

DPR 523A (1/95) HRG

☐ Artifact Record	1049 🗖	odusph Reco		l Other:					
☐ Archaeological	Record	District	cord	☐ Linear Fe	ture Record	∏ Millir 🗆	ng Station Re	cord	☐ Rock Art Record
Attachments:	□ NONE	□ Location] de	2 Sketch Map	Continuation :	Sheet I	'6uipling 🗖	Structure,	and Object Record

PRIMARY RECORD

Primary # HRI# Trinomial NRHP Status Code 1D

Other Listings

Review Code _____ Reviewer ___

B.M.

Page I of I

Resource Name or #: Broadway Theater and Commercial District

P1. Other Identifier: Barker Brothers Building

P2. Location: Not for Publication I Unrestricted

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec;

c. Address 722 S BROADWAY City Los Angeles Zip 90014

d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

Seven-story concrete and brick structure by R. B. Young originally with a pressed brick facade. The cornice and original parapet have been removed, the first floor has been altered, and the mezzanine has been obscured.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present:

Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other

P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic ☐ Both ☐ Prehistoric

1909 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

P11. Report Cita	ation:						
Attachments:	□ NONE	☐ Location Map	☐ Sketch Map	☐ Continuation	Sheet	Building, Structure	e, and Object Record
☐ Archaeologica	al Record	District Reco	rd Linear F	eature Record	☐ Milling	Station Record	☐ Rock Art Record
☐ Artifact Recor	d 🔲 Pho	tograph Record	☐ Other:				
DPR 523A (1/95) I	HRG						

#! H Primary # **DEPARTMENT OF PARKS AND RECREATION** State of California -- The Resources Agency

PRIMARY RECORD

IsimoniaT

EX9	MRHP Status Code	
	THIOTHER	

Date	Reviewer	Peview Code
		Other Listings

Resource Name or #: Broadway Theater and Commercial District

Page I of I

a. County Los Angeles P2. Location: 🗆 Not for Publication 🖼 Unrestricted P1. Other Identifier:

T; R; 1, of 1, of Sec; Date b. USGS 7.5' Quad and (P2b and P2C or P2d. Attach a Location Map as necessary.)

NW d. UTM: Zone; mE/ c. Address 730 S BROADWAY City Los Angeles Zip 90014

e. Other Locational Data:

P3a. Description:

Contemporary, multi-level parking structure of concrete and steel. Several storefronts are located on the first story.

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories/39 Other - Parking Garage

☐ Linear Feature Record

Attachments: \square NONE \square Location Map \square Sketch Map \square Continuation Sheet \square Building, Structure, and Object Record

P5b. Description of Photo:

□ Prehistoric □ Both Sources: Mistoric P6. Date Constructed/Age and

1967 (E) National Register form

nuknown P7. Owner and Address:

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Milling Station Record

☐ Rock Art Record

	11. Report Citation:
THE SOUTH STRONG THE SOUTH STRONG SOUTH STANDARD STRONG SOUTH STANDARD STRONG SOUTH STANDARD SOUTH SOUTH STANDARD SOUTH SOUTH STANDARD SOUTH STANDARD SOUTH STANDARD SOUTH SOUTH STANDARD SOUTH STANDARD SOUTH	
	DRIWENITA OTOTA RAY

□ Other: ☐ Artifact Record ☐ Photograph Record District Record ☐ Archaeological Record

DPR 523A (1/95) HRG

PRIMARY RECOR

Primary # HPI#

	111XIII					
ORD	Trinomial					
	NRHP Status Code	11				
Other Listings	31(1)(1)(1)(1)					

Review Cod

Reviewer

Page I of I

Resource Name or #: Broadway Theater and Commercial District

P1. Other Identifier:

P2. Location: Not for Publication I Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; B.M. c. Address 731 S BROADWAY City Los Angeles Zip 90014

d. UTM: Zone; mE/ mN


e. Other Locational Data:

P3a. Description:

Three-story brick and concrete retail building. The facade has been remodeled to a very low-relief Greek Revival with window openings on the second floor fit with multipane windows. The central window is flanked by fluted panels, and narrow windows to each side are crowned by medallions.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present: Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic ☐ Both ☐ Prehistoric 1913 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	■ NONE	☐ Location Map		Sketch Map		Continuation	Sheet	Building, Structure,	and Object Record
☐ Archaeological	Record	District Recor	ď	☐ Linear F	eatu				Rock Art Record
☐ Artifact Record	☐ Photo	ograph Record		Other:					
DPR 523A (1/95) H	RG								

IsimoninT HKI# Primary #

a. County Los Angeles

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

Reviewer	abo) "
	Listings
KXA aboO sutstS 9HAM	
HIIIOHHIRI	

Resource Name or #: Broadway Theater and Commercial District Review Code Date

and (P2b and P2C or P2d. Attach a Location Map as necessary.) P2. Location: 🗆 Not for Publication 🖼 Unrestricted

Other

c. Address 735 S BROADWAY City Los Angeles Zip 90014 b. USGS 7.5' Quad Date T; R; 1/, of 1/, of Sec;

d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

P1. Other Identifier:

Page I of I

DPR 523A (1/95) HRG

□ Archaeological Record

☐ Artifact Record ☐ Photograph Record

behind the fenestration. Much of the marble trim is missing. Four-story building brick building with 1937 alterations to the facade. Seismic retrofit left most of the window openings bricked up

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

Sources: Mistoric □ Both P6. Date Constructed/Age and

1908 (E) National Register form □ Prehistoric

Historic Resources Group P8. Recorded by: Christy Johnson

P10. Survey Type: Section 106 P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave.

Review

☐ Rock Art Record

☐ Milling Station Record

P11 Report Citation:	
P9. Date Recorded: P10. Survey Type: 5 Review	P10. Survey Type: Section
Historic Resources Gr	P8. Recorded by: Christy J Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028
	P7. Owner and Address:
Sources: Filiatoric Drehistoric	P6. Date Constructed/Age : Sources: ■ Historic □ B Cources: ■ Prehistoric □ Prehistoric □ Prehistoric I908 (E) Mational Register f
Oliwaio so choria sasa	P5b. Description of Photo:

□ Ofher:

☐ Linear Feature Record

Attachments:

| NONE | Location Map | Sketch Map | Continuation Sheet | Building, Structure, and Object Record

District Record


PRIMARY RECORD

Primary #
HRI#
Trinomial
NRHP Status Code ID

		NRHI	P Status Code 1D	
	Other Listings			
	Review Code	Reviewer		Date
Page I of I	Resource Name	or #: Broadway Theate	r and Commercial Distr	ict
P1. Other Identifie				
P2. Location:	Not for Publication 📓 Unrestric	ted a. Cou	inty Los Angeles	
and (P2b and	P2C or P2d. Attach a Location Ma	ap as necessary.)		
b. USGS 7.5'		of 1/4 of Sec; B.M.		
c. Address 73	7-747 S BROADWAY City Let	os Angeles Zip 90014		
d. UTM: Zone	; mE/ mN			
e. Other Locat	ional Data:			
P3a. Description:				
Eight-story concrete base and three floors	frame commercial building with s have been altered, partly with m	a glazed and molded terr irrored glass and partly w	ra cotta facade of plain pie vith brick.	ers and spandrel panels. T

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

1913 (E) National Register Form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	□ NONE	☐ Location Map		Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
☐ Archaeological	Record	District Recor	d	☐ Linear F	eatu	ire Record	Millir	ng S	Station Record	☐ Rock Art Record
☐ Artifact Record	☐ Photo	ograph Record		Other:			_			Thinks []
DPR 523A (1/95) H	RG									

HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

e. Other Locational Data:

ID	NRHP Status Code	
	HIHOHHAI	

				Nm /∃m ;	anoZ :MTU .b	
		1geles Zip 90014	VAY City Los Ar	-748 S BROADV	c. Address 744	
			T; R; 1, of	bate bate	b. USGS 7.5' Q	
		necessary.)	s Location Map as	2C or P2d. Attach	and (P2b and P.	
	y Los Angeles	a. Count	n 🖪 Unrestricted	of for Publication	Location: DNc	.29
				Globe Theater	Other Identifier:	.lq
	nd Commercial District	Broadway Theater a	source Name or #:	Ве	e l of l	bsg
əı	ped	Reviewer		Review C		
	10 M		spriis	Other Lis		
			will a marrie			

P3a. Description:

been obscured, and no entrance to the theater remains. features such as arched windows, comice, and ornamental bands with gargoyles. The first floor has been altered, the mezzanine has Ten-story concrete theater and office building with stone and brick facade by Morgan, Walls & Morgan including many ornamental

P2b. Description of Photo: Building □ Structure □ Object □ Site □ District B Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories/10 Theater

1912 (E) National Register form □ Prehistoric Sources: Mistoric 🗖 Both P6. Date Constructed/Age and

nuknown P7. Owner and Address:

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

		Did Donor Citotion:
1 11 1		
		The Later of the L
Linner TE		
	Company of the state of the sta	
		P5a. Photo or Drawing

	DPR 523A (1/95) HRG
	Artifact Record D Photograph Record D Other:
Feature Record Milling Station Record D Rock Art Reco	☐ Archaeological Record ☐ Linear F
Continuation Sheet 🛮 Building, Structure, and Object Recor	Attachments: NONE

PF

Primary # HRI# Trinomial NRHP Status Code 6X3

RIMARY	RECORD	

Other Listings

Review Code

_____Reviewer_

Page 1 of 1

Resource Name or #: Broadway Theater and Commercial District

P1. Other Identifier:

P2. Location: Not for Publication I Unrestricted

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date

T; R; 1/4 of 1/4 of Sec;

B.M.

c. Address 749 S BROADWAY City Los Angeles Zip 90014

d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

Four-story brick structure with a completely altered facade clad in long, fin-like terra cotta panels within a large enframement.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present:

Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other

P5b. Description of Photo:

P6. Date Constructed/Age and Sources: M Historic

Prehistoric

☐ Both

1912 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	□ NONE	☐ Location Map	☐ Sketch Map	Continuation	Sheet 🗖	Building, Structure,	and Object Record
☐ Archaeological ☐ Artifact Record				eature Record	Milling	Station Record	☐ Rock Art Record
DPR 523A (1/95) H		ograpiiiitooora	Li Other.				

HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

MRHP Status Code ID Trinomial

a. County Los Angeles

	mmercial District	e or #: Broadway Theater and Cor	Resource Name
Date		Reviewer	Review Code
. =			Other Listings

P1. Other Identifier:

Page I of I

and (P2b and P2C or P2d. Attach a Location Map as necessary.) P2. Location: 🗆 Not for Publication 🖼 Unrestricted

b. USGS 7.5' Quad Date

d. UTM: Zone; nTU .b Иш c. Address 750-758 S BROADWAY City Los Angeles Zip 90014

e. Other Locational Data:

P3a. Description:

facades. The first story and mezzanine are altered. Thirteen-story, concrete Beaux Arts commercial building with Ionic columns defining the base, and a heavy cornice terminating the

Building □ Structure □ Object □ Site □ District BElement of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

T; R; 1, of 1, of Sec;

□ Both Sources: Mistoric P6. Date Constructed/Age and

1911 (E) National Register form □ Prehistoric

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

	Report Citation:	l ld
P8. Recorded by: Christy J. Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028 P9. Date Recorded: P10. Survey Type: Section Review		
P7. Owner and Address: unknown		
P6. Date Constructed/Age Sources: ■ Historic □ E Prehistoric □ Prehistoric □ Prehistoric □ Preparer f		
P2b. Description of Photo:	a. Photo or Drawing	Ь2

PIT. Neport Granom.

DPR 523A (1/95) HRG	58								
☐ Artifact Record	D Photo	odusph Record		:nedfC					
☐ Archaeological Recor	Record	District Reco] p.	☐ Linear Fea	fure Record	IIIIM 🗆	is gn	Station Record	□ Rock Art Record
Attachments: 🛘 NO	I NONE	☐ Location Map	□ 2K	ketch Map [and Object Record

State of California -- The Resources Agency DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary # HRI# Trinomial MPHP Status C

N	Other Listings		WITH State	is Code ID	
	Review Code	Reviewer		ec wilcost	Date
Page 1 of 1	Resource Name o	r#: Broadway T	heater and	Commercial Distric	t Military
b. USGS 7.5' Quad	ublication ☑ Unrestricte 2d. Attach a Location Map Date T; R; 1/₄ of BROADWAY (301 W. 87 mN	as necessary.)	B.M. os Angeles	os Angeles Zip 90014	
e. Other Locational Data	r:				

P3a. Description:

Eight-story Classical Revival Beaux Arts commercial building divided by moldings into three sections above a heavy, plain, largely unfenestrated base. The building was desinged by Ernest McConnell, and its terra cotta and brick facade has a giant order of fluted columns, a deep, denticulated cornice, and plain, prominent string courses. The first floor has been altered.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P5a. Photo or Drawing P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic ☐ Both ☐ Prehistoric 1914 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

	_	
P11.	Report	Citation

Attachments:	□ NONE		Location Map		Sketch Map		Continuation	Sheet		Building, Structure	, and Object Record
☐ Archaeological	Record	园	District Reco	rd	☐ Linear F	eatu	ure Record	☐ Mill	ing	Station Record	Rock Art Record
☐ Artifact Record	☐ Phote	ogra	ph Record		Other:			-			Tuelta p
DPR 523A (1/95) H	RG										

Trinomial HBI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

URHP Status Code ID

a. County Los Angeles

toirte	or #: Broadway Theater and Commercial D	Веѕоитсе Иате
Date	Reviewer	Review Code
		Other Listings

P. Other identifier: Tower Theater

and (P2b and P2C or P2d. Attach a Location Map as necessary.) P2. Location: 🗆 Not for Publication 🖼 Unrestricted

c. Address 800-804 S BROADWAY City Los Angeles Zip 90014 b. USGS 7.5' Quad T; R; 1, of 1, of Sec; Date

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

P3a. Description:

Page I of I

including details such as urns, stained-glass window, and a large clock tower on the corner. The first floor has been altered. Four-story theater building by S. Charles Lee with shops on the 8th Street side, in French Renaissance style with a terra cotta facade

P4. Resources Present: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P3b. Resources Attributes: 07 Commercial Building, over 3 stories/10 Theater


□ Prehistoric Sources: Mistoric D Both P6. Date Constructed/Age and

1927 (E) National Register form

пикиоми P7. Owner and Address:

Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106 P9. Date Recorded:



P11. Report Citation:

DPH (36\f) ASS2 A9G

				i Other:	scord \Box	odusph Re	П БРОГ	DAdifact Record
□ Воск Ап Весога	g Station Record	nilliM 🗖	ature Record	☐ Linear Fe	ct Record	intei 🗷 🗷	Record	☐ Archaeological
s, and Object Record	Building, Structure	J teed2 no	Continuatio	2 Sketch Map	on Map [□ Locatio	□ NONE	Attachments:

State of California -- The Resources Agency DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

P3a. Description:


Primary #
HRI#
Trinomial
NRHP Status Code 1D

	Other Listings		
	Review Code	Reviewer	Date
Page I of I	Resource Name	e or #: Broadway Theater and Com	mercial District
P2. Location: and (P2b and F b. USGS 7.5' 0	I-835 S BROADWAY City I	icted a. County Los A	ngeles
e. Other Location	onal Data:		

Five-story concrete department store with terra cotta ornamentation, designed by A. F. Rosenheim in Classical style with a heavy cornice and decorative garlands. The first floor has been altered, and the storefronts are recessed.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P4. Resources Present: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: ☐ Historic ☐ Both ☐ Prehistoric

1906 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

P11.	Report	Citation
------	--------	----------

Attachments:	□ NONE	☐ Location Map		Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
☐ Archaeological	I Record	District Reco	rd	☐ Linear F	eatu	ire Record	Mill	ing :	Station Record	☐ Rock Art Record
Artifact Record	d ☐ Phot	ograph Record		Other:						- Distriction
DPR 523A (1/95) H	IRG									

HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

Trinomial

nitzi	Other		
	ADD III		
		_	

Reviewer	Review Code
	Reviewer

Page I of I

a. County Los Angeles

P2. Location: 🗆 Not for Publication 🖪 Unrestricted

P1. Other Identifier: Singer Building

T; R; 1, of 1, of Sec; b. USGS 7.5' Quad Date and (P2b and P2C or P2d. Attach a Location Map as necessary.)

d. UTM: Zone; mE/ Nm c. Address 806-808 S BROADWAY City Los Angeles Zip 90014

e. Other Locational Data:

P3a. Description:

character-defining feature of the property. facade. The first floor has been altered, but most of the facade remains intact. The glassblock sidewalk in front of the building is a Seven-story concrete structure in a restrained Italian Renaissance style by Meyer & Holler, with a terra cotta and pressed brick

P4. Resources Present: Building 🗖 Structure 🗖 Object 🗖 Site 🗖 District 🖀 Element of District 🗖 Other P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P6. Date Constructed/Age and

□ Prehistoric □ Both Sources: 🖪 Historic

1922 (E) National Register form

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Milling Station Record

☐ Rock Art Record

	Report Citation.	110
P9. Date Recorded: P10. Survey Type: Section Review		
P8. Recorded by: Christy J Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028		- A
P7. Owner and Address: unknown		\ \ !
P6. Date Constructed/Age: Sources: Historic Dehistoric Prehistoric D22 (E) Mational Register f	bad's' 1 	
P5b. Description of Photo:	niws () John	659

□ Ofher:

District Record

☐ Linear Feature Record

Attachments: \square NONE \square Location Map \square Sketch Map \square Continuation Sheet \square Building, Structure, and Object Record

Citation:	Report	. htq

DPR 523A (1/95) HRG

☐ Archaeological Record

Atiliact Record D Photograph Record

State of California -- The Resources Agency DEPARTMENT OF PARKS AND RECREATION


PRIMARY RECORD

P3a. Description:

Primary # HRI# Trinomial NRHP Status Code 1D

	Other Listings		
	Review Code	Reviewer	Date
Page I of I	Resource Name or #:	Broadway Theater and Commercial	District
P1. Other Identifier: Rialto	Theater Publication Unrestricted	a. County Los Angeles	
and (P2b and P2C or	P2d. Attach a Location Map as r	necessary.)	
b. USGS 7.5' Quad c. Address 812 S BRO			
d. UTM: Zone; mE e. Other Locational Da			

Two-story theater building by O. P. Dennis with a stuccoed facade. Some ornamentation remains, but the original triangular pediment has been removed. The first floor has been altered, and there is no longer an entrance to the theater from the street.



P3b. Resources Attributes: 06 Commercial Building, 1-3 stories/10 Theater

P5b. Description of Photo:

P6. Date Constructed/Age and Sources: M Historic ☐ Both ☐ Prehistoric 1917 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

P11. Report Citation	P11.	Report	Cita	tion
----------------------	------	--------	------	------

Attachments:	□ NONE	☐ Location Map		Sketch Map		Continuation	Sheet	Building, Structure	, and Object Record
☐ Archaeologica	I Record	District Recor	rd	☐ Linear F	eatu	re Record	Milling	Station Record	Rock Art Record
☐ Artifact Record	d ☐ Photo	ograph Record		Other:					National Land
DPR 523A (1/95) H	IRG								

HBI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

isen including a colorful terra cotta facade		e commercial building in Spanish Rena ce and arched windows. The base of th	
			P3s. Description:
		nal Data:	e. Other Locatio
			anoZ :MTU .b
		uad Date T; R; ¼, of ¼, -818 S BROADWAY City Los Ang	b. USGS 7.5' Q c. Address 814
		2C or P2d. Attach a Location Map as n	9 bns d29) bns
รอโอฐก.	a. County Los A	ot for Publication 🛭 Unrestricted	P1. Other Identifier: DN: DN:
mercial District	coadway Theater and Com	Resource Name or #: B	Page I of I
Date	Reviewer	Review Code	Date
		Other Listings	
□ sbo	Trinomial NRHP Status C	ECORD	A YAAMIA9
	#INU	NOUNTING THE OWN OWNER	DELVIZIAL OL

P4. Resources Present:

Building

Structure

Object

Object

Other

District

Element of District

Other P3b. Resources Attributes: 07 Commercial Building, over 3 stories

Sources: ■ Historic □ Both P6. Date Constructed/Age and

1923 (E) National Register form

Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106 P9. Date Recorded:

	P9. Date Recorded: P10. Survey Type: Section Review
Historic Ro	P8. Recorded by: Christy Jo Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028
	P7. Owner and Address:
Sonices:	P6. Date Constructed\Age a Sources: ■ Historic □ B □ Prehistoric □ Prehistoric 1923 (E) National Register f
	P5b. Description of Photo:

	DPR 523A (1/95) HRG
Other:	Artifact Record D Photograph Record
t 🔲 Linear Feature Record 🔻 🗖 Milling Station Record 🔻 🗖 Rock Art Record	Archaeological Record
Sketch Map Continuation Sheet Building, Structure, and Object Record	

State of California -- The Resources Agency **DEPARTMENT OF PARKS AND RECREATION**

PRIMARY RECORD

Primary #

DILLOILLATION	HRI#	
)	Trinomial	
	NRHP Status Code	1D
r Listinas		

Page 1 of 1

Resource Name or #: Broadway Theater and Commercial District

P1. Other identifier:

P2. Location:

Not for Publication
Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.)

Review Code ______ Reviewer

T; R; 1/4 of 1/4 of Sec; b. USGS 7.5' Quad Date B.M.

c. Address 820-824 S BROADWAY City Los Angeles Zip 90014


d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

Six-story reinforced concrete building by W. J. Saunders with a glazed brick and terra cotta facade with some ornamentation and a denticulated cornice. The base has been altered.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories ■ Building ¬ Structure ¬ Object ¬ Site ¬ District ■ Element of District ¬ Other P4. Resources Present:



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: M Historic □ Both ☐ Prehistoric 1913 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	□ NONE	☐ Location Map	☐ Sketch Map	☐ Continuation	Sheet 🛮	Building, Structure,	and Object Record
☐ Artifact Record	☐ Photo	■ District Record ograph Record	d Linear I	Feature Record	Milling	Station Record	☐ Rock Art Record
DPR 523A (1/95) H	RG						

HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code 6X3 Trinomial

		Commercial District	Resource Name	
e	Date		Reviewer	Review Code
	38 - SETS			Other Listings

 13:400 1 1 - 440	PG

Page I of 1

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.) P2. Location: 🗆 Not for Publication 🖼 Unrestricted

c. Address 828 S BROADWAY City Los Angeles Zip 90014 T; R; 1, of 36c; b. USGS 7.5' Quad Date B.M.

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

P3a. Description:

One-story cement block commercial building with a small footprint, containing two small storefronts.

P5b. Description of Photo: ■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

P6. Date Constructed/Age and

D Prehistoric Sources: Mistoric □ Both

uwonan P7. Owner and Address:

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

		1
and the second		
# E ▼		
. 9 !! *	GO-BURRITON OTIRRITON OTIRRITON	d To the state of
þе	COUNTY PREPRESE	
# -		11
		Pea Photo or Drawing

									. 98	623A (1/95) H	DPR
					Other:		выр Кесога	togra	□ Бис	tifact Record	1A 🗆
□ Воск Ай Весога	Station Record	BuilliN	ire Record	eatu	☐ Linear F	rd	District Reco			chaeological	
and Object Record	Building, Structure,	□ 1€	Continuation Shee		Sketch Map		Location Map		□ NONE	chments:	sttA

State of California -- The Resources Agency DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary #
HRI#
Trinomial
NRHP Status Code 1D

	Other Listings		
	Review Code	Reviewer	Date
Page 1 of 1	Resource Name or	#: Broadway Theater and Commercial District	
P1. Other Identifier:	Publication a Unrestricted	a. County Los Angeles	
	P2d. Attach a Location Map a	, 5	
	Date T; R; 1/4 of		
	S BROADWAY City Los A		
d. UTM: Zone; m8	E/ mN		
e. Other Locational D	ata:		

P3a. Description:

☐ Archaeological Record


Artifact Record

DPR 523A (1/95) HRG

District Record

☐ Photograph Record

Twelve-story concrete structure in Gothic Revival style by Walker & Eisen. The facade is clad in terra cotta. The first floor has been altered, and the Gothic tracery has been removed from several stories.



Attachments:

NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record

☐ Linear Feature Record

Other:

Rock Art Record

Milling Station Record

HR!# Primary # DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

6X3 aboD sutsts 9HRM Trinomial

a. County Los Angeles

Date	Reviewer	Peview Code
_		Other Listings
	Varia anna anima IIIIII	III III MANALE I LE ME III,

	P1. Other Identifier:
Resource Name or #: Broadway Theater and Commercial District	l îo l agsq

P2. Location: 🗆 Not for Publication 🖼 Unrestricted

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 839-847 S BROADWAY City Los Angeles Zip 90014 b. USGS 7.5' Quad T; R; 1, of 1, of Sec; B.M. Date

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

P3a. Description:

This one-story, flat-roofed commercial building contains a series of storefronts. A tiled fascia spans the length of the facade.

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

Attachments: 🗖 NONE 🗖 Location Map 🗖 Sketch Map 🗖 Continuation Sheet 🗖 Building, Structure, and Object Record

□ Prehistoric □ Both Sources: Mistoric P6. Date Constructed/Age and

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Review P10. Survey Type: Section 106

☐ Rock Art Record

☐ Milling Station Record

				Report Citation:	. hrq
P8. Recorded by: Christy J Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028 P9. Date Recorded: P10. Survey Type: Section Review				(o geometry)	
P7. Owner and Address: unknown	No.		DME F		
P6. Date Constructed/Age: Sources: ■ Historic □ B Conristoric □ Prehistoric					
P2b. Description of Photo:			DU	Photo or Drawig	£29

				0,	311 (30) 1) 4003 444
Office:		by Record	togra	оча 🗆	☐ Artifact Record
☐ Linear Feature Record	brd	District Rec	20	3ecord	☐ Archaeological I

DAH (36/r) ASSS HYG

State of California -- The Resources Agency DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD


Primary # HRI# Trinomial

NRHP Status Code 1D Other Listings Review Code ___ __ Reviewer Date Resource Name or #: Broadway Theater and Commercial District Page 1 of 1 P1. Jther Identifier: Orpheum Theater P2. Location: Not for Publication Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; c. Address 842-848 S BROADWAY City Los Angeles Zip 90014 d. UTM: Zone; mE/ e. Other Locational Data:

P3a. Description:

Thirteen-story concrete theater and office building in Spanish Renaissance Revival style by Schultze & Weaver. Facade of brick and terra cotta includes rows of urns and ornamental bands with brackets. The theater within was designed by G. A. Landsburgh. The base of the building has been altered. A large roof sign for the theater crowns the building.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories/10 Theater P4. Resources Present: Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Description of Photo:

P6. Date Constructed/Age and Sources: Historic □ Both ☐ Prehistoric 1925 (F) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106 Review

Attachments:	■ NONE	□ Location Map	☐ Sketch Map		Continuation	Sheet		Building, Structure,	and Object Record
☐ Archaeological	Record	District Reco	rd Linear F	eatu	re Record	☐ Mill	ing	Station Record	☐ Rock Art Record
☐ Artifact Record	☐ Photo	ograph Record	Other:						A COMPANY
DPR 523A (1/95) H	RG								

HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

Trinomial

a. County Los Angeles

NRHP Status Code ID

Other Listings

Review Code Reviewer

Page I of I

Resource Name or #: Broadway Theater and Commercial District

P2. Location: 🗆 Not for Publication 🖼 Unrestricted P .. Other identifier: Eastern Columbia Building

T; R; 1, of 1, of Sec; and (P2b and P2C or P2d. Attach a Location Map as necessary.)

Date b. USGS 7.5' Quad

c. Address 849 S BROADWAY City Los Angeles Zip 90014

d. UTM: Zone; mE/ NW

e. Other Locational Data:

P3a. Description:

character-defining feature of the property. condition with high integrity, though interior lobby spaces are altered. The terrazzo sidewalk in front of the building is a cotta in turquoise with gold trim. The storefronts have been sensitively altered, and the remainder of the exterior is in good Fourteen-story commercial building in Zig-Zag Moderne style designed by Claude Beelman. The exterior is clad in glazed terra

Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

P6. Date Constructed/Age and

P5b. Description of Photo:

□ Prehistoric □ Both Sources: Mistoric

1930 (E) National Register form

пикломп P7. Owner and Address:

P9. Date Recorded: Hollywood, CA 90028 1728 Whitley Ave. Historic Resources Group P8. Recorded by: Christy Johnson

Keview P10. Survey Type: Section 106

	Report Citation:	.hlq
- The second sec	生	
	j' .	
	Photo or Drawing	e9d

Citation:	Report	.11.


				Ofher:		aph Record	togra	оча 🗆	rtifact Record	$A\square$
☐ Rock Art Record	ng Station Record	IIIIM 🗆	ture Record	☐ Linear Fea	Ld	District Reco	20	Record	rchaeological	$A\square$
re, and Object Record	☐ Building, Structur	19942 n	Continuation	Sketch Map 🗖		Location Map		□ NONE	:stnemdos:	Stite

DPR 523A (1/95) HRG

State of California -- The Resources Agency

Primary #

DEPARTMENT OF PARKS AND RECREATION HRI# Trinomial PRIMARY RECORD NRHP Status Code 1D Other Listings Review Code Reviewer Resource Name or #: Broadway Theater and Commercial District Page 1 of 1 P1. Other identifier: Ninth and Broadway Building P2. Location: Not for Publication Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.) b. USGS 7.5' Quad Date T; R; 1/4 of 1/4 of Sec; c. Address 850-860 S BROADWAY City Los Angeles Zip 90014 d. UTM: Zone; mE/ e. Other Locational Data: P3a. Description: This thirteen-story commercial building, designed by Claude Beelman in the Zig-Zag Moderne style, is clad in tan glazed terra cotta with metal ornamented panels. The exterior has high integrity, and the interior lobby is altered. P3b. Resources Attributes: 07 Commercial Building, over 3 stories ■ Building ☐ Structure ☐ Object ☐ Site ☐ District ■ Element of District ☐ Other P4. Resources Present: P5b. Description of Photo: P5a, Photo or Drawing



P6. Date Constructed/Age and ☐ Both Sources: M Historic □ Prehistoric 1929 (E) National Register form

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028

P9. Date Recorded:

P10. Survey Type: Section 106

Review

P11.	Report	Citation:
------	--------	-----------

Attachments:	□ NONE	☐ Location Map	Sket	ch Map		Continuation	Sheet		Building, Structure,	and Object Record
☐ Archaeological	Record	District Recor	rd 🛮	Linear F	eatu	ire Record	☐ Mill	ing S	Station Record	Rock Art Record
☐ Artifact Record	☐ Photo	ograph Record	□ Oth	ier:						
DPR 523A (1/95) H	RG									

Primary # HRI# IsimoninT

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Trinomial NRHP Status Code 6X3

Other Listings

Review Code ______ Reviewer _____ Date Gommercial District

Page 1 of 1

P1. Other Identifier:

a. County Los Angeles

P2. Location: ☐ Not for Publication 圖 Unrestricted and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1', of 1', of Sec; B.M. c. Address 900-906 S BROADWAY City Los Angeles Zip 90015

Vm \∃m ; Sone ; mTU .b

e. Other Locational Data:

P3a. Description:

This three-story, concrete frame commercial building, located on a corner lot, has been altered. Square in plan and covered by a flat roof with a parapet and surrounding metal railing, the building has similar facades facing Minth Street and Broadway. The ground floor contains retail spaces, and the upper floors contain offices. The top of the parapet and the vertical piers (flush with the facade) which define the three bays of each facade are clad in glazed tile. The facades contain three broad window bays fenestrated with metal-frame windows. The center of each window bay on the second floor has been filled in and tiled over. The horizontal elements which span the areas above and below the windows are nonoriginal stucco with exposed tie rod ends. The building is in fair to good condition, and its integrity is low.

P3b. Resources Attributes: 06 Commercial Building, I-3 stories

P4. Resources Present:

Building

Structure

Object

Object

District

Element of District

Other

P2b. Description of Photo:


P6. Date Constructed/Age and Sources: ■ Historic □ Both □ Prehistoric

Pre-1905 (F) Building Permit

P7. Owner and Address: unknown

P8. Recorded by: Christy Johnson Historic Resources Group 1728 Whitley Ave. Hollywood, CA 90028 P9. Date Recorded:

P10. Survey Type: Section 106 Review



P11. Report Citation:

DPR 523A (1/95) HRG

				Cther:	by Record	Photogra		☐ Artifact Record
☐ Rock Art Record	g Station Record	□ Willin	sature Record	☐ Linear Fe	District Record	п р	Кесог	☐ Archaeological
ture, and Object Record	Building, Struct	on Sheet	□ Continuatio	Zketch Map	ocation Map	NE 🗆	ON 🖾	Attachments:

State of California -- The Resources Agency DEPARTMENT OF PARKS AND RECREATION

CONTINUATION SHEET

Primary # HRI# Trinomial

Page 1 of 1

Resource Name or #: Broadway Theater and Commercial District


Recorded by: Historic Resources Group

Date: 6/15/98

Continuation Mupdate

Blackstone's Department Store (901-911 S. Broadway) was built in 1916-1918 and designed by John Parkinson. It appeared individually eligible for the National Register (3S) in 1983. It is now included within the expanded boundaries of the Broadway Theater and Commercial District. The building is eligible as a contributor to the district as well as individually eligible, and its new status code is 2B2.

1998 photograph



central bays of the second story contain broad windows outlined by multi-paned of its original detailing, but the design is unaltered in the upper levels. The seven bays on the north (Minth St.) elevation. The lower story has been stripped brick and stone, the structure has five bays on its east (Broadway) elevation and commercial building at the southwest corner of Broadway and Minth. original condition: A Classical Revival decorative scheme distinguishes the six story Briefly describe the present physical description of the site or structure and describe any major alterations from its 7a. Architectural style: Classical Revival DESCRIPTION Original use: Commercial :esU 3neserf U.S. Post Office 90014 Ownership is: Public Los Angeles Address: 834 S. Broadway Present Owner: Reinis, Julius & Ruth M. Parcel number: John G. Downey Tract, Block B, Lots 1 & 2, Parcel 2. ros yugejes \$1006 Los Angeles 3. Street or rural address: 901-911 South Broadway Blackstone's Dept. Store; Famous Dept. Store; U.S. Post Office, Metro-Historic name: [politan Station] Common name: United States Post Office, Metropolitan Station **IDENTIFICATION** 0 HISTORIC RESOURCES INVENTORY :MTU THS **HAER** 28AH DEPARTMENT OF PARKS AND RECREATION Ser. No. State of California - The Resources Agency

Briefly describe the present physical description of the site or structure and describe any major alreading to describe the present physical description original condition: A Classical Revival decorative scheme distinguishes the six story commercial building at the southwest corner of Broadway and Winth, Built of brick and stone, the structure has five beyon its east (Broadway) elevation and brick and stone, the structure has five beyon its east (Broadway) elevation and of its original detailing, but the design is unaltered in the upper levels. The central bays on the north (Winth St.) elevation. The lower story has been stripped on the east and north respectively. A denticulated cornice, set over panelled piers and a plain frieze, and punctuated with fluted cornice, set over panelled piers and a plain frieze, and punctuated with fluted cornice, set over panelled piers and a plain frieze, and punctuated with fluted cornice, set over panelled piers and a plain frieze, and punctuated with fluted cornice, set over panelled end bays, wraps the building above the second floor. With the exception of the end bays on the east which respectively. A denticulated cornice, set over panelled end bays on the east which contains single windows. Fluted panels below the third through sixth floors is occupied by three windows. Fluted panels below the third through windows anchor this portion of the composition. Piers, panelled between the building culminates with swagged spandrels above all the sixth story bays, with a counterpoint of paired and trebled brackets upon which the bracketed cornice counters. A row of anteliaes fringes the upper edge of the cornice.

Rests, A row of anteliaes fringes the upper edge of the cornice.

12	1	
Date(s) of enclosed photograph(s)	.21	
Frontage 52 Depth 129		
Approx. property size (in feet)	.11	
Builder Weymouth Crowell	.01	
		SEE ATTACHED PHOTOS
Architect John Parkinson	.6	
Estimated Factual 1916-18		
Construction date:	.8	ereH (s)otoff rbsttA

13.	Condition: ExcellentGood Fair Deterior	ated No longer in existence
	Alterations: To street level frontage.	9200 35 ANI 35
15.	Surroundings: (Check more than one if necessary) Open lan ResidentialIndustrialCommercialX Other:	nd Scattered buildings Densely built-upX
16.	Threats to site: None knownXPrivate development Public Works project Other:	Zoning Vandalism
17.	Is the structure: On its original site? X Moved?	
18.	Related features:None	
int pur lum to edi: 191 \$2, the Met: inte exar cons	chased from John D. Hooker by Arthur H. berman. Mr. Fleming commissioned the promotesign the building. An important local of fice at an estimated cost of \$450,000. 6, and was completed in February, 1918. 500 in 1917 to \$213,150 in 1918. Blackst close of the year 1939. The structure 1 ropolitan Station. Blackstone's is sign egrity, its design by a prominent local ample of commercial architecture in Local ample commercial ample commercial architecture in Local ample commercial ample commercial architecture in Local ample commercial ample commercia	rner of the West Ninth Street and Broadway ne's, a department store. The property was Fleming, a wealthy Pasadena financier and minent Los Angeles architect, John Parkinson, contractor, Weymouth Crowell, constructed the Construction was initiated on December 22, Property improvement values increased from cone's became the Famous Department Store at ater became known as the U.S. Post Office, ificant for its architectural quality and architect, as a stylistic and representative Angeles during this period, and for its
		Locational sketch map (draw and label site and
20.	Main theme of the historic resource: (If more than one is checked, number in order of importance.) Architecture Arts & Leisure Economic/Industrial Exploration/Settlement Government Military Religion Social/Education	surrounding streets, roads, and prominent landmarks): NORTH
21.	Sources (List books, documents, surveys, personal interviews and their dates).	
	SEE BIBLIOGRAPHY	SEE ATTACHED MAP
22.	Date form preparedJanuary. 1983 By (name)Richard Starzak. Leslie Heumann OrganizationHatheway & Associates Address:1633 Westwood B1Ste. 203 CityLos Angeles, CaZip_90024 Phone:(213) 478-1176	
		13

HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code 2D2 Trinomial

	mmercial District	or #: Broadway Theater and Co	Resource Name
Date		Reviewer	Peview Code
			Other Listings

Page 1 of 2

P2. Location: 🗆 Not for Publication 🖼 Unrestricted a. County Los Angeles P. Other ,dentifier: Broadway Leasehold Building

and (P2b and P2C or P2d. Attach a Location Map as necessary.)

c. Address 908-910 S BROADWAY City Los Angeles Zip 90015 T; R; 1/, of 1/, of Sec; Date b. USGS 7.5' Quad

d. UTM: Zone; mE/

e. Other Locational Data:

P3a. Description:

along the top and bottom of each. A metal fire escape is affixed to the central bay. The facade terminates in a gabled parapet wall. each bay has a segmental-arched header. The spandrel panels between are unornamented except for the detail of the string courses grid are each topped by a capitol, above which they curve together to join at the top of the ogee arch. The top window opening of element, which encompasses three bays of wood-frame, mostly fixed sash windows. The faceted colonnettes defining the window cotta. The Gothic Revival style primary facade is defined by a wide ogee arch. The windows are set deep within this arched This seven-story commercial building is constructed of concrete and brick with the primary facade clad in glazed brick and terra

should be changed to 2D2. (3S), the building is eligible as a contributor to the expanded Broadway Theater and Entertainment District and its status code condition. Formerly listed in the State Historic Resources Inventory as appearing individually eligible for the National Register consisting of a grid of horizontally-oriented, metal frame windows. The upper floors are intact. The building is in fair to good The first floor has been altered, and most of it is obscured by signage. The second floor retains well-designed 1930s alterations

Linear Feature Record

■ Building □ Structure □ Object □ Site □ District ■ Element of District □ Other P4. Resources Present: P3b. Resources Attributes: 07 Commercial Building, over 3 stories

1914 (F) Building Permit D Prehistoric Sources: Mistoric D Both P6. Date Constructed/Age and

☐ Rock Art Record

☐ Milling Station Record

🗖 Location Map 🛕 Sketch Map 🛕 Continuation Sheet 🔞 Building, Structure, and Object Record

				Citation:	Pil Report
P10. Survey Type: Section 106 Review	A THE STREET		7		, -"
Hollywood, CA 90028		1111111	- t.		
Historic Resources Group 1728 Whitley Ave.					1
P8. Recorded by: Christy Johnson McAvoy					
P7. Owner and Address:	5-16				1
Prehistoric Prehistoric I914 (F) Building Permit			1		
P6. Date Constructed/Age Sources: Mistoric DE	1000 2010000				1 (1) (1) (1) (1) (1) (1) (1) (1) (1) (1
P5b. Description of Photo:	rii. Humanam mass) leave	painted to	otoda eaa

				500	IH (AD) N	D E33V	au
Ofher:		ph Record	togra	оча 🗆	Record	Adifact	
D Line	prd	District Reco		Record	plogical	Archae	

State of California -- The Resources Agency DEPARTMENT OF PARKS AND RECREATION

Primary # HRI#

BUILDING, STRUCTURE, AND OBJECT RECORD

Page 2 of 2

NRHP Status Code 2D2

Resource Name or #: Broadway Theater and Commercial District

B1. Historic Name: Broadway Leasehold Building

B2. Common Name:

B3. Original Use: offices/retail

B4. Present Use: same

B5. Architectural Style: Gothic Revival

B6. Construction History:

B7. Moved? M No ☐ Yes ☐ Unknown

Date: Original Location:

B8. Related Features:

B9a. Architect:

b. Builder:

B10. Significance: Theme

Area

Period of Significance Property Type Applicable Criteria

This commercial building is eligible for listing in the National Register as a contributor to the Broadway Theater and Commercial Historic District.

Broadway was the principal shopping district of Los Angeles from the turn of the century until the decades following World War II. This building was one of many within the district which exhibited a period revival style (in this case Gothic Revival) adapted to a modern building type, an office building. In addition to the office uses throughout the building, street-level storefronts opening onto the sidewalks contributed to the lively retail atmosphere of the street.

B11. Additional Resource Attributes:

B12. References: National Register of Historic Places Nomination Form, *Broadway Theater and Commercial District*, 1978.

Longstreth, Richard. City Center to Regional Mall: Architecture, the Automobile, and Retailing in Los Angeles, 1920-1950. Boston: MIT Press, 1997.

Los Angeles Department of Building and Safety Records, Historic Building Permits.

B14. Evaluator:

Date of Evaluation:

(This space reserved for official comments.)

S. BROADWAY

908-910

ALLEY

ALLEY

IsimoninT HRI# Primary #

DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

CONTINUATION SHEET

Resource Name or #: Broadway Theater and Commercial District

Page I of

Date:

☐ Continuation ☐ Update

Recorded by: Historic Resources Group

new status code is 2B2. Theater and Commercial District. The building is eligible as a contributor to the district as well as individually eligible, and its determined eligible for the National Register (2S2) in 1983. It is now included within the expanded boundaries of the Broadway The United Artists Theater Building (921-937 S. Broadway) was built in 1927 and designed by Walker and Eisen. It was

1998 photograph

State of California — The Resources Agency DEPARTMENT OF PARKS AND RECREATION

HISTORIC RESOURCES INVENTORY

HABS_	-	_ HAER	Ser. No. NR	******	SHL	Loc
UTM:	A	-		8		200 2002
	C			D		

•	TO THE THE POST OF	C	D
DENTIF 1.	COMMON name: United Artists Thea	tre	
2.	Historic name:United Artists Thes	tre: California Petrol	eum Bldg : Texas Co. Bldg
3.	Street or rural address: 921-933 South B	roadway	
	City Los Angeles	Zip <u>90015</u> Coun	ty_Los Angeles .
4.	Percel number:John G. Downey Trac	Block B Lots 5, 6	27.
5.	Present Owner: Palace Investment Co	Tnc Addr	ress: 8727 W. 3rd St.
	City Los Angeles Zip	90048 Ownership is: Public	Private X
6.	Present Use: Theatre/ Commercial	Original use:Theatre	/ Commercial
ESCRIP	TION	a projekted is	in Concession 28 2022, I
	Architectural style: Art Deco/Neo Goth	lc ·	dought of a fact. Section as
	Briefly describe the present physical description of		a sau maine altaratione from its
	original condition:	are are or su octure and describ	e any major atterations from its
A	remarkable Neo-Gothic variation	of the Art Deco style	. the United Arrists
Bu	ilding is a thirteen story theater	retail and office	structure. Extensive
Go	thic-inspired terracotta ornamenta	tion characterizes t	he eleven bay concrete
bu	ilding. The three south bays of	the three story have	of the huilding are
	cupied by the theatre entrance.		
	debred by the theatre entrance.	un immense ogee arch s	urmounted by a pinnacie
WE	ich rises through the fourth floo	or dominates the upper	floors of the theatre
er	try. Emphasized by decorative s	moldings, the arch c	ontains tracery which
di	vides the glazed surface into f	ive pointed-erch wi	ndows. Blind tracery
en	bellishes the wall surface around	the arch. An Art	Deco-inspired marquee
sh	ades the ground level entrance, w	hich has been altered	The office building
Q1	trance, marked by an ornamented	anthic arch is in t	he center how of the
6.	ands A section leads setable sec	gothic arth, is in t	ne center bey of the
	cade. A particularly notable scr		
Al	tered storefronts occupy the remai	ning ground level bay	s. A decorative metal
	ill, carried on attenuated metal co		
st	ory bays contain quadripartite w	rindows within ogee	and segmented arches.
(s	ee continuation sheet)		
			8
	Attach Photo(s) Here		Construction date:
	Armen Lugiolal Lists	8.	
			Estimated Factual
		9.	Architect Walker & Fisen
	ATT 1 1000 1 ATT 1	. 1	
	SEE ATTACHED PHOTOS		
		10.	Builder
			Scofield Engineering Co.
			The state of the s
		11.	Approx. property size (in feet)
	2		Frontage 150 Depth 150
			or approx. acreage
		12.	Date(s) of enclosed photograph(s)
			April 1983
		1	AVI 12 1700

4	Phone: (213) 478-1176
5 0	City Los Angeles, Ca. Zip 90024
	Address: 1633 Westwood BI., Ste. 203
*	Organization Hatheway & Associates
	8y (name) Richard Starzak, Lealie Heumann
Pro-	22. Date form prepared January, 1983
ANT TOURS AND DESIGN	
	** *****
THE ATTION THE PAGE	
SEE ATTACHED MAP	SEE BIBLIOGRAPHY
×-	snd their dates).
Accept 10 - 100 1 - 100 1	21. Sources (List books, documents, surveys, personal interviews
the a supplier has substitute	Religion Social/Education
The second of th	Government Military
Carl Charles on experience to page 1911	Emonomic/Industrial 3 Exploration/Settlement Emonomic/Industrial 3 Exploration/Settlement
great a sel Enjurante popular enc. i Angres	Architecture 1 Arts & Leisure 2
77	checked, number in order of importance.)
HTRON A	20. Main theme of the historic resource: (If more than one is
surrounding streets, roads, and prominent landmarks):	S - Chall A. Cables C. Lett. med the Commontal
Locational sketch map (draw and label site and	
halding is located at the west side of the Millians is located at the west side of the Millians of School of Property of School of School of Crane of Cra	SIGNIFICANCE Steely seas historical and/or architectural importance (included by the United Artists Theattre-California Petroleum Broadway, approximately 200 to 350 feet sout attructure was designed by the prominent Los N Elsen. Construction was begun on March 21, 1927, on December 26, 1927, The Scotield Engineer estimated cost of \$1,300,000, which eventually improvement values increased from \$370 in 1927, of the fine the eventually stand development of the City of Los Angeles. Petroleum Building is furthur significant for it design by a prominent architectural firm, ce stylistic and representative example of commercinatively. It is related in building function, period.
	18 Related features: None
Unknown?	7. Is the structure: On its original site? X oved?
	Public Works project Other:
meilsbns; ninoZ	16. Threats to site: None known XPrivate development
	Residentisi Industrial Commercial X Other:
Scarrered buildings Densely built-up A	15. Surroundings: (Check more than one if necessary) Open land

14. Alterations: Street level frontage.

13. Condition: Excellent Good X Fair Deteriorated No longer in existence

:4

171

(Continuation Sheet)

7b.

Corbels and keystones in the form of heads accent the segmented arches in the first and fifth bays, while the ogee arches of the other bays are miniature versions of the theatre frontispiece. The third story bays also alternate decorated arches, hightlighted by Gothic niches filled with statuary at the bases of the piers. A simplification in the decorative pattern marks the shaft of the office building, beginning at the fourth floor. Piers and mullions rise uninterruupted through the parapet, delineating bays of two windows separated between levels by bossed spandrels. Tracery creates a band of Gothic arches above the eleventh story windows, punctuated at the fourth bay from either end by windows with Gothic-arched heads. The same bays, which frame the central bank of three bays, are set back on the twelfth and thirteenth floors. Windows shaped in ogee arches capped by spandrels in high relief cap the building on the thirteenth floor. Culminating the verticality of the design, a tower, consisting of open Gothic tracery, rises in two setbacks above the central three bays and is crowned with a pinnacle.

The strong Art Deco statement of the United Artists building is reinforced by its mostly unaltered design, and by its proximity to other landmark buildings in the same style, especially the Eastern Columbia Building half a block away. Its tower has become a recognizable symbol in the Los Angeles skyline.



Primary # HRI# Trinomial

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

CONTINUATION SHEET

Resource Name or #: Broadway Theater and Commercial District

Page I of I


□ Continuation 🖪 Update

Date: 6/15/98

Recorded by: Historic Resources Group

The former Western Costume Building (939-947 S. Broadway) was built in 1924-1925 and designed by Kenneth MacDonald Jr. and Co. It appeared individually eligible for the National Register (3S) in 1983. It is now included within the expanded boundaries of the Broadway Theater and Commercial District. The building is eligible as a contributor to the district as well as individually eligible, and its new status code is 2B2.

1998 photograph



State of California — The Resources Agency DEPARTMENT OF PARKS AND RECREATION

			Ser. No.			
HABS_		HAER	NR		SHL	Loc
UTM:				В		
	C.			D		

21

HISTORIC RESOURCES INVENTORY	C D
IDENTIFICATION 1. Common name: Anjac Fashion Building	
2. Historic name: Western Costume Building;	939 S. Broadway Bldg.
3. Street or rural address: 939-947 South Broadway	У
City Los Angeles Zin S	90015 County Los Angeles
4. Parcel number: John G. Downey Tract, Bloc	
5. Present Owner: Needleman, Jack and Annets	
	Ownership is: Public Private X
6. Present Use: Commercial Offices Ori	
Building, 939 South Broadway is an eleven store Renaissance Revival style. However, a two soverlaid on the northernmost of the five been emphasized by a chevron molding and a fluted staper into triangles embellished with scrolled one story door, the four round-headed windows window. The remaining bays of the two story ground level and three windows, separated by Panelled piers, edged by spiralled moldings do of the first floor frieze by shields. A second terminates the base of the building. The shifloors and is faced with brown brick. No fenestration until a decorative frieze above the building is two stories high and define terracotta spandrels between sotries. Styl decorative frieze, fringed with antefixes, culm	the exuberantly Neo-Gothic United Artists bry commercial structure in the more typical story Gothic-inspired Art Deco entrance is ays of the facade. A segmented archway, spandrel, is flanked by fluted piers which designs. Elaborate metalwork frames the in the transom, and the arched second story base contain altered storefronts on the colonnette mullions, on the second story. Efine the bays and are accented at the level of frieze, topped by a cornice and antefixes, aft is composed of the third through ninth extraneous ornamentation interrupts the che ninth storyis reached. The capital of ed by continuous piers and mullions with dized Ionic capitals crown the piers. A minates the design.
Attach Photo(s) Here	8. Construction date: Estimated Factual
SEE ATTACHED PHOTOS	9. Architect Kenneth MacDonald Jr. & Co. 10. Builder MacDonald & Kahn
Street of a management of page 12.	11. Approx. property size (in feet) Frontage 100 Depth 159 or approx. acreage
Name and the management of the second of the	12. Date(s) of enclosed photograph(s) April 1983

E891 IFIGA Date(s) of enclosed photograph(s) or approx. acreage_ Frontage 100 651 A3G9G _ Approx. property size (in feet) .11. MacDonald & Kahn 10. SEE ATTACHED PHOTOS Kenneth MacDonald Jr. & Co. nosidanA .6 Factual 1924-25 _batemite3 Construction date: Attach Photo(s) Here decorative frieze, fringed with antefixes, culminates the design. Stylized Ionic capitals crown the piers. A terracotta spandrels between sotries. the building is two stories high and defined by continuous piers and mullions with The capital of fenestration until a decorative frieze above the ninth storyis reached. No extraneous ornamentation interrupts the floors and is faced with brown brick. The shaft is composed of the third through minth terminates the base of the building. of the first floor frieze by shields. A second frieze, topped by a cornice and antefixes, Panelled piers, edged by spiralled moldings define the bays and are accented at the level ground level and three windows, separated by colonnette mullions, on the second story. The remaining bays of the two story base contain altered storefronts on the one story door, the four round-headed windows in the transom, and the arched second story Elaborate metalwork frames the taper into triangles embellished with scrolled designs. emphasized by a chevron molding and a fluted spandrel, is flanked by fluted piers which A segmented archway, overlaid on the northernmost of the five bays of the facade. However, a two story Gothic-inspired Art Deco entrance is Renaissance Revival style. 939 South Broadway is an eleven story commercial structure in the more typical , gaibliud Located adjacent to the exuberantly Neo-Gothic United Artists original condition: 7b. Briefly describe the present physical description of the site or structure and describe any major alterations from its 7a. Architectural style: Renaissance Revival DESCRIPTION Original use: Commercial/Offices Present Use: Commercial Offices Zip 90014 Ownership is: Public LOS Angeles Address: 819 Santee Street Weedleman, Jack and Annette Present Owner: John G. Downey Tract, Block B, Lots 8 & 9, Parcel 6. Parcel number: County Los Angeles SIOO6 diz Los Angeles 939-947 South Broadway Street or rural address: Western Costume Building; 939 S. Broadway Bldg. Historic name: 1. Common name: .1 Anjac Fashion Building **IDENTIFICATION** HISTORIC RESOURCES INVENTORY :MTU THS HN HAER SAAH DEPARTMENT OF PARKS AND RECREATION

State of California - The Resources Agency

Ser. No.

21

13. Condition: ExcellentGoodY Fair Deterior	rated No longer in existence
14. Alterations: Minor to street level frontage	
15. Surroundings: (Check more than one if necessary) Open la ResidentialIndustrialCommercialX Other:	ndScattered buildings Densely built-upX
Threats to site: None known Private development Public Works project Other:	Zoning Vandalism
17. Is the structure: On its original site? Moved?	Unknown?
18. Related features:None	
The old Western Costume Building is located north of the West Olympic Boulevard intersect of the Ninth and Broadway Company. The MacDonald, Jr., was commissioned to design March 29, 1924, and completed by January, MacDonald & Kahn executed the construction frimprovement values increased from no value 1925. The structure has subsequently been is and is currently identified as the Anjac Fawestern Costume Building is significant for design by a prominent local architect, as commercial architecture in Los Angeles during scale, style, and period with neighboring contributing to a unique sense of time and plant	on the westside of Broadway, 130 to 230 feet ion. The structure was built at the request prominent Los Angeles architect, Kennet the building. Construction was initiated of 1925. The notable local contracting firm of or an estimated cost of \$375,000. Propert in 1924 to an assessed value of \$190,000 is dentified as the 939 South Broadway Building ashion Building at this address. The old its architectural integrity and quality, its a stylistic and representative example of this period, and for its consistency in the Contral Business in the Contral Business.
20. Main theme of the historic resource: (If more than one is checked, number in order of importance.) Architecture	Locational sketch map (draw and label site and surrounding streets, roads, and prominent landmarks):
Religion Social/Education	
 Sources (List books, documents, surveys, personal interviews and their dates). 	
SEE BIBLIOGRAPHY	SEE ATTACHED MAP
22. Date form prepared	
,	22
There is not proposed at the second of the file	I SUS publicas a real basin per amendana
the section of the se	

Primary # HRI# Trinomis1

State of California -- The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

HRI# Trinomial NRHP Status Code 6Y2

Date	Reviewer	9boD weive/
		Other Listings
44.5		

Resource Name or #: Broadway Streetscape Improvement Project	[10 [
2000 42421	

F1. Other Identifier:

Page

P2. Location: ☐ Not for Publication 圖 Unrestricted a. County Los Angeles and (P2b and P2C or P2d. Attach a Location Map as necessary.)

b. USGS 7.5' Quad Date T; R; 1/, of 1/, of Sec; B.M.

c. Address 950 S BROADWAY City Los Angeles Zip 90015

Mm \ampli Tone ; mE\ and children

e. Other Locational Data:

P3a. Description:

DPR 523A (1/95) HRG

☐ Archaeological Record

☐ Artifact Record ☐ Photograph Record

This seven-story commercial building has been entirely altered, with new windows and primary facade completely replacing the original appearance. The building is in good condition.

P3b. Resources Attributes: 07 Commercial Building, over 3 stories

Building

Structure

Object

District

Element of District

Other

P5b. Description of Photo:

P6. Date Constructed\Age and Sources: ■ Historic □ Both □ Prehistoric

P7. Owner and Address: unknown

P8. Recorded by:
Christy Johnson McAvoy
Historic Resources Group
1728 Whitley Ave.
Hollywood, CA 90028

P9. Date Recorded: 6/1/98 P10. Survey Type: Section 106 Review

D Milling Station Record

☐ Rock Art Record

			Report Citation:	P11. I
	30007		ONL I	N X
marks.			CLUB LAS PAL LAS Dancing	
			4.	5

□ Ofher:

☐ Linear Feature Record

Attachments: MONE Decation Map Sketch Map Decord Continuation Sheet Deciding, Structure, and Object Record

District Record

State of California -- The Resources Agency DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary # HRI# Trinomial NRHP Status Code 6Y2

	Other Listings Review Code	Reviewer	Date
Page I of I	Resource Name or #:	Broadway Streetscape Improvement Project	
and (P2b and P2C or b. USGS 7.5' Quad	S BROADWAY City Los An E/ mN	√ of Sec ; B.M.	

P3a. Description:

☐ Archaeological Record

☐ Artifact Record


DPR 523A (1/95) HRG

□ District Record

☐ Photograph Record

Other:

This is a two-story commercial building with retail storefronts on the ground floor and offices on the second story. The first story has been completely altered, and half of the second floor windows have been filled in.



Attachments: 🖪 NONE 🗆 Location Map 🗖 Sketch Map 🗖 Continuation Sheet 🗖 Building, Structure, and Object Record ☐ Linear Feature Record

Milling Station Record

Rock Art Record

HRI# Primary # DEPARTMENT OF PARKS AND RECREATION State of California -- The Resources Agency

PRIMARY RECORD

NRHP Status Code 6Y2 Trinomial

	_		-
tings	SiJ	her	0
			-

eview Code	Reviewer	Date
of uncorning	111111111111111111111111111111111111111	- Cypotin
r Listings		- Chain

P1. Other Identifier:

Page I of I

a. County Los Angeles

and (P2b and P2C or P2d. Attach a Location Map as necessary.) P2. Location: 🗖 Not for Publication 🖪 Unrestricted

c. Address 990 S BROADWAY City Los Angeles Zip 90015 T; R; 1, of 1, of Sec; b. USGS 7.5' Quad Date .M.8

d. UTM: Zone; mE/ Nm

e. Other Locational Data:

P3a. Description:

through the windows. of brick and has a flat roof with a parapet and large, metal frame display windows. Earthquake retrofit cross-bracing is visible This one story commercial building is heavily altered. Located at the corner of Olympic and Broadway, the building is constructed

P3b. Resources Attributes: 06 Commercial Building, 1-3 stories

P5b. Description of Photo:

■ Building □ Structure □ Object □ Site □ District □ Element of District □ Other

P4. Resources Present:

□ Prehistoric □ Both Sources: Mistoric P6. Date Constructed/Age and

nuknown P7. Owner and Address:

1728 Whitley Ave., Hollywood Historic Resources Group Christy Johnson McAvoy P8. Recorded by:

Section 106 Review P10. Survey Type: P9. Date Recorded: 6/1/98

STATE STATE OF THE	highlight with a subjection to	Property of the property of th	en by kep at en de troud	
		and the second		
	·			L.
三年二			L 1	
· · · · · · · · · · · · · · · · · · ·				
· · · · · · · · · · · · · · · · · · ·			Tied ()	
. eestaan P ^r	1 11 1000	022		
。 ₁₈₆ "自然对理社会还是详	THE WAR TO SEE	18日		
STREET, SALES OF STREET		(11 (a) (7) ()		
	NOV	716		
7	7 1 1 1	111		
1		2		
		7	22	

P11. Report Citation: None.

							5	RH (36\f) AESS A90
				per:	10 0	by Record	☐ Photogra	☐ Artifact Record
☐ Rock Art Record	Station Record	gnilliN	ure Record	Linear Featu	J. 1	District Record	Secord	☐ Archaeological F
and Object Record	Building, Structure,	□ 1e	Continuation Shee	tch Map 🗖	□ SK€	Location Map	■ NONE □	Attachments: g

APPENDIX C

Field Notes and Recommendations

...

MOL SITE WAS MEDIUM

0.6000000

	Appen	ndix C: FIELD	Appendix C: FIELD NOTES AND RECOMMENDATIONS	ONS
ADDRESS	BLDG STATUS	MATERIAL	DESCRIPTION	RECOMMENDATION
214 S. Broadway	Not in District	Тетгаzzo	Pink and gold terrazzo on sidewalk in front of parking lot.	May be removed.
214 S. Broadway	Not in District	Brass Plaque	Inscription describes history of first site of B'nai B'rith Temple.	Remove during construction and incorporate into new sidewalk.
235 S. Broadway	Not in District	Terrazzo	Green terrazzo with black band in foyer.	Protect during construction.
237-41 S. Broadway	Not in District	Marble	Rectangular pieces. White with a green border. Begins in the entrance and extends a few feet into sidewalk.	Protect marble in building entrances during construction. Marble on sidewalk may be removed as it appears that the pink has been used to replace the original white. No documentation required.
237-41 S. Broadway	Not in District	Steel Basement Doors	One hatch with two doors which appear to be original, but in poor condition.	May be removed. No documentation required.
242 S. Broadway (aka 240)	Contributing	Steel Basement Doors	One hatch with two doors.	May be removed. No documentation required.
242 S. Broadway	Contributing	Ceramic Tile	Tiled entryway.	Protect during construction.
249-59 S. Broadway	Contributing	Ceramic Tile	Tiled entryway with the words "Frank."	Protect during construction.
300-10 S. Broadway	Contributing	Steel Basement Door	Two hatches with two doors which appear to be original and in fair condition.	May be removed after it has been documented.
300-10 S. Broadway	Contributing	Glass Blocks	Clear square blocks in rectangular panels.	May be removed after it has been documented.
300-10 S. Broadway	Contributing	Ceramic Tile and Granite	Tiled entryway and granite step.	Protect during construction.

	Appen	dix C: FIELD	Appendix C: FIELD NOTES AND RECOMMENDATION	TIONS
315 S. Broadway	Contributing	Теггаzzo	Gold, white, and dark red square pattern. Begins in the entrance and extends approximately one and one-half feet into sidewalk.	Protect during construction and retain in place.
328-30 S. Broadway	Noncontributing	Steel Basement Door	One hatch with two doors.	May be removed. No documentation required.
340-44 S. Broadway	Contributing	Terrazzo	Terrazzo entryways in storefronts of 340 and 342.	Protect during construction.
341-45 S. Broadway	Noncontributing	Terrazzo	Gray, white, and black marble chips. Begins in the entrance and extends five feet into sidewalk.	Protect during construction and retain in place.
346-48 S. Broadway	Noncontributing	Ceramic Tile	White ceramic tile panel with black numbers "348."	Protect during construction and retain in place.
350-54 S. Broadway	Noncontributing	Steel Plate	Fixed steel plate.	May be removed. No documentation required.
351-53 S. Broadway	Noncontributing	Terrazzo	Buff terrazzo in entryway.	Protect during construction.
351-53 S. Broadway	Noncontributing	Steel Basement Door	One hatch with two doors.	May be removed. No documentation required.
400-22 S. Broadway	Noncontributing	Ceramic Tile	Multicolored square tiles in contemporary pattern on background of brown square tiles.	May be removed. No documentation required.
401-23 S. Broadway	Contributing	Concrete	Concrete stained green and scored with a square grid on a forty-five degree angle.	May be removed. No documentation required.

	THE CONTRACT OF THE PROPERTY O			
424 S. Broadway Coi	Contributing	Ceramic Tile	Two ceramic tile panels, white with black trim and letters which read "JUDSON RIVES BUILDING 424." A portion of one panel has been removed.	May be removed after it has been documented. Incorporate into new sidewalk if possible.
425-29 S. Broadway No	Noncontributing	Steel Basement Door	One hatch with four doors which do not appear to be original.	Retain in place at the owner's request.
425-29 S. Broadway No.	Noncontributing	Terrazzo	Terrazzo entryway.	Protect during construction.
451-57 S. Broadway Cor	Contributing	Steel Basement Door	Two hatches with two doors which do not appear to be original.	May be removed. No documentation required.
452-60 S. Broadway Co.	Contributing	Brass Band and Plaque	Brass plaque, which reads "J. McNeill Co. Contractor," and property line marker.	Property line marker may be removed and replaced in kind. Plaque should be removed during construction and incorporated into new sidewalk.
500-08 S. Broadway Co	Contributing	Glass Block	Squares within squares which span the full-length of the building.	Protect during construction and retain in place.
500-08 S. Broadway Co.	Contributing	Terrazzo	Green terrazzo foyer at 506 ½ and black, gray, and green terrazzo foyer at 508.	Protect during construction and retain in place.
501-15 S. Broadway Col	Contributing	Terrazzo	Terrazzo entryway.	Protect during construction.
501-15 S. Broadway Co.	Contributing	Steel Basement Door	Two hatches with three doors which do not appear to be original.	May be removed. No documentation required.
510-512 S. Broadway Co.	Contributing	Steel Basement Door	One hatch with two doors which do not appear to be original.	May be removed. No documentation required.
517-19 S. Broadway Co	Contributing	Теггаzzo	White, gray, and brown arc-shaped. Begins in store entrance and extends into sidewalk approximately three feet.	Protect during construction and retain in place.

	Apper	ndix C: FIELL	Appendix C: FIELD NOTES AND RECOMMENDATIONS	ONS
516-22 S. Broadway (aka 518)	Contributing	Теггаzzo	Abstract geometric pattern of red, yellow, brown, and black terrazzo. Pattern spans full-length of facade and extends to the curb. Band along curb has been replaced with concrete.	Protect during construction. Retain in place.
516-22 S. Broadway (aka 522)	Contributing	Теггаzzo	Terrazzo foyer.	Protect during construction.
523-25 S. Broadway	Noncontributing	Теггаzzo	Long rectangle of yellow and gold one foot wide in storefront.	Protect during construction and retain in place.
533 S. Broadway	Contributing	Terrazzo	Abstract geometric pattern in green, yellow, red, gray, and black. Pattern spans the full-length of the facade and extends to approximately eight inches from curb. A water meter is located along the curb	Protect during construction. Retain in place. Leave water meter in place. Concrete strip between terrazzo and curb should be replaced with the concrete specified for the sidewalks.
			arong the euro.	
534 S. Broadway	Contributing	Terrazzo	Abstract stylized pattern in green, yellow, red, and white. Intricate semicircular pattern fans out from building facade. The remainder of the terrazzo is white and extends to the curb. The white terrazzo between the semicircle and the curb has been damaged by three water meter plates and a tree well.	The ideal approach would be to retain the semicircle in place, relocate the water meters and restore all of the white terrazzo. The alternative approach would be to remove the terrazzo in straight line between the curb and the semicircle and replace it with the specified concrete for the sidewalks.
537-41 S. Broadway	Contributing	Concrete	Green stained concrete with a square grid on a forty-five degree angle.	May be removed. No documentation required.
537-41 S. Broadway	Contributing	Brass	Brass property line marker.	May be removed. No documentation required.

	Apper	idix C: FIELD	Appendix C: FIELD NOTES AND RECOMMENDATIONS	ONS
553 S. Broadway	Contributing	Terrazzo	Buff, black, and white diagonal squares in entryway of City Blues.	Protect during construction.
540 S. Broadway	Contributing	Terrazzo	Address in sidewalk at 536 and terrazzo in entryway at 540.	Protect during construction and retain in place.
548 S. Broadway	Contributing	Concrete	Red stained concrete scored with a square grid on a forty-five degree angle.	May be removed. No documentation required.
548 S. Broadway	Contributing	Steel Basement Door	One hatch with two doors which do not appear to be original.	May be removed. No documentation required.
548 S. Broadway	Contributing	Terrazzo	Terrazzo foyers to storefronts.	Protect during construction.
553 S. Broadway	Contributing	Concrete	Square grid.	May be removed. No documentation required.
555-59 S. Broadway	Contributing	Terrazzo	Tan with green strip in entryway of "Howard's".	Protect during construction.
555-59 S. Broadway	Contributing	Steel Basement Door	One hatch with two doors at 555.	May be removed. No documentation required.
601-05 S. Broadway	Contributing	Terrazzo	Gold and green rectangular checkerboard which wraps both street-facing facades and extends from the edge of the building to the curb.	Protect during construction and retain in place. Terrazzo may be removed to accommodate street lights and tree wells, as long as it occurs within the pattern. Pieces of the checkerboard which were previously damaged by public works
601-05 S. Broadway	Contributing	Marble	Marble entryways at 603 and 605.	Protect during construction.

Starting to be sudway | Continuing

	Apper	dix C: FIELD	Appendix C: FIELD NOTES AND RECOMMENDATION	TIONS
609-11 S. Broadway	Contributing	Terrazzo	Red and black semicircular pattern spanning two storefronts. Extends approximately four feet into sidewalk.	Protect during construction and retain in place.
612-16 S. Broadway	Contributing	Limestone	Rectangles which span the full-length of the facade and extend to curb.	May be removed. No documentation required.
609-19 S. Broadway	Contributing	Terrazzo	Highly intricate stylized pattern with abstracted fleur-de-lis motif in red, yellow, green, black, and brown. Terrazzo pattern begins in theater foyer and extends to the curb.	Protect during construction and retain in place.
609-19 S. Broadway	Contributing	Terrazzo	Pink with white script in entryway.	Protect during construction.
609-19 S. Broadway	Contributing	Marble	Marble dado in entryway of 619.	Protect during construction.
626-36 S. Broadway	Contributing	Glass Block	Squares, purple-tinted glass blocks within squares panels.	Protect during construction and retain in place.
644 S. Broadway	Contributing	Terrazzo	Dark gray rectangular panels which extend from building facade into the sidewalk for thirteen and one-half feet.	May be removed if located on top of a basement. Otherwise protect during construction and retain in place.
648 S. Broadway	Contributing	Теггаzzo	Stylized abstracted pattern with pictorial scenes from California including City	Protect during construction and retain in place.
0.00		7	Hall, cacti, musician, and sail boat. Terrazzo pattern spans the full-length of the facade and extends from the foyer to the curb.	Against the second of the seco
639-57 S. Broadway	Contributing	Ceramic Tile	Multicolored square tiles in contemporary pattern on background of brown square tiles.	May be removed. No documentation required.

	Арреп	dix C: FIELD	Appendix C: FIELD NOTES AND RECOMMENDATIONS	ONS
701-17 S. Broadway	Contributing	Steel Basement Door	One hatch with two panels which do not appear to be original.	May be removed. No docume_tation required.
701-17 S. Broadway	Contributing	Terrazzo	Gold entryway to 701 and 709.	Protect during construction.
701-17 S. Broadway	Contributing	Marble	Theater foyer and main entryway to United Building at 707.	Protect during construction.
710 S. Broadway (aka 712)	Contributing	Steel Basement Door	One hatch with two doors.	May be removed. No documentation required.
714-20 S. Broadway	Contributing	Terrazzo	Green, yellow, and gray geometric pattern which spans a single storefront at 714 and extends from the facade into the sidewalk for four feet.	Protect during construction and retain in place.
714-20 S. Broadway	Contributing	Terrazzo	Gray rectangular pieces which spans a single storefront at 716 and extends from the facade into the sidewalk for four feet.	Protect during construction and retain in place.
714-20 S. Broadway	Contributing	Теггаzzo	Diamond pattern in green, light yellow, and dark green. Terrazzo pattern spans two storefronts at 718-20 and extends from the facade to the curb.	Protect during construction and retain in place.
719 S. Broadway	Contributing	Теггаzzo	Beige in abstract geometric pattern which begins in the entrance and extends into the sidewalk for five feet. Reads Hudson's at both ends.	Protect during construction and retain in place.
731 S. Broadway	Contributing	Теггаzzo	Terrazzo foyers.	Protect during construction and retain in place.
735 S. Broadway	Noncontributing	Terrazzo	White with green border begins in foyer and extends four feet into the sidewalk.	Protect during construction and retain in place.

	Apper	dix C: FIELD	Appendix C: FIELD NOTES AND RECOMMENDATION	TIONS
744-48 S. Broadway	Contributing	Теггаzzо	Long narrow piece of light green terrazzo which begins at the facade and extends one foot into the sidewalk.	Protect during construction and retain in place.
744-48 S. Broadway	Contributing	Теггаzzo	Two squares of gold terrazzo at 748B.	May be removed. No documentation required.
749 S. Broadway	Noncontributing	Теггаzzo	Gold and black terrazzo foyer.	Protect during construction and retain in place.
749 S. Broadway	Noncontributing	Concrete Basement Door	One hatch.	May be removed. No documentation required.
750-58 S. Broadway	Contributing	Terrazzo	Long narrow green terrazzo strip which wraps around the building onto 8th Street.	Protect during construction and retain in place.
757-61 S. Broadway	Contributing	Terrazzo	Grey, green, and yellow abstract geometric pattern which spans a storefront and extends from the facade to the curb.	Terrazzo along the curb has been removed or is otherwise damaged. The remaining may be removed to accommodate curb work, and may be replaced with the concrete specified for the sidewalks. The cut must follow the pattern and the remaining terrazzo should be protected during construction and retained in place.
757-61 S. Broadway	Contributing	Marble	Rectangular panels of white marble which extend from the facade to the curb and wraps around the building onto 8th Street.	May be removed. No documentation required.
800-04 S. Broadway	Contributing	Terrazzo	Dark red rectangles and squares which begins in the foyer and extends into the sidewalk for three and one-half feet.	Protect during construction and retain in place.

$\overline{}$			Γ	I		<u> </u>	Т		· ·
SNC	Protect during construction and retain in place.	Protect during construction and retain in place.	May be removed. No documentation required.	Protect during construction and retain in place.	Protect during construction and retain in place. Band of terrazzo along the curb may be removed to accommodate curb work, but must be replaced in kind.	Protect during construction and retain in place.	Protect during construction.	May be removed. No documentation required.	Terrazzo on sidewalk may be removed as it has been damaged. Terrazzo in entrance should be protected during construction and retain in place.
Appendix C: FIELD NOTES AND RECOMMENDATIONS	Clear glass block squares within squares panels.	Terrazzo in foyer.	Square grid on a forty-five degree angle.	Pink marble with lettering in foyer.	Green and white zig-zag pattern which extends from the foyer to the curb.	Red, green, yellow, black, and gold semicircle beginning in entrance and extending two feet into sidewalk.	Dark red marble in foyer of Orpheum Theater.	Red stained concrete scored in square grid with stripes.	Orange terrazzo begins in two storefronts at 844 and extends into sidewalk. One side reads "Klein" and the other has image of spectacles. Both are rendered in black terrazzo. Irregular to fit storefront
idix C: FIELD	Glass Block	Terrazzo	Concrete	Marble	Теггаzzо	Теггаzzo	Marble	Concrete	Terrazzo
Аррег	Contributing	Contributing	Contributing	Contributing	Contributing	Contributing	Contributing	Contributing	Contributing
	806-08 S. Broadway	806-08 S. Broadway	812 S. Broadway	814-18 S. Broadway	820-24 S. Broadway	830-34 S. Broadway	842-48 S. Broadway	842-48 S. Broadway	842-48 S. Broadway

	Appen	dix C: FIELD	Appendix C: FIELD NOTES AND RECOMMENDATIONS	ONS
842-48 S. Broadway	Contributing	Marble	White marble with red band begins in foyer and continues into the lobby. A white block with black letters which reads "846 So. Broadway." is located on the sidewalk at the edge of the facade.	Protect during construction and retain in place.
842-48 S. Broadway	Contributing	Steel Basement Doors	One hatch with two doors and two fixed steel plates at 842.	May be removed. No documentation required.
842-48 S. Broadway	Contributing	Brass Plaque	Brass plaque in sidewalk which reads "McNeill Contractors."	Plaque should be removed during construction and given to property owner.
839-847 S. Broadway	Noncontributing	Concrete	Red stained concrete scored in rectangular grid.	May be removed. No documentation required.
849 S. Broadway	Contributing	Terrazzo	Abstract geometric pattern in red, yellow, green, and black which begins in the foyer and extends to the curb wrapping the building.	Protect during construction and retain in place. Band of terrazzo along the curb may be removed to accommodate curb work, but must be replaced in kind.
908-10 S. Broadway	Contributing	Terrazzo	Band of white terrazzo extends approximately one and one-half feet from foyer into sidewalk.	Protect during construction at retain in place.
921-37 S. Broadway	Contributing	Concrete	Checkerboard of black and white 18" squares.	May be removed. No documentation required.

APPENDIX D

Broadway Streetscape Design Study

Marin Committee

10.



BROADWAY STREETSCAPE DESIGN STUDY EXECUTIVE SUMMARY FOR COMMUNITY PRESENTATION

(DRAFT FOR STAFF REVIEW) 4/8/96

as an increase where a larger many

Broadway Streetscape Design Study Executive Summary For Community Presentation

Draft for Staff Review 4/6/96

INTRODUCTION

Like all great urban streets, Broadway at once connects us to the City's past while serving the present. This renovation seeks to reinforce Broadway's role as a focus of downtown city life and community by both strengthening its essential infrastructure and enhancing its ability to serve its historic function as a significant transportation and commercial corridor.

In recent decades, Broadway has become a dynamic commercial center for the region's Latino community. It's lively combination of retail stores, cafe's, cinemas and vendors creates the backdrop for a spirited street scene which welcomes all Los Angeles.

Deteriorating sidewalks and street lighting and lack of maintenance have however created a perception of a declining and unsafe environment which has an adverse impact on the retail environment of the street. The purpose of this renovation project is to provide the setting for a welcoming and vibrant Broadway street scene through the provision of new sidewalks, enhanced lighting and pedestrian amenities, enhancing the street's ability to serve its historic function as a significant transportation and commercial corridor.

HISTORIC AND CULTURAL CONTEXT

For over a century, Broadway has been a street where people of Los Angeles have gathered together to partake of and enjoy city life. As the city grew in area and population over the decades, the particular character of the street changed, yet it always remained a focus of downtown life. Originally called Fort Street, Broadway first played a prominent role in the nineteenth century as the city expanded south from El Pueblo, then in the 1880s with the reconstruction of a new City Hall between 2nd and 3rd Streets, the character of the street began a dramatic change, quickly becoming an important commercial thoroughfare, including Bullock's, located on Broadway.

Broadway's preeminence as the commercial core of Los Angeles was matched by its growth as the leading theatre district for the region, boosted by the decision of the west coast's two major vaudeville circuits -- the Orpheum and Pantages -- to locate there. Sid Graumann built the first theatre, considered the City's first movie palace. The introduction of sound to the movies caused a new wave of theatre building in the late 1920s. By 1930, every major film studio had secured an outlet in downtown Los Angeles. With a dozen major theaters in a six block area, Broadway contained the highest concentration of movie palaces in the world, and a combined seating capacity of more than 15,000.

In the next several decades after 1930, Broadway began to lose its central role as the theater and commercial core of the City. As the white clientele moved away from Downtown into the suburbs and westside, so did the lavish movie theatres and department stores. The demise of a city wide public transit system also contributed to the dispersal of the white middle class audiences from the downtown area.

After World War II, the patronage of the Mexican-American population living close to downtown transformed Broadway into a Latino-oriented shopping district. Spanish language signs were layered on top of the opulent architecture of the 1920s and street fronts were transformed to accommodate smaller stores. By the end of the 1960s, the street was dominated by Latinos and it became a primary venue for Chicano commercial, religious and cultural expressions. Today, Broadway remains a hub of activity for Latinos in the City, and Chicanos have been joined by Salvadorians, cuatemalans, and Micaraguans in their intense public use of the street.

HISTORIC SIGNIFICANCE

The Broadway Historic Theater and Commercial District was listed in the National Register of Historic Places in 1979. Occupying Third through Ninth Streets, The district is significant under National Register criterion 'A' as vestiges of Los Angeles premier commercial and theatre district. The district is also significant under criterion 'C' for the architectural quality of its contributing buildings which were constructed between 1894 and 1931. Although the National Register application did not specifically mention features of the historic streetscape, many remain from the period and contribute to the character of the district.

Remarkably, many of the original feature which characterized the streetscape of Broadway during its period as the premier commercial and theatre district of Los Angeles remain in place. Much of the terrazzo, tilework and stamped concrete remains, as do the street lamp bases, and many marquees and awnings. As Broadway had developed into the central shopping district for the city's Latino community, layers of new character defining materials have been added to the existing historic fabric - Spanish language signs, vendors, and street entertainers.

Unlike other parts of downtown Los Angeles which have complètely lost their historic character, Broadway remains in many ways the street that it was in the 1920s and 1930s.

DESIGN CONCEPT

Like all great urban streets, Broadway at once connects us to the city's past while serving the present. This renovation seeks to reinforce Broadway's role as a focus of downtown city life and community by both strengthening its essential infrastructure and its ability to connect past and present. Since the physical and budgetary demands upon the project are rigorous, every modification has been carefully considered to deliver the most with the least over the long run. The design of all proposed elements is based on compatibility with the historic context and durability and ease of maintenance.

The design concept is an integrated image which focuses the identity of the Street. This image is composed fundamentally of a framework or "armature" of new sidewalks, renewed and intensified streetlighting, new street trees and street furnishing elements. Superimposed on this framework are layers of graphic elements such as banners, signs and new terrazo paving sidewalk elements. The design concept will address not only the overall identity of the Street, but its unique parts: the historic theatres, institutions such as Clifton's, and the arcades.

In defining space, focusing identity, and providing amenities such as the new paving and greatly intensified street lighting, the street environment will be "merchant and shopper friendly"

DESIGN ELEMENTS

There are six basic component elements to the design: sidewalk paving, street lighting, street graphics, building facade treatments, street furnishings, and street trees.

Sidewalks

To appropriately set off the remarkable terrazzo paving in front of a number of the significant historic buildings along the street and to welcome the addition of new terrazzo paving elements, the sidewalks are paved in a simple, concrete checkerboard pattern. To reflect the pedestrian environment, the checks are small in scale and are subtly defined one to the other by differential gradients of broom finish. To recall the typical techniques of the decades of the early twentieth century, the concrete is given sparkle and shine with the addition of quartz crystals. Based on discussions with the historic preservation consultants (Historic Resources Group), the existing concrete and tile paving can be replace with new paving. Our recommendation to replace existing concrete with a dark gray or "black" integral color (Scofoeld c-24 "charcoal") broom finished concrete with a 2'x2' square score pattern can be determined compatible with the historic context of the Street as well as meeting aesthetic, constructibility, and maintenance requirements. The existing historic terrazzo and marble paving segments will be reviewed for repair and or restoration feasibility during the design development phase. In addition, we recommend the addition of new terrazzo and special scored and stained concrete

segments to identify cross streets. New terrazzo paving can also be used to provide interpretive opportunities at historically significant locations.

Street Lighting

We recommend that the historic light fixtures be restored and renovated. These light standards renovated light poles will be designed to be hung with banners. These light standards can also carry interpretive signage related to the history of the street and its requirements for the roadway and sidewalks will be significantly exceeded, increasing current light levels by a factor of two to three. Our reccommendations include installing new appropriately designed lanterns, based on historic designs, which can be placed on the existing pole fixtures in their existing locations along with the inclusion of high mast lights at the intersections incorporated into new signal systems. We believe that such an approach can be determined compatible with the historic context of the street. We and our lighting consultants (Lighting Design Alliance) are currently reviewing the detailed photometric, operational, assessment and construction cost implications of this recommendation.

Street Graphics Program

The recommended banners and signage proposed for the streetlights as well as directional signage and the proposed new sidewalk terrazzo designs provide significant opportunity to reinforce a coherent, unifying visual identity to the street's acting as a counterpoint to the diversity of signs, colors and images of the street's retail environment. While recommended ranges of colors and styles for the components of this program will be detailed during the design development phase, components of this program will reflect both the historic and contemporary identity of the street.

Building facades


The street is famous for its remarkable collection of building facades representing a range of architectural styles of the early decades of this century. Specific guidelines for the renovation of awnings and facades are being developed in conjunction with our historic resources consultants, along with the location of awning and building mounted signs.

Street Furnishings

While the high levels of pedestrian traffic on the street limit the opportunities available for the placement of street furnishings, the existing newsstands provide an additional unifying element the streetscape. We recommend that the existing newsstands receive a new superstructure of a uniform enclosure shell. We are currently exploring opportunities to finance the construction of these elements by the advertising industry, through their carrying City approved advertising. In addition, we recommend the replacement of existing trash cans with distinct uniformly painted wire cans, potentially a part of the newsstand financing program.

Street Trees

The existing Ficus trees installed several decades ago have proven to be inappropriate to this street scene. We recommend Jacarndas replace them and be added at selected locations where possible. The recommended replacement tree species and placement will be "merchant and shopper friendly", compatible with lighting and storefront visibility requirements, and providing shade. We also recommend the addition of specially designed tree grates and tree fences to offer additional interpretive possibilities.



MPBELL 8 AMPBELL

KEY PLAN


4/8/96

CAMPBELL

&
CAMPBELL

ARCHITECTS - PLANNERS

LANDSCAPE ARCHITECTS



APPENDIX E

Table of Changes in Evaluation Codes

Address	Common or Historic Name Prev	Previous Evaluation Code	Updated Evaluation Code
200-206 S. Broadway		(Not evaluated)	6Y2
235 S. Broadway	Goodwill Industries	(Not evaluated)	6Y2
237-241 S. Broadway	Boston Dry Goods Store	38	583
242 S. Broadway	Victor Clothing Company	38	2D2
248-260 S. Broadway		(Not evaluated)	6Y2
249-251 S. Broadway	Irvine Block/Pan American Building	3S	2B2
300-310 S. Broadway	Bradbury Building	1D	ID
301-313 S. Broadway	Million Dollar Theater/Metro. Water Dist. Bldg.	. 1D	ID
312 S. Broadway		6X3	6X3
315 S. Broadway	Grand Central Market	1D	ID
318-322 S. Broadway	Blackstone Building	6X3	6Y2
324-326 S. Broadway		6X3	6X3
327-329 S. Broadway		6X3	6X3
328-330 S. Broadway		6X3	6X3
331-335 S. Broadway		6X3	6X3
336 S. Broadway		6X3	6X3
337-339 S. Broadway		6X3	6X3
340-344 S. Broadway	Trustee Building	ID	1D
341-343 S. Broadway		ID	6Y2
346 S. Broadway		6X3	6X3

I CARLLE OF CASE OF COLUMN				
Address	Common or Historic Name P	Previous Evaluation Code	Updated Evaluation Code	
347_349 S Broadway		6X3	6X3	
350-354 S. Broadway		ID	6Y2	
251_253 S Broadway		6X3	6X3	
255 250 S. Broadway		6X3	6X3	-
256 364 S. Broadway		1D	6Y2	
300-304 S. Broadway		6Z1	6Z1	
400-422 S. Broadway	Broadway Department Store	1D	ID	
124 C Broadway	Broadway Central Block	ID	ID	
425_429 S Broadway		6Z1	6Z1	
430 S Broadway	Bumiller Building/Campbell W. Blake Bldg.	1D	ID	
431-435 S. Broadway	Wilson Building	ID	ID	20
437 S. Broadway		6X3	6X3	
440 S. Broadway		6X3	6X3	
443-445 S. Broadway		6Z1	6Z1	
450 S Broadway		6X3	6X3	
451-457 S. Broadway		ID	, ID	
452-460 S. Broadway	Chester Williams Building	ID	ID	
500-508 S. Broadway	Jewelry Trades Building	1D	ID	
501-515 S. Broadway		ID	Ð	
510 S. Broadway		ID	ī	

Address	Common or Historic Name	Previous Evaluation Code	Updated Evaluation Code
516-522 S. Broadway	Roxie Theater	1D	ID
517-519 S. Broadway		1D	ID
523-525 S. Broadway		6X3	6X3
527-531 S. Broadway	Schulte United/Broadway Interiors	1D	1D
528 S. Broadway	Clune's Broadway/Cameo Theater	1D	ID
533 S. Broadway		1D	1D
534 S. Broadway	Arcade (formerly Pantages) Theater	1D	1D
535 S. Broadway		6X3	6X3
537-541 S. Broadway		1D	1D
540 S. Broadway	Broadway Arcade Building	1D	I.D
543-547 S. Broadway		6Z1	6Z1
548 S. Broadway	Eden Hotel	1D	1D
553 S. Broadway		1D	1D
555-559 S. Broadway	Swelldom Dep't Store/Sun Drug Co.	LL.	1D
558 S. Broadway		ID	1D
600-610 S. Broadway	Walter P. Story Building	1D	ID
601-605 S. Broadway	Norton Building	ID	1D
609-619 S. Broadway	Los Angeles Theater	1D	ID
612-616 S. Broadway	Desmond's	1D	1D
618-622 S. Broadway	Schaber's Cafeteria/Broadway Cafeteria	ID	1D

Address	Common or Historic Name	Previous Evaluation Code	Updated Evaluation Code
621-625 S. Broadway		6X3	6X3
626-636 S. Broadway	Palace Theater	ID	ID
629 S. Broadway		6X3	6X3
633 S. Broadway		6Z3	6Z3
635 S. Broadway		6X3	6X3
638 S. Broadway	Forrester Building	1D	1D
639-657 S. Broadway	Hollenbeck Block/Bullock's Dep't Store	1D	ID
644 S. Broadway	J. E. Carr Building	1D	ID
648 S. Broadway	Clifton's Brookdale Cafeteria Building	6X3	6X3
648 S. Broadway	Clifton's Cafeteria Terrazzo Sidewalk	(Not evaluated)	18
660 S. Broadway		6X3	6X3
700-708 S. Broadway		1D (Now demolished)	6Y2 (New building)
701-717 S. Broadway	Loew's State Theater Building	ID	ID
710 S. Broadway	Yorkshire Apartments	1D	ID
714-720 S. Broadway		ID	ID
719 S. Broadway	Woolworth's	ID	ID
722 S. Broadway		ID	ID
730 S. Broadway		6X3	6X3
731 S. Broadway		ID	ID
735 S. Broadway		6X3	6X3

Address	Common or Historic Name	Previous Evaluation Code	Updated Evaluation Code
737-747 S. Broadway		1D	1.0
744-748 S. Broadway	Globe Theater	1D	QI
749 S. Broadway		6X3	6X3
750-758 S. Broadway		ID	ID
757-761 S. Broadway		1D	1D
800-804 S. Broadway	Tower Theater	ID	ID
801-835 S. Broadway	Hamburger's/May Co. Dep't Store	ID	ID
806-808 S. Broadway	Singer Building	1D	ID
812 S. Broadway	Rialto Theater	1D	1D
814-818 S. Broadway		1D	ID
820-824 S. Broadway		1D	О
828 S. Broadway		eX3	6X3
830-834S. Broadway		1D	ID
839-847 S. Broadway		6X3	6X3
842-848 S. Broadway	Orpheum Theater	ID	1D .
849 S. Broadway	Eastern Columbia Building	1D	ID
850-860 S. Broadway	Ninth and Broadway Building	ID	ID
900-906 S. Broadway		6X3	6X3
901 S. Broadway	Blackstone's Dep't Store/U.S. Post Office	38	2D2
908-910 S. Broadway	Leasehold Co. Building	38	2D2
With the			

	Common or Historic Name	Previous Evaluation Code	Updated Evaluation Code	
Address	COMMENCES			
921-937 S. Broadway	United Artists Theater/Texas Oil Co. Bldg.	2S2	2B2	
939-947 S. Broadway	Western Costume Building	. 3S	2B2	
950 S. Broadway		(Not evaluated)	6Y2	
952-956 S. Broadway		(Not evaluated)	6Y2	
990 S. Broadway		(Not evaluated)	6Y2	

